



Lexmark™

MB3442, MX331, MX431, XM1342 MFPs

7019-235, -4xx

Service Manual

- [Start diagnostics](#)
- [Maintenance](#)
- [Safety and notices](#)
- [Index](#)

May 08, 2023

www.lexmark.com

Product information

Product name:

Lexmark MB3442dw, Lexmark MB3442i, Lexmark MX331adn, Lexmark MX431adn, Lexmark MX431adw, Lexmark XM1342 MFPs

Machine type:

7019

Model(s):

235, 4a6, 4b6, 486, 489

Edition notice

May 08, 2023

The following paragraph does not apply to any country where such provisions are inconsistent with local law: LEXMARK INTERNATIONAL, INC., PROVIDES THIS PUBLICATION “AS IS” WITHOUT WARRANTY OF ANY KIND, EITHER EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Some states do not allow disclaimer of express or implied warranties in certain transactions; therefore, this statement may not apply to you.

This publication could include technical inaccuracies or typographical errors. Changes are periodically made to the information herein; these changes will be incorporated in later editions. Improvements or changes in the products or the programs described may be made at any time.

References in this publication to products, programs, or services do not imply that the manufacturer intends to make these available in all countries in which it operates. Any reference to a product, program, or service is not intended to state or imply that only that product, program, or service may be used. Any functionally equivalent product, program, or service that does not infringe any existing intellectual property right may be used instead. Evaluation and verification of operation in conjunction with other products, programs, or services, except those expressly designated by the manufacturer, are the user's responsibility.

Trademarks

Lexmark and the Lexmark logo are trademarks or registered trademarks of Lexmark International, Inc. in the United States and/or other countries.

All other trademarks are the property of their respective owners.

© 2020 Lexmark International, Inc.

All rights reserved.

P/N

Table of contents

Product information.....	2
Edition notice.....	2
Notices, conventions, and safety information.....	9
Laser notice.....	9
Conventions.....	10
Safety information.....	10
Change history.....	15
Change history.....	15
General information.....	21
Printer model configurations.....	21
Supported paper sizes, types, and weights.....	21
Supported paper sizes.....	21
Supported paper types.....	24
Supported paper weights.....	24
Supported fax.....	25
Finding the printer serial number.....	26
Tools required for service.....	27
Diagnostics and troubleshooting.....	29
Troubleshooting precautions.....	29
Troubleshooting overview.....	31
Performing the initial troubleshooting check.....	31
Using Safe Mode.....	31
Securing the printer.....	32
Resetting the printer without admin credentials.....	32
Using the security reset jumper.....	32
Data security notice.....	33
Fixing print quality issues.....	34
Gray background or toner fog check.....	34
Blank page check.....	36
Print is too dark check.....	37
Print is too light check.....	39
Paper curl check.....	41
Folded or wrinkled paper check.....	42

Solid black pages check.....	43
Skewed print check	45
Streaked vertical lines appear on prints during a print job check.....	47
Streaked vertical lines appear on prints during a copy job check.....	48
Horizontal light bands check.....	50
Vertical light bands check.....	51
Vertical dark bands check.....	52
Vertical dark streaks with print missing check	53
White streaks and voided areas check	54
Clipped pages or images check.....	55
Incorrect margins on prints check	57
Toner rubs off check.....	57
Toner specks appear on prints during a print job check	58
Toner specks appear on prints during a copy job check.....	60
Repeating defects check.....	61
Paper jams.....	62
200 paper jams.....	62
202 paper jams.....	69
232 paper jams	75
242 paper jams	77
280–295 paper jams.....	77
User attendance messages.....	81
29-33 user attendance messages.....	81
4y user attendance messages.....	83
8y user attendance messages.....	87
Printer hardware errors.....	89
111 errors.....	89
121 errors.....	91
126 errors.....	93
140 errors.....	94
162 errors.....	95
6yy errors.....	97
84y errors	101
Procedure before starting the 9yy service checks	107
900 errors	108
912 errors.....	112
938–992 errors.....	115
Other symptoms.....	116
Base printer symptoms	116
Fax symptoms	118
Service menus.....	131
Understanding the printer control panel.....	131

Using the control panel	131
Understanding the status of the indicator light	131
Diagnostics menu.....	132
Entering the Diagnostics Menu	132
Reports	132
Advanced Print Quality Samples.....	133
Format Fax Storage	133
Event Log.....	133
Input tray quick print.....	134
Output bin quick feed	134
Printer Setup.....	134
Printer diagnostics & adjustments	136
Scanner Diagnostics.....	138
Config Menu.....	139
Entering the Config Menu	139
Config Menu	140
Service Engineer (SE) menu.....	143
Entering the SE Menu.....	143
General SE Menu.....	143
Network SE Menu.....	143
Scanner SE Menu	144
Fax SE Menu.....	144
EWS SE Menu.....	145
Entering invalid engine mode.....	145
Entering Recovery mode.....	146
Parts removal.....	149
Important removal information.....	149
Removal precautions	149
Handling ESD-sensitive parts.....	151
Critical information for controller board or control panel replacement	151
Restoring the printer configuration.....	152
Updating the printer firmware	154
Ribbon cable connectors	156
Low insertion force (LIF) connector	156
Adjustments.....	157
Adjusting the fax volume	157
Removal procedures.....	157
Left side removals.....	158
Left cover removal	158
Main drive gears removal.....	159
Imaging unit coupling removal	163
Pick roller clutch removal	164

Left front door link removal.....	165
Right side removals.....	167
Right cover removal.....	167
Controller board removal	169
LVPS removal.....	171
HVPS removal	171
Sensor (MPF paper present) removal	173
Right front door link removal.....	174
MPF solenoid cable removal.....	174
Main fan removal	175
Speaker removal	177
Interlock switch removal.....	177
Front removals.....	178
Control panel removal.....	178
Upper front cover removal.....	179
Front door removal	179
Transfer roller removal	180
MPF pick roller removal	181
Pick separator roller removal	182
Sensor (input) removal	182
Important information before installing the duplex shaft bushing	184
Rear removals.....	185
Rear door removal.....	185
Fuser removal.....	186
Top removals.....	186
Printhead removal	186
Redrive removal.....	188
Bin full sensor actuator removal.....	189
Bottom removals.....	191
Duplex guide removal.....	191
ADF and scanner removals.....	192
ADF cover removal	192
ADF tray removal.....	193
ADF separator pad removal	193
ADF and scanner removal	193
Scanner pivot arm removal.....	198
Component locations.....	201
Printer configuration.....	201
Controller board connectors.....	201

Maintenance.....	209
Cleaning printer parts.....	209
Cleaning the printer	209
Cleaning the scanner	209
Parts catalog.....	212
Legend.....	212
Assembly 1: Covers.....	213
Assembly 2: Control panel.....	215
Assembly 3: Electronics.....	217
Assembly 4: Gears.....	221
Assembly 5: Paper path.....	223
Assembly 6: 550-sheet optional tray.....	225
Assembly 7: ADF and scanner.....	227
Assembly 8: Miscellaneous.....	229
Printer specifications.....	231
Power consumption.....	231
Product power consumption	231
Sleep Mode.....	231
Hibernate Mode.....	232
Off mode	232
Total energy usage	232
Applicability of Regulation (EU) 2019/2015 and (EU) 2019/2020.....	232
Selecting a location for the printer.....	232
Noise emission levels.....	233
Temperature information.....	234
Theory of operation.....	235
POR sequence.....	235
Print cycle operation.....	235
Print engine layout	235
Print cycle	236
Printer operation.....	242
Printer sections	242
Printer paper path	243
Printer paper path sensors	245
Main drive	246
Tray drive	247

ADF theory.....248
 ADF paper path.....248

Index.....249

Part number index.....253

Part name index..... 255

Notices, conventions, and safety information

Laser notice

The printer is certified in the U.S. to conform to the requirements of DHHS 21 CFR, Chapter I, Subchapter J for Class I (1) laser products, and elsewhere is certified as a Class I laser product conforming to the requirements of IEC 60825-1: 2014.

Class I laser products are not considered to be hazardous. The laser system and printer are designed so there is never any human access to laser radiation above a Class I level during normal operation, user maintenance, or prescribed service conditions. The printer has a non-serviceable printhead assembly that contains a laser with the following specifications:

Class: IIIb (3b) AlGaInP

Nominal output power (milliwatts): 25

Wavelength (nanometers): 775–800

Avis relatif à l'utilisation du laser

Cette imprimante est certifiée conforme aux exigences de la réglementation des Etats-Unis relative aux produits laser de classe I (1) (DHHS 21 CFR, Chapitre I, Sous-chapitre J). Pour les autres pays, elle est certifiée conforme aux exigences des normes CEI 60825-1:2014 relatives aux produits laser de classe I.

Les produits laser de classe I ne sont pas considérés comme dangereux. Le système laser ainsi que l'imprimante ont été conçus de manière à ce que personne ne soit jamais exposé à des radiations laser dépassant le niveau de classe I dans le cadre d'un fonctionnement normal, de l'entretien par l'utilisateur ou de la maintenance. L'imprimante dispose d'un ensemble de têtes d'impression non réparable contenant un laser doté des caractéristiques suivantes :

Class: IIIb (3b) AlGaInP

Nominal output power (milliwatts): 25

Wavelength (nanometers): 775–800

Aviso de láser

Esta impresora se ha certificado en EE.UU. cumpliendo con los requisitos de DHHS 21 CFR, capítulo I, subcapítulo J para los productos láser de Clase I (1) y en otros países está certificada como un producto láser de Clase I de acuerdo con los requisitos de IEC 60825-1: 2014.

Los productos láser de Clase I no se consideran peligrosos. El sistema láser y la impresora se han diseñado para que el ser humano no acceda nunca a las radiaciones láser por encima del nivel de Clase I durante su uso normal, ni en tareas de mantenimiento o intervenciones de servicio técnico prescritas. El conjunto de cabezal de impresión de la impresora no se puede reparar y contiene un láser con las siguientes especificaciones:

Class: IIIb (3b) AlGaInP

Nominal output power (milliwatts): 25

Wavelength (nanometers): 775–800

Laser-Hinweis

Der Drucker wurde in den USA zertifiziert und entspricht den Anforderungen der Vorschriften DHHS 21 CFR Kapitel I für Laserprodukte der Klasse I (1), andernorts ist er als Laserprodukt der Klasse I zertifiziert, das den Anforderungen von IEC 60825-1 entspricht: 2014.

Laserprodukte der Klasse I werden nicht als gefährlich betrachtet. Das Lasersystem und der Drucker sind so konstruiert, dass unter normalen Betriebsbedingungen, bei der Wartung durch den Benutzer oder bei den vorgeschriebenen Wartungsbedingungen Menschen keiner Laserstrahlung ausgesetzt sind, die die Werte für Klasse I überschreitet. Der Drucker verfügt über eine Druckkopfeinheit, die nicht gewartet werden kann und mit einem Laser mit den folgenden Spezifikationen ausgestattet ist.

Class: IIIb (3b) AlGaInP

Nominal output power (milliwatts): 25

Wavelength (nanometers): 775–800

Conventions

Note: A *note* identifies information that could help you.

Warning: A *warning* identifies something that could damage the product hardware or software.

CAUTION: A *caution* indicates a potentially hazardous situation that could injure you.

Different types of caution statements include:

 **CAUTION—POTENTIAL INJURY:** Indicates a risk of injury.

 **CAUTION—SHOCK HAZARD:** Indicates a risk of electrical shock.

 **CAUTION—HOT SURFACE:** Indicates a risk of burn if touched.

 **CAUTION—TIPPING HAZARD:** Indicates a crush hazard.

 **CAUTION—PINCH HAZARD:** Indicates a risk of being caught between moving parts.

Safety information

- The safety of this product is based on testing and approvals of the original design and specific components. The manufacturer is not responsible for safety in the event of use of unauthorized replacement parts.
- The maintenance information for this product has been prepared for use by a professional service person and is not intended to be used by others.
- There may be an increased risk of electrical shock and personal injury during disassembly and servicing of this product. Professional service personnel should understand this risk and take necessary precautions.

 **CAUTION—SHOCK HAZARD:** When you see this symbol on the product, there is a danger from hazardous voltage in the area of the product where you are working. Unplug the product before you begin, or use caution if the product must receive power in order to perform the task.

-  **CAUTION—POTENTIAL INJURY:** The lithium battery in this product is not intended to be replaced. There is a danger of explosion if a lithium battery is incorrectly replaced. Do not recharge, disassemble, or incinerate a lithium battery. Discard used lithium batteries according to the manufacturer's instructions and local regulations.
-  **CAUTION—POTENTIAL INJURY:** To avoid the risk of fire or electrical shock, connect the power cord to an appropriately rated and properly grounded electrical outlet that is near the product and easily accessible.
-  **CAUTION—POTENTIAL INJURY:** To avoid the risk of fire or electrical shock, use only the power cord provided with this product or the manufacturer's authorized replacement.
-  **CAUTION—POTENTIAL INJURY:** Do not use this product with extension cords, multioutlet power strips, multioutlet extenders, or UPS devices. The power capacity of these types of accessories can be easily overloaded by a laser printer and may result in a risk of fire, property damage, or poor printer performance.
-  **CAUTION—POTENTIAL INJURY:** Only a Lexmark Inline Surge Protector that is properly connected between the printer and the power cord provided with the printer may be used with this product. The use of non-Lexmark surge protection devices may result in a risk of fire, property damage, or poor printer performance.
-  **CAUTION—POTENTIAL INJURY:** If the printer weight is greater than 20 kg (44 lb), then it may require two or more people to lift it safely.

Consignes de sécurité

- La sécurité de ce produit est basée sur des tests et certifications de sa conception d'origine et de ses composants spécifiques. Le fabricant décline toute responsabilité en cas d'utilisation de pièces de rechange non autorisées.
 - Les informations de maintenance de ce produit sont destinées à des professionnels qualifiés et ne sont pas conçues pour être utilisées par d'autres personnes.
 - Il existe un risque potentiel de choc électrique et de blessures lors du démontage et de la maintenance de ce produit. Le personnel professionnel de maintenance doit comprendre les risques et prendre les précautions nécessaires.
-  **ATTENTION—RISQUE D'ELECTROCUTION :** Ce symbole indique un danger lié à des niveaux de tension dangereux dans la zone du produit à manipuler. Débranchez le produit avant de commencer, ou agissez avec prudence si le produit doit être alimenté pour effectuer l'opération.
 -  **ATTENTION—RISQUE DE BLESSURE :** La batterie lithium de ce produit n'est pas destinée à être remplacée. Si vous ne respectez pas les instructions de remplacement de la batterie, vous risquez de provoquer une explosion. Ne rechargez pas, ne désassemblez pas et ne brûlez pas la batterie au lithium. Mettez les batteries lithium usagées au rebut selon les instructions du fabricant et les réglementations locales.
 -  **ATTENTION—RISQUE DE BLESSURE :** Pour éviter tout risque d'électrocution ou d'incendie, branchez le câble d'alimentation directement à une prise électrique répondant aux exigences requises et correctement mise à la terre, proche du produit et facile d'accès.
 -  **ATTENTION—RISQUE DE BLESSURE :** Pour éviter tout risque d'incendie ou d'électrocution, utilisez uniquement le câble d'alimentation fourni avec ce produit ou un câble de remplacement autorisé par le fabricant.

-  **ATTENTION—RISQUE DE BLESSURE** : Ce produit ne doit pas être utilisé avec des rallonges, des barres multiprises, des rallonges multiprises ou des périphériques UPS. La capacité de ces types d'accessoires peut être facilement dépassée par une imprimante laser, d'où un risque de dégâts matériels, d'incendie ou de performances d'impression amoindries.
-  **ATTENTION—RISQUE DE BLESSURE** : Utilisez uniquement un parasurtenseur correctement raccordé à l'imprimante et au câble d'alimentation fourni avec la machine. L'utilisation de parasurtenseurs non fabriqués par Lexmark comporte un risque d'incendie et de dégâts matériels, et peut amoindrir les performances de l'imprimante.
-  **ATTENTION—RISQUE DE BLESSURE** : Si votre imprimante pèse plus de 20 kg (44 lb), l'intervention d'au moins deux personnes est nécessaire pour la soulever sans risque.

Información de seguridad

- La seguridad de este producto se basa en las pruebas y comprobaciones del diseño original y los componentes específicos. El fabricante no se hace responsable de la seguridad en caso de uso de piezas de repuesto no autorizadas.
- La información de mantenimiento de este producto se ha preparado para su uso por parte de un profesional de asistencia técnica y no está diseñada para su uso por parte de otros usuarios.
- Es posible que haya un mayor riesgo de descarga eléctrica y daños personales durante el desmontaje y el mantenimiento de este producto. El personal de asistencia profesional debe conocer este riesgo y tomar las precauciones necesarias.

 **PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS:** Cuando vea este símbolo en el producto, existe peligro de tensiones peligrosas en el área del producto en la que está trabajando. Desconecte el producto antes de empezar o tenga cuidado si el producto debe recibir alimentación a fin de realizar la tarea.

 **PRECAUCIÓN: POSIBLES DAÑOS PERSONALES:** La batería de litio de este producto no debe reemplazarse. Existe riesgo de explosión si se sustituye incorrectamente una batería de litio. No recargue, desmonte ni incinere una batería de litio. Deseche las baterías de litio usadas según las instrucciones del fabricante y las normativas locales.

 **PRECAUCIÓN: POSIBLES DAÑOS PERSONALES:** Para evitar el riesgo de incendio o descarga eléctrica, conecte el cable de alimentación a una toma de corriente debidamente conectada a tierra con la potencia adecuada que se encuentre cerca del dispositivo y resulte fácilmente accesible.

 **PRECAUCIÓN: POSIBLES DAÑOS PERSONALES:** Para evitar el riesgo de incendio o descarga eléctrica, utilice exclusivamente el cable de alimentación que se suministra junto con este producto o el repuesto autorizado por el fabricante.

 **PRECAUCIÓN: POSIBLES DAÑOS PERSONALES:** No utilice este producto con cables alargadores, regletas de varias tomas, cables alargadores de varias tomas o sistemas de alimentación ininterrumpida. La potencia de este tipo de accesorios puede sobrecargarse fácilmente si se utiliza una impresora láser, lo que puede dar lugar a que el rendimiento de la impresora sea bajo, a daños materiales o a posibles incendios.

 **PRECAUCIÓN: POSIBLES DAÑOS PERSONALES:** Solo debe usarse con este producto un protector de sobretensión insertable Lexmark debidamente conectado entre la impresora y el cable de alimentación que con ella se suministra. El uso de protectores de sobretensión de marcas distintas a Lexmark puede dar lugar a que el rendimiento de la impresora sea bajo, a daños materiales o a posibles incendios.

 **PRECAUCIÓN: POSIBLES DAÑOS PERSONALES:** si el peso de la impresora es superior a 20 kg (44 lb), pueden ser necesarias dos o más personas para levantarla de forma segura.

Sicherheitshinweise

- Die Sicherheit dieses Produkts basiert auf Tests und Zulassungen des Originaldesigns und der spezifischen Komponenten. Sofern nicht autorisierte Ersatzteile eingesetzt werden, übernimmt der Hersteller keinerlei Verantwortung in Bezug auf die Sicherheit dieses Produkts.
- Die Wartungsinformationen für dieses Produkt wurden für ausgebildete Servicemitarbeiter zusammengestellt und dürfen nicht von anderen verwendet werden.
- Möglicherweise besteht bei der Demontage und Wartung dieses Produkts eine erhöhte Stromschlag- und Verletzungsgefahr. Ausgebildete Servicemitarbeiter sollten sich dieser Gefahr bewusst sein und die notwendigen Vorsichtsmaßnahmen ergreifen.

 **VORSICHT – STROMSCHLAGGEFAHR:** Wenn Sie dieses Symbol sehen, besteht eine Gefahr durch gefährliche Spannungen in dem Produktbereich, in dem Sie arbeiten. Trennen Sie das Produkt von seiner Stromverbindung, bevor Sie beginnen, oder gehen Sie vorsichtig vor, wenn das Produkt für die Durchführung der Aufgabe mit Strom versorgt werden muss.

 **VORSICHT – MÖGLICHE VERLETZUNGSGEFAHR** Die Lithiumbatterie in diesem Produkt darf nicht ausgetauscht werden. Wird eine Lithiumbatterie nicht ordnungsgemäß ausgetauscht, besteht Explosionsgefahr. Lithiumbatterien dürfen auf keinen Fall wieder aufgeladen, auseinander genommen oder verbrannt werden. Befolgen Sie zum Entsorgen verbrauchter Lithiumbatterien die Anweisungen des Herstellers und die örtlichen Bestimmungen.

 **VORSICHT – MÖGLICHE VERLETZUNGSGEFAHR** Um Feuer- und Stromschlaggefahr zu vermeiden, schließen Sie das Netzkabel direkt an eine ordnungsgemäß geerdete Steckdose an, die sich in der Nähe des Geräts befindet und leicht zugänglich ist.

 **VORSICHT – MÖGLICHE VERLETZUNGSGEFAHR** Um das Risiko eines Feuers oder elektrischen Schlags zu vermeiden, verwenden Sie ausschließlich das diesem Produkt beiliegende Netzkabel bzw. ein durch den Hersteller zugelassenes Ersatzkabel.

 **VORSICHT – MÖGLICHE VERLETZUNGSGEFAHR** Verwenden Sie das Produkt nicht mit Verlängerungskabeln, Mehrfachsteckdosen, Mehrfachverlängerungen oder Geräten für unterbrechungsfreie Stromversorgung. Die Belastbarkeit solcher Zubehörteile kann durch Laserdrucker schnell überschritten werden, was zu Brandgefahr, Beschädigung von Eigentum oder einer eingeschränkten Druckerleistung führen kann.

 **VORSICHT – MÖGLICHE VERLETZUNGSGEFAHR** Mit diesem Produkt darf nur ein Lexmark Inline Surge Protector verwendet werden, der vorschriftsgemäß zwischen dem Drucker und dem mitgelieferten Netzkabel angeschlossen ist. Die Verwendung von nicht von Lexmark stammenden Überspannungsschutzgeräten kann zu Brandgefahr, Beschädigung von Eigentum oder einer eingeschränkten Druckerleistung führen.

 **VORSICHT – MÖGLICHE VERLETZUNGSGEFAHR** Wenn der Drucker mehr als 20 kg wiegt, sind zum sicheren Anheben mindestens zwei Personen notwendig.

Change history

Change history

May 7, 2023

- Updated the assembly index and units/FRU for PN41X2929. See [“Covers” on page 213](#).
- Updated the units/FRU for PN41X2587. See [“Electronics” on page 217](#).

May 2, 2023

- Removed the Unwanted marks on the display removal information from the Control panel removal of the Parts removal chapter. See [“Control panel removal” on page 178](#).

February 14, 2023

- Updated the following topics in the Removals chapter:
 - ADF and scanner removal. See [“ADF and scanner removal” on page 193](#).
 - Controller board removal. See [“Controller board removal” on page 169](#).

January 31, 2023

- Added error code 845.02. See [“840–845 error messages” on page 101](#) in the Diagnostics and troubleshooting chapter.

January 10, 2023

- Added an installation note in the Control panel removal topic of the Parts removal chapter. See [“Control panel removal” on page 178](#).

December 22, 2022

- Added the topic Important information before installing the duplex shaft bushing in the Removals chapter. See [“Important information before installing the duplex shaft bushing” on page 184](#).
- Updated the Gears assembly in the Parts catalog chapter. See [“Gears” on page 221](#).

November 29, 2022

- Added the topic group Securing the printer in the Diagnostics and troubleshooting chapter. It includes these topics:
 - Resetting the printer without admin credentials. See [“Resetting the printer without admin credentials” on page 32](#).
 - Using the security reset jumper. See [“Using the security reset jumper” on page 32](#).

November 8, 2022

- Added the topic Interlock switch removal in the Removals chapter. See [“Interlock switch removal” on page 177](#).
- Added PN 41X4485 in the Electronics assembly in the Parts catalog chapter. See [“Electronics” on page 217](#).

September 6, 2022

- Updated the Entering recovery mode topic in the Service menus chapter. See [“Entering Recovery mode” on page 146](#).

August 23, 2022

- Added the Applicability of Regulation (EU) 2019/2015 and (EU) 2019/2020 regulatory notice in the Printer specifications chapter.

August 16, 2022

- Added the Enabling the security reset jumper topic in the Printer specifications chapter.

July 28, 2022

- Added the new topic Adjusting the fax volume to the Removals chapter. See [“Adjusting the fax volume” on page 157](#).
- Updated the following topics in the Parts catalog chapter:
 - Covers. Updated the units/FRU for upper front cover with decals. See [“Covers” on page 213](#).
 - Electronics. Added 41X4479 controller board (MB3442adw, MX431adw, XM1342); updated the art and units/FRU for toner cartridge contact and; updated the units/FRU for transfer roller, bearing, and spring. See [“Electronics” on page 217](#).
 - Gears. Updated the units/FRU for main drive gears kit. See [“Gears” on page 221](#).
 - Paper path. Changed art for the redrive to include the bin full sensor actuator. See [“Paper path” on page 223](#).

May 17, 2022

- Updated the following topics in the Diagnostics and troubleshooting chapter:
 - 29-33 user attendance messages. See [“29–33 user attendance messages” on page 81](#).
 - 4y user attendance messages. See [“41-43 user attendance messages” on page 83](#).
 - 8y user attendance messages. See [“80-88 user attendance messages” on page 87](#).
- Added the Restoring the printer configuration topic in the Parts removal chapter. See [“Restoring the printer configuration” on page 152](#).
- Updated the description of PN 41X2597 to Scanner with fax card (MX331) (simplex ADF) in the Parts catalog chapter. See [“ADF and scanner” on page 227](#).

April 6, 2022

- Added PN 41X4471 in the Gears assembly and illustration of the Parts catalog chapter. See [“Gears” on page 221](#).

February 3, 2022

- Updated the Controller board removal topic in the Parts removal chapter. See [“Controller board removal” on page 169](#).

November 18, 2021

- Added PN 41X4273 in the Electronics assembly of the Parts catalog chapter. See [“Electronics” on page 217](#).

October 26, 2021

- Updated the 900 error service check topic in the Diagnostics and troubleshooting chapter. See [“900 error service check” on page 108](#).
- Updated the description of PN 41X2580 and added PN 41X4207 in the Parts catalog chapter. See [“Covers” on page 213](#).
- Added the Applicability of Regulation (EU) 2019/2015 and (EU) 2019/2020 topic in the Printer specifications chapter.

September 14, 2021

- Added the Sensor (input) removal topic in the Parts removal chapter. See [“Sensor \(input\) removal” on page 182](#).
- Added PN 41X1083 in the Electronics assembly of the Parts catalog chapter. See [“Electronics” on page 217](#).

August 25, 2021

- Updated the illustration and added the following PNs in the Paper path assembly of Parts catalog chapter. See [“Paper path” on page 223](#).
 - 41X4195
 - 41X4196

July 21, 2021

- Changed PN 41X2589 to PN 41X2598 in the notes in assembly 7 of the Parts catalog chapter. See [“ADF and scanner” on page 227](#).

June 24, 2021

- Added the 900 error messages topic in the Diagnostics and troubleshooting chapter. See [“900 error messages” on page 108](#).
- Added the 900 error service check topic in the Diagnostics and troubleshooting chapter. See [“900 error service check” on page 108](#).

May 3, 2021

- Updated the following removal topics in the Parts removal chapter:
 - Controller board removal
 - ADF and scanner removal
- Removed the Sensor (front door interlock) removal topic in the Parts removal chapter.
- Replaced PN 41X2391 with PN 41X2425 in the Parts catalog chapter. See [“Gears” on page 221](#).
- Updated the description for the following PNs in the Parts catalog chapter. See [“Electronics” on page 217](#) and [“ADF and scanner” on page 227](#).
 - 41X2975
 - 41X2660
 - 41X2976
 - 41X2661
 - 41X2977

- 41X2598
- 41X2980

March 23, 2021

- Added the XM1342 printer model.
- Updated the Fax card removal topic in the Parts removal chapter.
- Updated the following assembly topics in the Parts catalog chapter:
 - Covers
 - Electronics
 - ADF and scanner
 - Miscellaneous
- Updated the Controller board connectors topic in the Component locations chapter.
- Added PN 41X2929 in the Parts catalog chapter.

February 16, 2021

- Added the MB3442i printer model in the Printer model configurations topic of the General information chapter.
- Added the following topics in the General information chapter:
 - Supported fax
 - Finding the printer serial number
- Added the following topics in the Diagnostics and troubleshooting chapter:
 - Fax symptoms
 - Fax error log codes
 - Modem/fax card service check
 - Cannot set up etherFAX
 - Cannot send or receive faxes using etherFAX
 - Fax transmission service check
 - Fax reception service check
 - Lost connection to HTTPS fax server when using etherFAX service check
 - Fax station error service check
 - Fax failure service check
- Updated the User attendance messages topic in the Diagnostics and troubleshooting chapter.
- Updated the Config Menu topic in the Service menus chapter.
- Added the following topics in the Service menus chapter:
 - Fax SE Menu
 - EWS SE Menu
- Added the Speaker removal topic in the Parts removal chapter.
- Updated the Controller board connectors topic in the Component locations chapter.
- Added PN 41X2978 in the Parts catalog chapter.
- Updated the Wiring diagram

October 23, 2020

- Added the following Base printer symptoms topics in the Diagnostics and troubleshooting chapter:
 - Tray near empty service check
 - False bin full error service check
- Added the Bin full sensor actuator removal topic in the Parts removal chapter.

September 29, 2020

- Updated the Using Safe Mode topic in the Diagnostics and troubleshooting chapter.
- Updated the ADF and scanner assembly topic in the Parts catalog chapter.
- Removed PN 41X2664 in the Parts catalog chapter.

September 7, 2020

- Updated the Critical information for controller board or control panel replacement topic in the Parts removal chapter.
- Updated the 938–992 error messages table in the Diagnostics and troubleshooting chapter.
- Added the NVRAM mismatch failure service check topic in the Diagnostics and troubleshooting chapter.

August 3, 2020

- Removed the following topics in the Parts removal chapter:
 - Restoring the printer configuration after replacing the controller board
 - Restoring solutions, licenses, and configuration settings

July 15, 2020

- Added the 280–295 paper jam messages in the Diagnostics and troubleshooting chapter.
- Added the 840–845 error messages topic in the Diagnostics and troubleshooting chapter.
- Updated the 600–680 error messages topic in the Diagnostics and troubleshooting chapter.
- Added the following topics in the Diagnostics and troubleshooting chapter:
 - ADF jam service check
 - ADF failure service check
 - Scanner communication error service check
 - Scanner communication failure service check
 - Scanner noise service check
 - Duplex scan error service check
- Updated the Config menu topic in the Service menus chapter.
- Added PN 41X2664 in the Parts catalog chapter.

June 8, 2020

- Added the Entering Recovery Mode topic in the Service menus chapter.

May 12, 2020

- Updated the description of the following parts in the Electronics topic in the Parts catalog chapter:
 - PN 41X2659
 - PN 41X2660

– PN 41X2661

April 14, 2020

- First release.

General information

Printer model configurations

The Lexmark MX331, Lexmark MB3442, Lexmark MX431, and Lexmark XM1342 MFPs are small, monochrome, network-capable, laser printers.

Model	Configurations	Machine type/model
MX331adn	Network-ready monochrome laser four-in-one MFP with 2.8-inch touch screen, 40 ppm, 10/100 Ethernet, front USB, internal duplex printing, and simplex scanning for small workgroups.	7019-235
MB3442adw	Network-ready monochrome laser four-in-one MFP with 2.8-inch touch screen, 42 ppm, wireless, 10/100 Ethernet, front USB, internal duplex printing, and duplex scanning for small workgroups.	7019-486
MB3442i	Network-ready monochrome laser three-in-one MFP with 2.8-inch touch screen, 42 ppm, wireless, 10/100 Ethernet, front USB, internal duplex printing, and duplex scanning for small workgroups.	7019-486
MX431adn	Network-ready monochrome laser four-in-one MFP with 2.8-inch touch screen, 42 ppm, Gigabit Ethernet, front USB, internal duplex printing, and duplex scanning for small workgroups.	7019-4a6
MX431adw	Network-ready monochrome laser four-in-one MFP with 2.8-inch touch screen, 42 ppm, wireless, Gigabit Ethernet, front USB, internal duplex printing, and duplex scanning for small workgroups.	7019-4b6
XM1342		7019-489

Supported paper sizes, types, and weights

Supported paper sizes

Paper size	Standard 250-sheet tray	Optional 550-sheet tray	Multipurpose feeder	Two-sided printing	Scanner	ADF
A4 210 x 297 mm (8.27 x 11.7 in.)	✓	✓	✓	✓	✓	✓

¹ The default support is long-edge feed.

² Paper must at least be 210 mm (8.27 in.) wide and 279.4 mm (11 in.) long for two-sided printing.

³ When Universal is selected, the page is formatted for 215.90 x 355.60 mm (8.5 x 14 in.) unless specified by the application.

Paper size	Standard 250-sheet tray	Optional 550-sheet tray	Multipurpose feeder	Two-sided printing	Scanner	ADF
A5 Portrait (SEF) 148 x 210 mm (5.83 x 8.27 in.)	✓	✓	✓	X	✓	✓
A5 Landscape (LEF)¹ 210 x 148 mm (8.27 x 5.83 in.)	✓	✓	✓	X	✓	✓
A6 105 x 148 mm (4.13 x 5.83 in.)	✓	✓	✓	X	✓	✓
JIS B5 182 x 257 mm (7.17 x 10.1 in.)	✓	✓	✓	X	✓	✓
Oficio (Mexico) 215.9 x 340.4 mm (8.5 x 13.4 in.)	✓	✓	✓	✓	X	✓
Hagaki 100 x 148 mm (3.94 x 5.83 in.)	✓	X	✓	X	✓	X
Statement 139.7 x 215.9 mm (5.5 x 8.5 in.)	✓	✓	✓	X	✓	✓
Executive 184.2 x 266.7 mm (7.25 x 10.5 in.)	✓	✓	✓	X	✓	✓
Letter 215.9 x 279.4 mm (8.5 x 11 in.)	✓	✓	✓	✓	✓	✓
Legal 215.9 x 355.6 mm (8.5 x 14 in.)	✓	✓	✓	✓	X	✓
Folio 215.9 x 330.2 mm (8.5 x 13 in.)	✓	✓	✓	✓	X	✓

¹ The default support is long-edge feed.

² Paper must at least be 210 mm (8.27 in.) wide and 279.4 mm (11 in.) long for two-sided printing.

³ When Universal is selected, the page is formatted for 215.90 x 355.60 mm (8.5 x 14 in.) unless specified by the application.

Paper size	Standard 250-sheet tray	Optional 550-sheet tray	Multipurpose feeder	Two-sided printing	Scanner	ADF
Universal³ 99 x 148 mm to 215.9 x 359.92 mm (3.9 x 5.83 in. to 8.5 x 14.17 in.)	✓	✓	✓	✓ ²	X	✓
7 3/4 Envelope 98.4 x 190.5 mm (3.875 x 7.5 in.)	X	X	✓	X	✓	X
9 Envelope 98.4 x 225.4 mm (3.875 x 8.9 in.)	X	X	✓	X	✓	X
10 Envelope 104.8 x 241.3 mm (4.12 x 9.5 in.)	X	X	✓	X	✓	X
DL Envelope 110 x 220 mm (4.33 x 8.66 in.)	X	X	✓	X	✓	X
C5 Envelope 162 x 229 mm (6.38 x 9.01 in.)	X	X	✓	X	✓	X
B5 Envelope 176 x 250 mm (6.93 x 9.84 in.)	X	X	✓	X	✓	X
Other Envelope 98.4 x 162 mm to 176 x 250 mm (3.87 x 6.38 in. to 6.93 x 9.84 in.)	X	X	✓	X	✓	X

¹ The default support is long-edge feed.

² Paper must at least be 210 mm (8.27 in.) wide and 279.4 mm (11 in.) long for two-sided printing.

³ When Universal is selected, the page is formatted for 215.90 x 355.60 mm (8.5 x 14 in.) unless specified by the application.

Supported paper types

Paper type	Standard 250-sheet tray	Optional 550-sheet tray	Multipurpose feeder	Two-sided printing	Automatic document feeder
Plain paper	✓	✓	✓	✓	✓
Card stock	X	X	✓	X	X
Recycled	✓	✓	✓	✓	X
Paper labels*	✓	✓	✓	X	X
Bond	✓	✓	✓	✓	X
Letterhead	✓	✓	✓	✓	X
Preprinted	✓	✓	✓	✓	X
Colored Paper	✓	✓	✓	✓	X
Light Paper	✓	✓	✓	✓	X
Heavy Paper	✓	✓	✓	✓	X
Rough/Cotton	✓	✓	✓	✓	X
Envelope	X	X	✓	X	X
Rough envelope	X	X	✓	X	X

* One-sided paper labels are supported for occasional use of less than 20 pages per month. Vinyl, pharmacy, or two-sided labels are not supported.

Supported paper weights

	Standard 250-sheet tray	Optional 550-sheet tray	Multipurpose feeder	Two-sided printing	Automatic document feeder
Paper weight	60–120 g/m ² (16–32 lb)	60–120 g/m ² (16–32 lb)	60–217 g/m ² (16–58 lb)	60–90 g/m ² (16–24 lb)	60–90 g/m ² (16–24 lb)

Supported fax


Printer model	Analog fax	etherFAX ¹	Fax server	Fax over IP (FoIP) ²
MB3442adw	✓	✓	✓	✓
MB3442i	x	✓	✓	✓
MX331adn	✓	✓	✓	✓
MX331dn	x	✓	✓	✓
MX431adn	✓	✓	✓	✓
MX431adw	✓	✓	✓	✓
MX431dn	x	✓	✓	✓
XM1342	✓	✓	✓	✓

¹ Needs a subscription. For more information, go to <https://www.etherfax.net/lexmark> or contact the place where you purchased the printer.

² Needs an installed license bundle. For more information, contact the place where you purchased the printer.

Finding the printer serial number

1 Open the front door.



2 Locate the printer serial number behind the front door.



Tools required for service

- Flat-blade screwdrivers, various sizes
- #1 Phillips screwdriver, magnetic
- #2 Phillips screwdriver, magnetic
- #2 Phillips screwdriver, magnetic short-blade
- Torx screwdriver (T20 head)
- Needle-nose pliers
- Diagonal side cutters
- Spring hook
- Feeler gauges
- Analog or digital multimeter
- 3-mm ball hex wrench
- Toner vacuum
- Flashlight

Diagnostics and troubleshooting

Troubleshooting precautions

-  **CAUTION—SHOCK HAZARD:** When you see this symbol on the product, there is a danger from hazardous voltage in the area of the product where you are working. Unplug the product before you begin, or use caution if the product must receive power in order to perform the task.
-  **CAUTION—SHOCK HAZARD:** This product uses an electronic power switch. It does not physically disconnect the input AC voltage. To avoid the risk of electrical shock, always remove the power cord from the printer when removal of the input AC voltage is required.
-  **CAUTION—SHOCK HAZARD:** To avoid the risk of electrical shock while troubleshooting with covers removed or doors open, do not touch the exposed wires or circuits while the printer is connected to an electrical outlet.
-  **CAUTION—SHOCK HAZARD:** To avoid the risk of electrical shock and to prevent damage to the printer, remove the power cord from the electrical outlet and disconnect all connections to any external devices before you connect or disconnect any cable, electronic board, or assembly.
-  **CAUTION—HOT SURFACE:** The inside of the printer might be hot. To reduce the risk of injury from a hot component, allow the surface to cool before touching it.
-  **CAUTION—PINCH HAZARD:** To avoid the risk of a pinch injury, use caution in areas marked with this label. Pinch injuries may occur around moving parts, such as gears, doors, trays, and covers.

Précautions de dépannage

-  **ATTENTION—RISQUE D'ELECTROCUTION :** Ce symbole indique un danger lié à des niveaux de tension dangereux dans la zone du produit à manipuler. Débranchez le produit avant de commencer, ou agissez avec prudence si le produit doit être alimenté pour effectuer l'opération.
-  **ATTENTION—RISQUE D'ELECTROCUTION :** Ce produit utilise un commutateur d'alimentation électronique. Il ne déconnecte pas physiquement la tension d'alimentation CA. Pour éviter tout risque d'électrocution, débranchez toujours le cordon d'alimentation de l'imprimante lorsque vous devez déconnecter la tension d'alimentation CA.
-  **ATTENTION—RISQUE D'ELECTROCUTION :** Pour éviter tout risque d'électrocution lors du dépannage de l'imprimante avec les capots retirés ou les portes ouvertes, prenez garde de ne pas toucher les fils ou circuits dénudés si l'imprimante est connectée à une prise électrique.
-  **ATTENTION—RISQUE D'ELECTROCUTION :** Pour éviter tout risque d'électrocution et éviter d'endommager l'imprimante, débranchez le cordon d'alimentation de la prise électrique et déconnectez toute connexion à tout périphérique externe avant de brancher ou débrancher des câbles ou circuits et assemblages électroniques.
-  **ATTENTION—SURFACE CHAUDE :** L'intérieur de l'imprimante risque d'être brûlant. Pour réduire le risque de brûlure, laissez la surface ou le composant refroidir avant d'y toucher.
-  **ATTENTION : RISQUE DE PINCEMENT :** Pour éviter tout risque de blessure par pincement, agissez avec précaution au niveau des zones signalées par cette étiquette. Les blessures par pincement peuvent se produire autour des pièces mobiles telles que les engrenages, portes, tiroirs et capots.

Precauciones durante la solución de problemas

-  **PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS:** Cuando vea este símbolo en el producto, existe peligro de tensiones peligrosas en el área del producto en la que está trabajando. Desconecte el producto antes de empezar o tenga cuidado si el producto debe recibir alimentación a fin de realizar la tarea.
-  **PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS:** Este producto utiliza un interruptor de corriente electrónico. No desconecta físicamente la entrada de voltaje de CA. Para evitar el riesgo de descarga eléctrica, desenchufe siempre el cable de alimentación de la impresora cuando sea necesario retirar la entrada de voltaje de CA.
-  **PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS:** Para evitar el riesgo de descarga eléctrica al solucionar problemas sin las cubiertas o con las puertas abiertas, no toque los cables ni los circuitos expuestos mientras la impresora está conectada a una toma de corriente.
-  **PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS:** Para evitar el riesgo de descargas eléctricas y daños en la impresora, retire el cable de alimentación de la toma eléctrica y desconecte todas las conexiones a dispositivos externos antes de conectar o desconectar cualquier cable, placa electrónica o conjunto.
-  **PRECAUCIÓN: SUPERFICIE CALIENTE:** El interior de la impresora podría estar caliente. Para evitar el riesgo de heridas producidas por el contacto con un componente caliente, deje que la superficie se enfríe antes de tocarlo.
-  **PRECAUCIÓN: PELIGRO DE ATRAPAMIENTO:** Para evitar el riesgo de lesión por atrapamiento, preste atención en las áreas marcadas con esta etiqueta. Las lesiones por atrapamiento se pueden producir en torno a partes móviles, tales como engranajes, puertas, bandejas y cubiertas.

Vorsichtsmaßnahmen bei der Fehlerbehebung

-  **VORSICHT – STROMSCHLAGGEFAHR:** Wenn Sie dieses Symbol sehen, besteht eine Gefahr durch gefährliche Spannungen in dem Produktbereich, in dem Sie arbeiten. Trennen Sie das Produkt von seiner Stromverbindung, bevor Sie beginnen, oder gehen Sie vorsichtig vor, wenn das Produkt für die Durchführung der Aufgabe mit Strom versorgt werden muss.
-  **VORSICHT – STROMSCHLAGGEFAHR:** Dieses Produkt verwendet einen elektronischen Leistungsschalter. Er trennt die Eingangswchselspannung nicht physikalisch. Um das Risiko eines elektrischen Schlags zu vermeiden, ziehen Sie stets das Netzkabel vom Drucker ab, wenn eine Abtrennung der Eingangswchselspannung erforderlich ist.
-  **VORSICHT – STROMSCHLAGGEFAHR:** Um die Gefahr eines Stromschlags während der Fehlerbehebung bei entfernten Abdeckungen oder offenen Klappen zu vermeiden, berühren Sie die freiliegenden Drähte oder Stromkreise nicht, wenn der Drucker an eine Steckdose angeschlossen ist.
-  **VORSICHT – STROMSCHLAGGEFAHR:** Um das Risiko eines elektrischen Schlags und Schäden am Drucker zu vermeiden, ziehen Sie das Netzkabel aus der Steckdose und trennen Sie alle Verbindungen zu jeglichen externen Geräten, bevor Sie Kabel, Elektronikplatinen oder Baugruppen einstecken oder abziehen.
-  **VORSICHT – HEISSE OBERFLÄCHE:** Das Innere des Druckers kann sehr heiß sein. Vermeiden Sie Verletzungen, indem Sie heiße Komponenten stets abkühlen lassen, bevor Sie ihre Oberfläche berühren.



VORSICHT – QUETSCHGEFAHR: Um das Risiko einer Quetschung zu vermeiden, gehen Sie in Bereichen, die mit diesem Etikett gekennzeichnet sind, mit Vorsicht vor. Quetschungen können im Bereich von beweglichen Komponenten auftreten, wie z. B. Zahnrädern, Klappen, Fächern und Abdeckungen.

Troubleshooting overview

Performing the initial troubleshooting check

- With the power cord unplugged from the electrical outlet, check if the cord is free from breakage, short circuits, disconnected wires, or incorrect connections.
- Make sure that the printer is properly grounded.
- Make sure that the power supply line voltage is within 10% of the rated line voltage.
- Make sure that the printer is securely installed on a level surface in a well-ventilated area.
- Make sure that the temperature and relative humidity are within the specifications. See [“Temperature information” on page 234](#).
- Avoid locations that:
 - Generate ammonia gas
 - Are exposed to direct sunlight
 - Are near open flames
 - Are dusty
- Make sure that the recommended paper for this printer is used.
- Do a test print with paper from a newly opened package, and then check the result.

Using Safe Mode

Safe Mode lets the printer continue to operate in a special limited mode in which it attempts to continue offering as much functionality as possible despite known issues.

Notes:

- When in Safe Mode, the printer only prints in simplex mode from tray 1 at the slowest operating point.
- This setting cannot be used if the sensor (tray present) is damaged.

Warning—Potential Damage: Safe Mode is intended as a short-term workaround and must be used only in the case of a non-critical error when a print job must be completed before service can be arranged to repair the printer. The printer must be returned to standard operating mode before diagnostics can be run or full-function printing can continue.

Enter Safe Mode from the Configuration menu, and then POR the printer. See [“Config Menu” on page 140](#).

Return the printer to standard operating mode to service the printer and return to full-function printing.

Securing the printer

Resetting the printer without admin credentials

Notes:

- Resetting the printer or replacing the controller board deletes all security settings.
 - Before changing the security settings, ask permission from your administrator.
- 1 Perform an Out of Service Erase to reset the printer to factory defaults without using admin credentials. For more information, see [“Erasing printer memory” on page 34](#).

Warning—Potential Damage: This method makes the device vulnerable to hacking because it allows the creation of an admin account afterwards. By default, newer firmware versions restrict Out of Service Erase to admin users only, making the printer more secure and remembering the admin password more important.

- 2 If Out of Service Erase is unavailable, then use the security reset jumper to reset the printer to factory defaults. For more information, see [“Using the security reset jumper” on page 32](#).
- 3 If the effect of the jumper reset is disabled, then replace the controller board. For more information, see [“Controller board removal” on page 169](#).


Using the security reset jumper

The security reset jumper is on the controller board. It can be used if the admin password is lost or forgotten, and Out of Service Erase is not available.

Notes:

- To enable the effect of the security reset jumper, from the home screen navigate to: **Security > Miscellaneous > Security Reset Jumper > Enable “Guest” Access**.
 - To disable the effect of the jumper, select **No Effect** from the Security Reset Jumper section in the Security menu. If the password is forgotten or lost, perform an Out of Service Erase or replace the controller board. See [“Resetting the printer without admin credentials” on page 32](#) or [“Controller board removal” on page 169](#).
- 1 Turn off the printer.
 - 2 Remove the controller board shield.

- 3 Locate the security jumper (A) on the controller board.



- 4 Move the jumper to cover the middle and exposed prongs.

Note: The movement of the jumper triggers the reset, not the jumper position.

- 5 Attach the controller board shield.
- 6 Turn on the printer.

Notes:

- The security framework remains in place after the reset. Public permissions are reset to default and now include Out of Service Erase as an option.
- If LDAP is used to authenticate the copy function in MFPs, then the LDAP configuration and copy function are no longer protected.
- If Enable Audit is activated in the Security Audit Log, then the printer logs a message each time the jumper is reset.
- Physical access to the printer is required to use the jumper, making it more secure against hacking. To prevent tampering of the jumper, secure the controller board cage with a Kensington lock.

Data security notice

Identifying printer memory

- **Volatile memory**—The printer uses standard random access memory (RAM) to buffer user data temporarily during simple print and copy jobs.
- **Nonvolatile memory**—The printer may use two forms of nonvolatile memory: EEPROM and NAND (flash memory). Both types are used to store the operating system, printer settings, network information, scanner and bookmark settings, and embedded solutions.
- **Hard disk memory**—Some printers have a hard disk drive installed. The hard disk is designed for printer-specific functionality and cannot be used for long-term storage of data that is not print-related. The hard disk does not let users extract information, create folders, create disk or network file shares, or transfer FTP information directly from a client device. The hard disk can retain buffered user data from complex print jobs, form data, and font data.

The following parts can store memory:

- Printer control panel
- User interface controller card (UICC)
- Controller board
- Optional hard disks

Note: The printer control panel and controller board contain NVRAM.

Erasing printer memory

To erase volatile memory or buffered data, turn off the printer.

To erase non-volatile memory or individual settings, device and network settings, security settings, and embedded solutions, do the following:

- 1 From the control panel, navigate to:
Settings > Device > Maintenance > Out of Service Erase > Sanitize all information on nonvolatile memory > Yes
- 2 Select either **Start initial setup** or **Leave printer offline**.

Fixing print quality issues

Gray background or toner fog check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1</p> <p>a Remove any packing material left on the imaging unit.</p> <p>Note: You may need a pair of pliers to remove pieces of plastic inside the imaging unit.</p> <p>b Make sure that there are no obstructions between the charge roller and photoconductor drum.</p> <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.

Action	Yes	No
<p>Step 2</p> <p>a Turn off the printer, wait for 10 seconds, and then turn on the printer.</p> <p>b Set the toner darkness to a lighter setting. From the control panel, navigate to Settings > Print > Quality > Toner Darkness.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>Check if the printer is using a genuine and supported Lexmark toner cartridge.</p> <p>Note: If the printer is using a third-party cartridge, then refer the users to their cartridge supplier.</p> <p>Is the printer using a genuine and supported Lexmark toner cartridge?</p>	Go to step 5.	Go to step 4.
<p>Step 4</p> <p>Insert a genuine and supported Lexmark toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5</p> <p>Remove any packing material left on the imaging unit.</p> <p>Note: You may need a pair of pliers to remove pieces of plastic inside the imaging unit.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6</p> <p>Replace the toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Make sure that the HVPS1 cable on the controller board and HVPS is properly connected.</p> <p>Does the problem remain?</p>	Go to step 8.	The problem is solved.
<p>Step 8</p> <p>Replace the HVPS. See “HVPS removal” on page 171.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Blank page check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1 Verify that the toner cartridge is not empty.</p> <p>Is the toner cartridge empty?</p>	Go to step 2.	Go to step 3.
<p>Step 2 Replace the toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3 Check if the printer is using a genuine and supported Lexmark toner cartridge.</p> <p>Note: If the printer is using a third-party cartridge, then refer the users to their cartridge supplier.</p> <p>Is the printer using a genuine and supported Lexmark toner cartridge?</p>	Go to step 5.	Go to step 4.
<p>Step 4 Insert a genuine and supported Lexmark toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5</p> <p>a Remove any packing material left on the imaging unit.</p> <p>Note: You may need a pair of pliers to remove pieces of plastic inside the imaging unit.</p> <p>b Firmly shake the imaging unit to redistribute the toner, and then insert it.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.

Action	Yes	No
<p>Step 6</p> <p>a Make sure that the transfer roller is properly installed.</p> <p>b Check the transfer roller for contamination and damage.</p> <p>Is the transfer roller free of contamination and damage?</p>	Go to step 9.	Go to step 7.
<p>Step 7</p> <p>Remove, and then install the transfer roller. See “Transfer roller removal” on page 180.</p> <p>Does the problem remain?</p>	Go to step 8.	The problem is solved.
<p>Step 8</p> <p>Replace the transfer roller.</p> <p>Does the problem remain?</p>	Go to step 9.	The problem is solved.
<p>Step 9</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Make sure that the HVPS1 cable on the controller board and HVPS is properly connected.</p> <p>Does the problem remain?</p>	Go to step 10.	The problem is solved.
<p>Step 10</p> <p>Replace the HVPS. See “HVPS removal” on page 171.</p> <p>Does the problem remain?</p>	Go to step 11.	The problem is solved.
<p>Step 11</p> <p>Replace the printhead. See “Printhead removal” on page 186.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Print is too dark check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1</p> <p>Check if the printer is using a genuine and supported Lexmark toner cartridge.</p> <p>Note: If the printer is using a third-party cartridge, then refer the users to their cartridge supplier.</p> <p>Is the printer using a genuine and supported Lexmark toner cartridge?</p>	Go to step 3.	Go to step 2.
<p>Step 2</p> <p>Insert a genuine and supported Lexmark toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>a Remove any packing material left on the imaging unit.</p> <p>Note: You may need a pair of pliers to remove pieces of plastic inside the imaging unit.</p> <p>b Make sure that there are no obstructions between the charge roller and photoconductor drum.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4</p> <p>a Turn off the printer, wait for 10 seconds, and then turn on the printer.</p> <p>b Set the toner darkness to a lighter setting.</p> <p>From the control panel, navigate to Settings > Print > Quality > Toner Darkness.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5</p> <p>Replace the imaging unit.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Make sure that the HVPS1 cable on the controller board and HVPS is properly connected.</p> <p>Does the problem?</p>	Go to step 7.	The problem is solved.
<p>Step 7</p> <p>Replace the HVPS. See “HVPS removal” on page 171.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Print is too light check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1</p> <p>Check if the toner cartridge is empty or if it has reached its end of life.</p> <p>Is the toner cartridge empty or has reached its end of life?</p>	Go to step 2.	Go to step 3.
<p>Step 2</p> <p>Replace the toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>Check if the printer is using a genuine and supported Lexmark toner cartridge.</p> <p>Note: If the printer is using a third-party cartridge, then refer the users to their cartridge supplier.</p> <p>Is the printer using a genuine and supported Lexmark toner cartridge?</p>	Go to step 5.	Go to step 4.
<p>Step 4</p> <p>Insert a genuine and supported Lexmark toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.

Action	Yes	No
<p>Step 5</p> <p>a Turn off the printer, wait for 10 seconds, and then turn on the printer.</p> <p>b Do the following:</p> <ol style="list-style-type: none"> 1 Set the toner darkness to a darker setting. From the control panel, navigate to Settings > Print > Quality > Toner Darkness. 2 Set the paper type, texture, and weight to match the paper loaded. From the control panel, navigate to Settings > Paper > Media Configuration > Media Types. <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6</p> <p>a Remove the imaging unit.</p> <p>b Push either side of the transfer roller, and then check if it depresses and bounces back into place.</p> <p>c If the transfer roller does not depress and bounce back into place, then reinstall the transfer roller.</p> <p>d Firmly shake the toner cartridge to redistribute the toner, and then insert it.</p> <p>e Turn off the printer, wait for 10 seconds, and then turn on the printer.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7</p> <p>a Make sure that the transfer roller is properly installed.</p> <p>b Check the transfer roller for contamination and damage.</p> <p>Is the transfer roller free of contamination and damage?</p>	Go to step 9.	Go to step 8.
<p>Step 8</p> <p>Reinstall or replace the transfer roller. See “Transfer roller removal” on page 180.</p> <p>Does the problem remain?</p>	Go to step 9.	The problem is solved.
<p>Step 9</p> <p>Replace the imaging unit. See “Transfer roller removal” on page 180.</p> <p>Does the problem remain?</p>	Go to step 10.	The problem is solved.

Action	Yes	No
<p>Step 10</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Make sure that the HVPS1 cable on the controller board and HVPS is properly connected.</p> <p>Does the problem remain?</p>	Go to step 11.	The problem is solved.
<p>Step 11</p> <p>Replace the HVPS. See “HVPS removal” on page 171.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Paper curl check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31.](#)

Action	Yes	No
<p>Step 1</p> <p>Check if the printer is using a genuine and supported Lexmark toner cartridge.</p> <p>Note: If the printer is using a third-party cartridge, then refer the users to their cartridge supplier.</p> <p>Is the printer using a genuine and supported Lexmark toner cartridge?</p>	Go to step 3.	Go to step 2.
<p>Step 2</p> <p>Insert a genuine and supported Lexmark toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>Check if the printer is using a genuine and supported Lexmark fuser.</p> <p>Is the printer using a genuine and supported Lexmark fuser?</p>	Go to step 5.	Go to step 4.

Action	Yes	No
<p>Step 4</p> <p>Insert a genuine and supported Lexmark fuser.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5</p> <p>Make sure that the paper guide setting matches the size of the paper loaded.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6</p> <p>Set the paper type, texture, and weight to match the paper loaded.</p> <p>From the control panel, navigate to Settings > Paper > Media Configuration > Media Types.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7</p> <p>a Make sure that the paper loaded is from a fresh package.</p> <p>Note: Paper absorbs moisture due to high humidity. Store paper in its original wrapper until you use it.</p> <p>b Make sure that the printer supports the paper loaded.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Folded or wrinkled paper check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1</p> <p>a Check if the printer is using a non-Lexmark toner cartridge. Note: If the printer is using a third-party cartridge, then refer the users to their cartridge supplier.</p> <p>b Make sure that the toner cartridge is compatible with the imaging unit.</p> <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.
<p>Step 2</p> <p>a Check if the paper loaded is from a fresh package. Note: Paper absorbs moisture due to high humidity. Store paper in its original wrapper until you use it.</p> <p>b Make sure that the printer supports the paper loaded.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>a Check the toner cartridge for leaks.</p> <p>b Using an approved toner vacuum, completely remove the stray toner from the printer, toner cartridge, and imaging unit.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4</p> <p>a Remove the fuser. See “Fuser removal” on page 186.</p> <p>b Make sure that the fuser entry guide is free of waste toner and dust.</p> <p>Warning—Potential Damage: Clean the fuser entry guide with a toner vacuum and cloth. Do not use compressed air.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5</p> <p>Replace the fuser.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Solid black pages check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1 Check if the printer is using a genuine and supported Lexmark toner cartridge.</p> <p>Note: If the printer is using a third-party cartridge, then refer the users to their cartridge supplier.</p> <p>Is the printer using a genuine and supported Lexmark toner cartridge?</p>	Go to step 3.	Go to step 2.
<p>Step 2 Insert a genuine and supported Lexmark toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>a Remove any packing material left on the imaging unit.</p> <p>Note: You may need a pair of pliers to remove pieces of plastic inside the imaging unit.</p> <p>b Check the charge roller contact on the right side of the imaging unit for damage and contamination.</p>  <p>Is the charge roller contact free of damage and contamination?</p>	Go to step 6.	Go to step 4.
<p>Step 4</p> <p>a Perform a POR.</p> <p>b Perform a print test.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5 Replace the imaging unit.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.

Action	Yes	No
<p>Step 6</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Make sure that the HVPS1 cable on the controller board and HVPS is properly connected.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7</p> <p>Replace the HVPS. See “HVPS removal” on page 171.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Skewed print check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31.](#)

Action	Yes	No
<p>Step 1</p> <p>Check the guides in the tray where the skewed prints are printed from.</p> <p>Note: If the paper source is the MPF, then proceed to step 6.</p> <p>Does the position of the guides match the paper loaded?</p>	Go to step 3.	Go to step 2.
<p>Step 2</p> <p>Adjust the guides to match the paper loaded.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>Check if the printer supports the paper loaded.</p> <p>Is the paper supported?</p>	Go to step 5.	Go to step 4.

Action	Yes	No
<p>Step 4 Remove the paper, and then load a supported one.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5 Perform a print test.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6 Check the guides in the MPF tray.</p> <p>Does the position of the guides match the paper loaded?</p>	Go to step 8.	Go to step 7.
<p>Step 7 Adjust the guides to match the paper loaded.</p> <p>Does the problem remain?</p>	Go to step 8.	The problem is solved.
<p>Step 8 Make sure that the printer supports the paper loaded.</p> <p>Does the problem remain?</p>	Go to step 9.	The problem is solved.
<p>Step 9 Check the MPF pick roller for excess wear and contamination.</p> <p>Is the MPF pick roller free from excess wear and contamination?</p>	Go to step 11.	Go to step 10.
<p>Step 10 Replace the front door with MPF pick roller. See “Front door removal” on page 179.</p> <p>Does the problem remain?</p>	Go to step 11.	The problem is solved.
<p>Step 11 Reinstall or replace the transfer roller. See “Transfer roller removal” on page 180.</p> <p>Does the problem remain?</p>	Go to step 12.	The problem is solved.
<p>Step 12 Replace the imaging unit.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Streaked vertical lines appear on prints during a print job check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1</p> <p>a Make sure that the printer is not placed in a cold and damp area.</p> <p>b Print 15 simplex pages to dry the transfer roller.</p> <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.
<p>Step 2</p> <p>Check if the printer is using a genuine and supported Lexmark toner cartridge.</p> <p>Note: If the printer is using a third-party cartridge, then refer the users to their cartridge supplier.</p> <p>Is the printer using a genuine and supported Lexmark toner cartridge?</p>	Go to step 4.	Go to step 3.
<p>Step 3</p> <p>Insert a genuine and supported Lexmark toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4</p> <p>Check the status of the imaging unit.</p> <p>Is the imaging unit near its end of life?</p>	Go to step 6.	Go to step 5.
<p>Step 5</p> <p>Remove, and then insert the imaging unit.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6</p> <p>Replace the imaging unit.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Streaked vertical lines appear on prints during a copy job check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1</p> <p>a Make sure that the printer is not placed in a cold and damp area.</p> <p>b Print 15 simplex pages to dry the transfer roller.</p> <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.
<p>Step 2</p> <p>Clean the scanner. See “Cleaning the scanner” on page 209.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>Open the scanner cover, and then check if it closes properly.</p> <p>Does the cover close properly?</p>	Go to step 5.	Go to step 4.
<p>Step 4</p> <p>Make sure that the scanner glass pad is clean and properly installed.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5</p> <p>With the scanner cover open, perform a copy job to check the scanner lamp.</p> <p>Note: The scanner lamp must light up and move along the scan area.</p> <p>Is the scanner lamp functional?</p>	Go to step 7.	Go to step 6.

Action	Yes	No
<p>Step 6</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Reseat the scanner cables.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7</p> <p>Check the scanner and its components for damage.</p> <ul style="list-style-type: none"> • Scanner lamp • Motor (scanner) • Scanner belt • Glass panes • Cables <p>Are the scanner and its components free of damage?</p>	Go to step 9.	Go to step 8.
<p>Step 8</p> <p>Replace the ADF and scanner. See “ADF and scanner removal” on page 193.</p> <p>Does the problem remain?</p>	Go to step 9.	The problem is solved.
<p>Step 9</p> <p>Check the firmware version.</p> <p>Is the firmware updated to the latest version?</p>	Go to step 11.	Go to step 10.
<p>Step 10</p> <p>Update the firmware.</p> <p>Does the problem remain?</p>	Go to step 11.	The problem is solved.
<p>Step 11</p> <p>a Make sure that the controller board is properly installed.</p> <p>b Reseat all the cables on the controller board.</p> <p>Does the problem remain?</p>	Go to step 12.	The problem is solved.
<p>Step 12</p> <p>Replace the controller board. See “Controller board removal” on page 169.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Horizontal light bands check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1 Check if the banding is along the edge of the paper.</p> <p>Is the banding along the edge of the paper?</p>	Go to step 2.	Go to step 3.
<p>Step 2 Replace the fuser. See “Fuser removal” on page 186.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3 Check if the toner cartridge is empty or if it has reached its end of life.</p> <p>Is the toner cartridge empty or has reached its end of life?</p>	Go to step 4.	Go to step 5
<p>Step 4 Replace the toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5 Check if the printer is using a genuine and supported Lexmark toner cartridge.</p> <p>Note: If the printer is using a third-party cartridge, then refer the users to their cartridge supplier.</p> <p>Is the printer using a genuine and supported Lexmark toner cartridge?</p>	Contact the next level of support.	Go to step 6.
<p>Step 6 Insert a genuine and supported Lexmark toner cartridge.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Vertical light bands check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1 Check if the banding is along the edge of the paper.</p> <p>Is the banding along the edge of the paper?</p>	Go to step 2.	Go to step 3.
<p>Step 2 Replace the fuser. See “Fuser removal” on page 186.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3 Check if the printer is using a genuine and supported Lexmark toner cartridge.</p> <p>Note: If the printer is using a third-party cartridge, then refer the users to their cartridge supplier.</p> <p>Is the printer using a genuine and supported Lexmark toner cartridge?</p>	Go to step 5.	Go to step 4.
<p>Step 4 Insert a genuine and supported Lexmark toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5</p> <ul style="list-style-type: none"> a Remove the imaging unit. b Clean the printhead laser glass window with a soft cloth. <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Vertical dark bands check




Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1 Check if the banding is along the edge of the paper.</p> <p>Is the banding along the edge of the paper?</p>	Go to step 2.	Go to step 3.
<p>Step 2 Replace the fuser. See “Fuser removal” on page 186.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>a Remove any packing material left on the imaging unit. Note: You may need a pair of pliers to remove pieces of plastic inside the imaging unit.</p> <p>b Make sure that there are no obstructions between the charge roller and photoconductor drum.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4 Check if the printer is using a genuine and supported Lexmark toner cartridge. Note: If the printer is using a third-party cartridge, then refer the users to their cartridge supplier.</p> <p>Is the printer using a genuine and supported Lexmark toner cartridge?</p>	Go to step 6.	Go to step 5.
<p>Step 5 Insert a genuine and supported Lexmark toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.

Action	Yes	No
<p>Step 6 Remove, and then insert the imaging unit.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Vertical dark streaks with print missing check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1 Check if the toner cartridge is empty or if it has reached its end of life.</p> <p>Is the toner cartridge empty or has reached its end of life?</p>	Go to step 2.	Go to step 3.
<p>Step 2 Replace the toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3 Check if the printer is using a genuine and supported Lexmark toner cartridge.</p> <p>Note: If the printer is using a third-party cartridge, then refer the users to their cartridge supplier.</p> <p>Is the printer using a genuine and supported Lexmark toner cartridge?</p>	Go to step 5.	Go to step 4.
<p>Step 4 Insert a genuine and supported Lexmark toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.

Action	Yes	No
<p>Step 5</p> <p>a Remove any packing material left on the imaging unit.</p> <p>Note: You may need a pair of pliers to remove pieces of plastic inside the imaging unit.</p> <p>b Check the charge roller contact on the right side of the imaging unit for damage and contamination.</p>  <p>Is the charge roller contact free of damage and contamination?</p>	Contact the next level of support.	Go to step 6.
<p>Step 6</p> <p>Replace the imaging unit.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

White streaks and voided areas check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1</p> <p>Check if the printer is using a genuine and supported Lexmark toner cartridge.</p> <p>Note: If the printer is using a third-party cartridge, then refer the users to their cartridge supplier.</p> <p>Is the printer using a genuine and supported Lexmark toner cartridge?</p>	Go to step 3.	Go to step 2.
<p>Step 2</p> <p>Insert a genuine and supported Lexmark toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>a Perform a POR.</p> <p>b Perform a print test.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4</p> <p>Check the status of the imaging unit.</p> <p>Is the imaging unit near its end of life?</p>	Go to step 5.	Contact the next level of support.
<p>Step 5</p> <p>Replace the imaging unit.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Clipped pages or images check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1</p> <p>a Remove any packing material left on the imaging unit.</p> <p>Note: You may need a pair of pliers to remove pieces of plastic inside the imaging unit.</p> <p>b Make sure that there are no obstructions between the charge roller and photoconductor drum.</p> <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.
<p>Step 2</p> <p>Remove, and then insert the toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>Check if the printer is using a genuine and supported Lexmark toner cartridge.</p> <p>Note: If the printer is using a third-party cartridge, then refer the users to their cartridge supplier.</p> <p>Is the printer using a genuine and supported Lexmark toner cartridge?</p>	Go to step 5.	Go to step 4.
<p>Step 4</p> <p>Insert a genuine and supported Lexmark toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5</p> <p>Remove, and then insert the imaging unit.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6</p> <p>Replace the imaging unit.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7</p> <p>a Remove the imaging unit.</p> <p>b Clean the printhead laser glass window with a soft cloth.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Incorrect margins on prints check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1</p> <p>Adjust the guides in the tray to match the size of the paper loaded.</p> <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.
<p>Step 2</p> <p>Do either of the following:</p> <ul style="list-style-type: none"> Set the paper size to match the paper loaded in the tray. Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Printer registration adjustments Change the paper loaded in the tray to match the paper size set in the tray. <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Toner rubs off check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1</p> <p>Check if the printer is using a genuine and supported Lexmark toner cartridge.</p> <p>Note: If the printer is using a third-party cartridge, then refer the users to their cartridge supplier.</p> <p>Is the printer using a genuine and supported Lexmark toner cartridge?</p>	Go to step 3.	Go to step 2.
<p>Step 2</p> <p>Insert a genuine and supported Lexmark toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>Set the paper type, texture, and weight to match the paper loaded.</p> <p>From the control panel, navigate to Settings > Paper > Media Configuration > Media Types.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4</p> <p>Remove, and then install the fuser. See “Fuser removal” on page 186.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5</p> <p>Replace the fuser.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Toner specks appear on prints during a print job check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1</p> <p>Check if the printer is using a genuine and supported Lexmark toner cartridge.</p> <p>Note: If the printer is using a third-party cartridge, then refer the users to their cartridge supplier.</p> <p>Is the printer using a genuine and supported Lexmark toner cartridge?</p>	Go to step 3.	Go to step 2.
<p>Step 2</p> <p>Insert a genuine and supported Lexmark toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>a From the control panel, navigate to Status/Supplies > Supplies.</p> <p>b Check the status of the imaging unit.</p> <p>Is the imaging unit near its end of life or showing signs of toner leakage?</p>	Go to step 4.	Go to step 5.
<p>Step 4</p> <p>Replace the imaging unit.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5</p> <p>Check if toner specks appear only on the edges or back side of the paper.</p> <p>Do toner specks appear only on the edges or back side of the paper?</p>	Go to step 6.	Go to step 7.
<p>Step 6</p> <p>Replace the transfer roller. See “Transfer roller removal” on page 180.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7</p> <p>Check the printer for stray toner contamination.</p> <p>Is the printer contaminated with stray toner?</p>	Go to step 8.	Contact the next level of support.
<p>Step 8</p> <p>Using an approved toner vacuum, completely remove the stray toner from the printer, toner cartridge, and imaging unit.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Toner specks appear on prints during a copy job check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1 Clean the scanner. See “Cleaning the scanner” on page 209.</p> <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.
<p>Step 2 Check the firmware version.</p> <p>Is the firmware updated to the latest version?</p>	Go to step 4.	Go to step 3.
<p>Step 3 Update the firmware.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4 Replace the ADF and scanner. See “ADF and scanner removal” on page 193.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5</p> <ul style="list-style-type: none"> a Make sure that the controller board is properly installed. b Reseat all the cables on the controller board. <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6 Replace the controller board. See “Controller board removal” on page 169.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Repeating defects check



Note: Before performing this print quality check, print the Print Quality Test Pages. From the control panel, navigate to **Settings > Troubleshooting > Print Quality Test Pages**, and then perform the initial print quality check. See [“Performing the initial troubleshooting check” on page 31](#).

Action	Yes	No
<p>Step 1</p> <p>Using the Print Quality Test Pages, check if the distance between the repeating defects is equal to any of the following:</p> <ul style="list-style-type: none"> • 37.7 mm (1.48 in.) • 96 mm (3.78 in.) <p>Does the distance between the repeating defects match any of the measurements?</p>	Go to step 2.	Go to step 3.
<p>Step 2</p> <p>Replace the imaging unit.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>Check if the distance between the repeating defects is equal to any of the following:</p> <ul style="list-style-type: none"> • 37.5 mm (1.48 in.) • 43.5 mm (1.71 in.) <p>Does the distance between the repeating defects match any of the measurements?</p>	Go to step 4.	Go to step 5.
<p>Step 4</p> <p>Replace the toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5</p> <p>Check if the distance between the repeating defects is equal to 52 mm (2.05 in.).</p> <p>Does the distance between the repeating defects match the measurement?</p>	Go to step 6.	Go to step 7.

Action	Yes	No
<p>Step 6 Replace the transfer roller. See “Transfer roller removal” on page 180.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7 Check if the distance between the repeating defects is equal to any of the following:</p> <ul style="list-style-type: none"> • 62.5 mm (2.46 in.) • 79.8 mm (3.14 in.) <p>Does the distance between the repeating defects match any of the measurements?</p>	Go to step 8.	Contact the next level of support.
<p>Step 8 Replace the fuser. See “Fuser removal” on page 186.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Paper jams

200 paper jams

200 paper jam messages

Error code	Description	Action
200.02	Paper fed from the MPF was detected earlier than expected at the sensor (input).	See “Sensor (input): Paper arrived too early jam service check” on page 63 .
200.04	Paper fed from the MPF cleared the sensor (input) earlier than expected.	See “Sensor (input): Paper cleared too early jam service check” on page 64 .
200.05	Paper fed from the MPF never cleared the sensor (input).	See “Sensor (input): Paper failed to clear jam service check” on page 67 .
200.06	Paper fed from the MPF was detected later than expected or was never detected at the sensor (input).	See “Sensor (input): Paper failed to arrive jam service check” on page 65 .
200.12	Paper fed from tray 1 was detected earlier than expected at the sensor (input).	See “Sensor (input): Paper arrived too early jam service check” on page 63 .
200.13	Paper fed from tray 1 was detected later than expected or was never detected at the sensor (input).	See “Sensor (input): Paper failed to arrive jam service check” on page 65 .
200.14	Paper fed from tray 1 cleared the sensor (input) earlier than expected.	See “Sensor (input): Paper cleared too early jam service check” on page 64 .

Error code	Description	Action
200.15	Paper fed from tray 1 never cleared the sensor (input).	See “Sensor (input): Paper failed to clear jam service check” on page 67.
200.22	Paper fed from tray 2 was detected earlier than expected at the sensor (input).	See “Sensor (input): Paper arrived too early jam service check” on page 63.
200.23	Paper fed from tray 2 was detected later than expected or was never detected at the sensor (input).	See “Sensor (input): Paper failed to arrive jam service check” on page 65.
200.24	Paper fed from tray 2 cleared the sensor (input) earlier than expected.	See “Sensor (input): Paper cleared too early jam service check” on page 64.
200.25	Paper fed from tray 2 never cleared the sensor (input).	See “Sensor (input): Paper failed to clear jam service check” on page 67.
200.91	Paper remains detected at the sensor (input) after the printer is turned on.	See “Sensor (input): Static jam service check” on page 69.

Sensor (input): Paper arrived too early jam service check

Action	Yes	No
<p>Step 1 Identify the source tray.</p> <p>Is MPF the source tray?</p>	Go to step 2.	Go to step 4.
<p>Step 2 <ul style="list-style-type: none"> a Make sure that the MPF pick roller is free of contamination. b Clean the MPF pick roller. </p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3 Replace the front door. See “Front door removal” on page 179.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.
<p>Step 4 Make sure that the paper is properly loaded in the tray.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5 Make sure that each tray is free of paper fragments and partially fed paper.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.

Action	Yes	No
<p>Step 6</p> <p>a Make sure that the pick roller and separator roller are free from contamination.</p> <p>b Clean the pick roller and separator roller.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7</p> <p>a Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Sensor tests</p> <p>b Find the sensor (input).</p> <p>c Make sure that the sensor actuator freely moves and is not stuck.</p> <p>Does the sensor status change while toggling the sensor?</p>	Go to step 9.	Go to step 8.
<p>Step 8</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Make sure that the JMTR1 sensor cable is properly connected to the controller board.</p> <p>Does the problem remain?</p>	Go to step 9.	The problem is solved.
<p>Step 9</p> <p>Perform a print test.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Sensor (input): Paper cleared too early jam service check

Action	Yes	No
<p>Step 1</p> <p>a Remove the tray insert.</p> <p>b Make sure that the paper is properly loaded in the tray.</p> <p>c From the printer control panel or Printing Preferences or Print dialog, verify the paper size settings.</p> <p>Note: The tray has no size sensing mechanism. Manually set the paper size through the printer control panel or Printing Preferences or Print dialog.</p> <p>Does the paper size match the settings that you want?</p>	Go to step 3.	Go to step 2.
<p>Step 2</p> <p>Change the paper size or adjust the size setting in the tray.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.

Action	Yes	No
<p>Step 3</p> <p>a Make sure that the tray is not overfilled.</p> <p>b Make sure that the paper guides are not set too tight against the paper.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4</p> <p>Check the tray for crumpled, damaged, or deformed paper.</p> <p>Are there crumpled, damaged, or deformed paper in the tray?</p>	Go to step 5.	Go to step 6.
<p>Step 5</p> <p>Replace the crumpled, damaged, or deformed paper.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6</p> <p>a Enter theDiagnostics menu, and then navigate to: Printer diagnostics & adjustments > Sensor tests</p> <p>b Find the sensor (input).</p> <p>c Make sure that the sensor actuator freely moves and is not stuck.</p> <p>Does the sensor status change while toggling the sensor?</p>	Go to step 8.	Go to step 7.
<p>Step 7</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Make sure that the JMTR1 sensor cable is properly connected to the controller board.</p> <p>Does the problem remain?</p>	Go to step 8.	The problem is solved.
<p>Step 8</p> <p>Perform a print test.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Sensor (input): Paper failed to arrive jam service check

Note: This service check is not applicable to tray 2.

Action	Yes	No
<p>Step 1</p> <p>a Remove the tray insert.</p> <p>b Make sure that the paper is properly loaded in the tray.</p> <p>c From the printer control panel or Printing Preferences or Print dialog, verify the paper size settings.</p> <p>Note: The tray has no size sensing mechanism. Manually set the paper size through the printer control panel or Printing Preferences or Print dialog.</p> <p>Does the paper size match the settings that you want?</p>	Go to step 3.	Go to step 2.
<p>Step 2</p> <p>Change the paper size or adjust the size setting in the tray.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>a Make sure that the tray is not overfilled.</p> <p>b Make sure that the paper guides are not set too tight against the paper.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4</p> <p>Check the tray for crumpled, damaged, or deformed paper.</p> <p>Are there crumpled, damaged, or deformed paper in the tray?</p>	Go to step 5.	Go to step 6.
<p>Step 5</p> <p>Replace the crumpled, damaged, or deformed paper.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6</p> <p>a Enter theDiagnostics menu, and then navigate to: Printer diagnostics & adjustments > Sensor tests</p> <p>b Find the sensor (input).</p> <p>c Make sure that the sensor actuator freely moves and is not stuck.</p> <p>Does the sensor status change while toggling the sensor?</p>	Go to step 8.	Go to step 7.
<p>Step 7</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Make sure that the JMTR1 sensor cable is properly connected to the controller board.</p> <p>Does the problem remain?</p>	Go to step 8.	The problem is solved.

Action	Yes	No
<p>Step 8 Perform a print test.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Sensor (input): Paper failed to clear jam service check

Action	Yes	No
<p>Step 1</p> <p>a Remove the tray insert.</p> <p>b Make sure that the paper is properly loaded in the tray.</p> <p>c From the printer control panel or Printing Preferences or Print dialog, verify the paper size settings.</p> <p>Note: The tray has no size sensing mechanism. Manually set the paper size through the printer control panel or Printing Preferences or Print dialog.</p> <p>Does the paper size match the settings that you want?</p>	Go to step 3.	Go to step 2.
<p>Step 2</p> <p>Change the paper size or adjust the size setting in the tray.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>a Make sure that the tray is not overfilled.</p> <p>b Make sure that the paper guides are not set too tight against the paper.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4</p> <p>Check the tray for crumpled, damaged, or deformed paper.</p> <p>Are there crumpled, damaged, or deformed paper in the tray?</p>	Go to step 5.	Go to step 6.
<p>Step 5</p> <p>Replace the crumpled, damaged, or deformed paper.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6</p> <p>Identify the source tray.</p> <p>Is MPF the source tray?</p>	Go to step 7.	Go to step 9.

Action	Yes	No
<p>Step 7 Make sure that the MPF pick roller is free of contamination.</p> <p>Does the problem remain?</p>	Go to step 8.	The problem is solved.
<p>Step 8 Replace the front door. See “Front door removal” on page 179.</p> <p>Does the problem remain?</p>	Go to step 9.	The problem is solved.
<p>Step 9 Make sure that the pick roller is free of contamination.</p> <p>Does the problem remain?</p>	Go to step 10.	The problem is solved.
<p>Step 10</p> <ul style="list-style-type: none"> a Replace the pick roller. b Replace the separator roller. <p>Does the problem remain?</p>	Go to step 11.	The problem is solved.
<p>Step 11</p> <ul style="list-style-type: none"> a Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Sensor tests b Find the sensor (input). c Make sure that the sensor actuator freely moves and is not stuck. <p>Does the sensor status change while toggling the sensor?</p>	Go to step 13.	Go to step 12.
<p>Step 12</p> <ul style="list-style-type: none"> a Remove the right cover. See “Right cover removal” on page 167. b Make sure that the JMTR1 sensor cable is properly connected to the controller board. <p>Does the problem remain?</p>	Go to step 13.	The problem is solved.
<p>Step 13 Perform a print test.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Sensor (input): Static jam service check

Action	Yes	No
Step 1 Check the paper path for paper fragments and partially fed paper. Is the paper path free of paper fragments and partially fed paper?	Go to step 3.	Go to step 2.
Step 2 Remove the paper fragments and partially fed paper. Does the problem remain?	Go to step 3.	The problem is solved.
Step 3 a Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Sensor tests b Find the sensor (input). c Make sure that the sensor actuator freely moves and is not stuck. Does the sensor status change while toggling the sensor?	Go to step 5.	Go to step 4.
Step 4 a Remove the right cover. See “Right cover removal” on page 167. b Make sure that the JMTR1 sensor cable is properly connected to the controller board. Does the problem remain?	Go to step 5.	The problem is solved.
Step 5 Perform a print test. Does the problem remain?	Contact the next level of support.	The problem is solved.

202 paper jams

202 paper jam messages

Error code	Description	Action
202.03	Paper fed from the MPF never arrived at the sensor (fuser exit).	See “Sensor (fuser exit): Paper failed to arrive jam service check” on page 70.
202.13	Paper fed from tray 1 never arrived at the sensor (fuser exit).	
202.23	Paper fed from tray 2 never arrived at the sensor (fuser exit).	
202.x4	Paper cleared the sensor (fuser exit) too soon.	See “Sensor (fuser exit): Paper cleared too early jam service check” on page 72.

Error code	Description	Action
202.05	Paper fed from the MPF never cleared the sensor (fuser exit).	See “Sensor (fuser exit): Paper failed to clear jam service check” on page 72.
202.15	Paper fed from tray 1 never cleared the sensor (fuser exit).	
202.25	Paper fed from tray 2 never cleared the sensor (fuser exit).	
202.91	Paper remains detected at the sensor (fuser exit) after the printer is turned on.	See “Sensor (fuser exit): Static jam service check” on page 74.
202.93	The sensor (fuser exit) detected a jam during or after a flush action.	
202.95	Paper fed from an unknown tray never cleared the sensor (fuser exit).	

Sensor (fuser exit): Paper failed to arrive jam service check

Action	Yes	No
<p>Step 1</p> <p>Check the fuser paper path for paper fragments and partially fed paper.</p> <p>Is the fuser paper path free of paper fragments and partially fed paper?</p>	Go to step 3.	Go to step 2.
<p>Step 2</p> <p>Remove the paper fragments and partially fed paper.</p> <p>Warning—Potential Damage: Do not remove any paper or paper fragments from the fuser using tools.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>a Remove paper in the tray, flip it over, and then reload paper.</p> <p>b Resend the print job.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4</p> <p>Replace the paper in the tray, and then resend the print job.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.

Action	Yes	No
<p>Step 5</p> <p>a Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Sensor tests</p> <p>b Find the sensor (fuser exit).</p> <p>c Make sure that the sensor actuator freely moves and is not stuck.</p> <p>Does the sensor status change while toggling the sensor?</p>	Go to step 7.	Go to step 6.
<p>Step 6</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Make sure that the JEXIT1 sensor cable is properly connected to the controller board.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7</p> <p>a Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Motor tests</p> <p>b Find the main motor (forward).</p> <p>c Open the front door, remove the imaging unit, and then close the front door.</p> <p>d Activate the motor test.</p> <p>e Open the rear door, and then check if the fuser belt is properly rotating.</p> <p>Is the fuser belt properly rotating?</p>	Go to step 9.	Go to step 8.
<p>Step 8</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Make sure that the JMTR1 sensor cable is properly connected to the controller board.</p> <p>Does the problem remain?</p>	Go to step 9.	The problem is solved.
<p>Step 9</p> <p>Replace the fuser. See “Fuser removal” on page 186.</p> <p>Does the problem remain?</p>	Go to step 10.	The problem is solved.
<p>Step 10</p> <p>Perform a print job.</p> <p>Does the problem remain?</p>	Go to step 11.	The problem is solved.

Action	Yes	No
<p>Step 11 Replace the main drive gears. See “Main drive gears removal” on page 159.</p> <p>Does the problem remain?</p>	Go to step 12.	The problem is solved.
<p>Step 12 a Make sure that the metal shutter in the printer frame is not stuck. b Check the metal shutter for fuser entry.</p> <p>Does the metal shutter freely move?</p>	Contact the next level of support.	The problem is solved.

Sensor (fuser exit): Paper cleared too early jam service check

Action	Yes	No
<p>Step 1 Remove all paper from the bin.</p> <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.
<p>Step 2 Check the fuser exit area, rear door, and redrive area for jammed paper or paper fragments.</p> <p>Are there jammed paper or paper fragments?</p>	Go to step 3.	Contact the next level of support.
<p>Step 3 Remove the jammed paper or paper fragments.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Sensor (fuser exit): Paper failed to clear jam service check

Action	Yes	No
<p>Step 1 a Make sure that the fuser exit area, rear door, and redrive area are free of jammed paper or paper fragments b Make sure that the rear door can properly close. c Check the rear door for damage.</p> <p>Is the rear door functional and free of damage?</p>	Go to step 3.	Go to step 2.

Action	Yes	No
<p>Step 2</p> <p>a Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Sensor tests</p> <p>b Find the sensor (fuser exit).</p> <p>c Make sure that the sensor actuator freely moves and is not stuck.</p> <p>Does the sensor status change while toggling the sensor?</p>	Go to step 5.	Go to step 3.
<p>Step 3</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Make sure that the JEXIT1 sensor cable is properly connected to the controller board.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4</p> <p>Replace the rear door. See “Rear door removal” on page 185.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5</p> <p>Replace the fuser. See “Fuser removal” on page 186.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6</p> <p>Check the redrive for damage.</p> <p>Is the redrive free of damage?</p>	Go to step 8.	Go to step 7.
<p>Step 7</p> <p>Replace the redrive. See “Redrive removal” on page 188.</p> <p>Does the problem remain?</p>	Go to step 8.	The problem is solved.
<p>Step 8</p> <p>Perform a print test.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Sensor (fuser exit): Static jam service check

Action	Yes	No
<p>Step 1 Remove paper fragments and partially fed paper.</p> <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.
<p>Step 2 a Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Sensor tests b Find the sensor (fuser exit). c Make sure that the sensor actuator freely moves and is not stuck.</p> <p>Does the sensor status change while toggling the sensor?</p>	Go to step 4.	Go to step 3.
<p>Step 3 a Remove the right cover. See “Right cover removal” on page 167. b Make sure that the JEXIT1 sensor cable is properly connected to the controller board.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4 Perform a print test.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

232 paper jams

232 paper jam messages

Error code	Description	Action
232.03	Paper fed from MPF was detected later than expected or was never detected at the sensor (input) during a duplex print job.	See “Sensor (input): Paper (duplex job) failed to arrive jam service check” on page 75.
232.13	Paper fed from tray 1 was detected later than expected or was never detected at the sensor (input) during a duplex print job.	
232.23	Paper fed from tray 2 was detected later than expected or was never detected at the sensor (input) during a duplex print job.	
232.05	Paper fed from the MPF never cleared the sensor (input) during a duplex print job.	
232.15	Paper fed from tray 1 never cleared the sensor (input) during a duplex print job.	
232.25	Paper fed from tray 2 never cleared the sensor (input) during a duplex print job.	
232.93	Paper fed from an unknown tray was detected later than expected or was never detected at the sensor (input) during a duplex print job.	
232.95	Paper fed from an unknown tray never cleared the sensor (input) during a duplex print job.	

Sensor (input): Paper (duplex job) failed to arrive jam service check

Action	Yes	No
<p>Step 1</p> <p>Remove all paper from the bin, and then resend the print job.</p> <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.
<p>Step 2</p> <p>Check the fuser access area for jammed paper and obstructions.</p> <p>Is the fuser access area free of jammed paper and obstructions?</p>	Go to step 4.	Go to step 3.
<p>Step 3</p> <p>Remove the jammed paper and obstructions.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.

Action	Yes	No
<p>Step 4</p> <p>Check the duplex path area for jammed paper and obstructions.</p> <p>Is the duplex path area free of jammed paper and obstructions?</p>	Go to step 6.	Go to step 5.
<p>Step 5</p> <p>Remove the jammed paper and obstructions.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6</p> <p>Check the duplex guide for proper installation.</p> <p>Is the duplex guide properly installed?</p>	Go to step 8.	Go to step 7.
<p>Step 7</p> <p>Reseat the duplex guide, and then make sure that it is properly closed.</p> <p>Does the problem remain?</p>	Go to step 8.	The problem is solved.
<p>Step 8</p> <p>Check the duplex guide for damage.</p> <p>Is the duplex guide free of damage?</p>	Go to step 10.	Go to step 9.
<p>Step 9</p> <p>Replace the duplex guide. See “Duplex guide removal” on page 191.</p> <p>Does the problem remain?</p>	Go to step 10.	The problem is solved.
<p>Step 10</p> <p>a Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Sensor tests</p> <p>b Find the sensor (input).</p> <p>c Make sure that the sensor actuator freely moves and is not stuck.</p> <p>Does the sensor status change while toggling the sensor?</p>	Go to step 12.	Go to step 11.
<p>Step 11</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Make sure that the JMTR1 sensor cable is properly connected to the controller board.</p> <p>Does the problem remain?</p>	Go to step 12.	The problem is solved.

Action	Yes	No
<p>Step 12 Perform a print test.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

242 paper jams

242 paper jam messages

Error code	Description	Action
242.26	Paper fed from tray 2 was picked but it never reached the sensor (input).	See “Optional tray pick drive failure service check” on page 96.
242.80	Paper jam caused by the motor (tray 2) not turning on.	
242.81	Paper jam caused by the motor (tray 2) not turning off.	
242.82	Paper jam caused by the motor (tray 2) speed not ramping up to the required level.	
242.83	Paper jam caused by the motor (tray 2) stalling.	
242.84	Paper jam caused by the motor (tray 2) running too slow.	
242.85	Paper jam caused by the motor (tray 2) running too fast.	
242.86	Paper jam caused by the motor (tray 2) running too long.	

280–295 paper jams

280–295 paper jam messages

Error code	Description	Action
280.11	Paper remains detected at the sensor (ADF scan) after the printer is turned on.	See “ADF jam service check” on page 78.
280.13	Paper never arrived at the sensor (ADF scan).	
280.15	Paper never cleared the sensor (ADF scan).	
295.01	An imagepipe error occurred. Gap between scanned pages is too small.	

ADF jam service check

Action	Yes	No
<p>Step 1</p> <p>Check the ADF paper path for paper fragments, partially fed paper, and obstructions.</p> <ul style="list-style-type: none"> • Under the ADF cover • Under the ADF • ADF bin <p>Is the paper path free of paper fragments, partially fed paper, and obstructions?</p>	Go to step 3.	Go to step 2.
<p>Step 2</p> <p>Remove the paper fragments, partially fed paper, and obstructions.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>a Open the ADF cover, and then check if it closes properly.</p> <p>b Check the cover for improper installation.</p> <p>Is the ADF cover functional and properly installed?</p>	Go to step 5.	Go to step 4.
<p>Step 4</p> <p>a Reinstall the ADF cover.</p> <p>b Check the ADF cover for damage.</p> <p>Is the ADF cover free of damage?</p>	Go to step 5.	Go to step 6.
<p>Step 5</p> <p>a Check the ADF cover pick mechanism for improper operation.</p> <p>b Check the ADF pick roller and feed roller for wear, damage, and contamination.</p> <p>Are the pick components functional and free of wear, damage, and contamination?</p>	Go to step 7.	Go to step 6.
<p>Step 6</p> <p>Clean the affected components or replace the ADF cover. See “ADF cover removal” on page 192.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7</p> <p>a Check the ADF separator pad for improper installation.</p> <p>b Check the separator pad for wear, damage, and contamination.</p> <p>Is the ADF separator pad properly installed and free of wear, damage, and contamination?</p>	Go to step 9.	Go to step 8.

Action	Yes	No
<p>Step 8 Reinstall, clean, or replace the ADF separator pad. See “ADF separator pad removal” on page 193.</p> <p>Does the problem remain?</p>	Go to step 9.	The problem is solved.
<p>Step 9 a Enter the Diagnostics menu, and then navigate to: Scanner diagnostics > Motor tests b Select ADF transport, and then start the test.</p> <p>Does the motor run?</p>	Go to step 11.	Go to step 10.
<p>Step 10 a Make sure that the ADF is properly installed. Lift the ADF, and then check if it closes properly. b Check the ADF for damage.</p> <p>Is the ADF free of damage?</p>	Go to step 11.	Go to step 16.
<p>Step 11 a Enter the Diagnostics menu, and then navigate to: Scanner diagnostics > Sensor tests b Run the test on the following sensors:</p> <ul style="list-style-type: none"> • ADF paper present • ADF scan <p>Do the status of the sensors change while toggling the sensors?</p>	Go to step 13.	Go to step 12.
<p>Step 12 Check the affected sensor and its flag for damage.</p> <p>Is the sensor free of damage?</p>	Go to step 13.	Go to step 16.
<p>Step 13 a Enter the Diagnostics menu, and then navigate to: Scanner diagnostics > Motor tests b Select Scanner, and then start the test.</p> <p>Does the motor run?</p>	Go to step 17.	Go to step 14.

Action	Yes	No
<p>Step 14</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Reseat the following cables on the controller board:</p> <ul style="list-style-type: none"> • JADFM1 • JFBM1 • JSCANSNS1 • scanner ground cable <p>Does the problem remain?</p>	Go to step 15.	The problem is solved.
<p>Step 15</p> <p>Check the scanner and its components for damage.</p> <ul style="list-style-type: none"> • Belt • Cables <p>Is the scanner free of damage?</p>	Go to step 17.	Go to step 16.
<p>Step 16</p> <p>Replace the ADF and scanner. See “ADF and scanner removal” on page 193.</p> <p>Does the problem remain?</p>	Go to step 17.	The problem is solved.
<p>Step 17</p> <p>Make sure that the controller board is properly installed. Reseat all the cables on the controller board.</p> <p>Does the problem remain?</p>	Go to step 18.	The problem is solved.
<p>Step 18</p> <p>Check the controller board and its connector pins for damage.</p> <p>Are the controller board and its connectors free of damage?</p>	Contact the next level of support.	Go to step 19.
<p>Step 19</p> <p>Replace the controller board. See “Controller board removal” on page 169.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

User attendance messages

29-33 user attendance messages

29–33 user attendance messages

Error code	Description	Action
29.xx	Packing material present on supplies.	Remove the packing material from the supplies.
31.40	The toner cartridge is missing or unresponsive.	See “Unsupported or unresponsive toner cartridge service check” on page 82.
31.60	The imaging unit is missing or unresponsive.	See “Unsupported or unresponsive imaging unit service check” on page 81.
32.40	The toner cartridge is unsupported.	See “Unsupported or unresponsive toner cartridge service check” on page 82.
32.60	The imaging unit is unsupported.	See “Unsupported or unresponsive imaging unit service check” on page 81.
33.40	A non-Lexmark black toner cartridge was detected.	See “Unsupported or unresponsive toner cartridge service check” on page 82.
33.60		

Unsupported or unresponsive imaging unit service check

Action	Yes	No
<p>Step 1</p> <p>Check whether the imaging unit installed is genuine and supported by the printer model.</p> <p>Is the imaging unit a genuine and supported Lexmark unit?</p>	Go to step 3.	Go to step 2.
<p>Step 2</p> <p>Install a genuine and supported Lexmark imaging unit.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>a Check the imaging unit contacts for contamination. b Check the imaging unit for leaks and damage.</p> <p>Are the imaging unit and its contacts free of contamination and damage?</p>	Go to step 5.	Go to step 4.
<p>Step 4</p> <p>Clean or replace the imaging unit.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.

Action	Yes	No
<p>Step 5</p> <p>a Check the imaging unit smart chip contacts for contamination. b Check if the contacts are bent or damaged.</p> <p>Are the contacts free of contamination and damage?</p>	Go to step 7.	Go to step 6.
<p>Step 6</p> <p>Clean or repair the smart chip contact.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7</p> <p>Reseat the smart chip contact cable on the controller board.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Unsupported or unresponsive toner cartridge service check

Action	Yes	No
<p>Step 1</p> <p>Check whether the toner cartridge installed is genuine.</p> <p>Is the cartridge a genuine and supported Lexmark unit?</p>	Go to step 3.	Go to step 2.
<p>Step 2</p> <p>Install a genuine and supported Lexmark toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>a Check the toner cartridge contacts for contamination. b Check the toner cartridge for leaks and damage.</p> <p>Are the toner cartridge and its contacts free of contamination and damage?</p>	Go to step 5.	Go to step 4.
<p>Step 4</p> <p>Clean or replace the toner cartridge.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5</p> <p>Check the toner cartridge smart chip contacts for contamination.</p> <p>Are the contacts free of contamination?</p>	Go to step 7.	Go to step 6.

Action	Yes	No
Step 6 Clean the smart chip contact. Does the problem remain?	Go to step 7.	The problem is solved.
Step 7 Reseat the smart chip contact cable on the controller board. Does the problem remain?	Contact the next level of support.	The problem is solved.

4y user attendance messages

41-43 user attendance messages

Note: The .xy in the error code after 42 indicates the printer and cartridge regions. Where x is the printer region and y is the cartridge region. The numeric value is from 0 to 6. See the following table for the xy definitions:

Printer and toner cartridge regions

Region	Numeric code
The printer is not regionalized and matches any regionalized cartridge.	0y
The cartridge is not regionalized and only matches with printer region 0.	x0
North America (United States, Canada)	1
European Economic Area, Western Europe, Nordic countries, Switzerland	2
Asia Pacific	3
Latin America	4
Rest of Europe, Middle East, Africa	5
Australia, New Zealand	6
Invalid region	9

Error code	Description	Action
41.60	The imaging unit and toner cartridge are mismatched or incompatible.	See “Mismatched supplies error service check” on page 85.
42.10	Toner cartridge region does not match the printer region.	See “Toner cartridge service check” on page 86.
42.02		
42.03		
42.04		
42.05		
42.09		
42.10		
42.12		
42.13		
42.14		
42.15		
42.19		
42.20		
42.21		
42.23		
42.24		
42.25		
42.29		
42.30		

Error code	Description	Action
42.31	Toner cartridge region does not match the printer region.	See “Toner cartridge service check” on page 86.
42.32		
42.34		
42.35		
42.39		
42.40		
42.41		
42.42		
42.43		
42.45		
42.49		
42.50		
42.51		
42.52		
42.53		
42.54		
42.59		
42.90		
42.91		
42.92		
42.93		
42.94		
42.95		
43.40	A toner cartridge sensor error was detected.	

Mismatched supplies error service check

Action	Yes	No
<p>Step 1</p> <p>Check whether the supplies installed are genuine and supported by the printer model.</p> <p>Are the supplies genuine and supported Lexmark units?</p>	Go to step 3.	Go to step 2.
<p>Step 2</p> <p>Install genuine and supported Lexmark units.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.

Action	Yes	No
<p>Step 3 Replace the affected supply with the correct unit.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Toner cartridge service check

Action	Yes	No
<p>Step 1 Make sure that the imaging unit and toner cartridge are genuine Lexmark supplies.</p> <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.
<p>Step 2</p> <ul style="list-style-type: none"> a Shake the toner cartridge. b Clean the toner cartridge smart chip contacts, and then check the contacts for damage. c Clean the toner cartridge spring contacts, and then check the contacts for damage. d Perform a print test. <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3 Reset the printer configuration. See “Restoring the printer configuration” on page 152.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

8y user attendance messages

80-88 user attendance messages

Error code	Description	Action
80.0x	The remaining life of the fuser, pick roller, or transfer roller are nearly low.	See “Supplies low service check” on page 88.
80.1x	The remaining life of the fuser, pick roller, or transfer roller are low.	
80.2x	The remaining life of the fuser, pick roller, or transfer roller are very low.	
80.3x	The life of the fuser, pick roller, or transfer roller has ended.	
84.0x	The remaining life of the imaging unit is nearly low.	
84.1x	The remaining life of the imaging unit is low.	
84.2x	The remaining life of the imaging unit is very low.	
84.3x	The imaging unit life has ended.	
84.4x	The imaging unit life has ended. The printer forces a hard stop on the imaging unit.	
88.0x	The remaining life of the toner cartridge is nearly low.	
88.1x	The remaining life of the toner cartridge is low.	
88.2x	The remaining life of the toner cartridge is very low.	
88.3x	The toner cartridge life has ended.	
88.4x	The toner cartridge life has ended. The printer forces a hard stop on the toner cartridge.	

Supplies low service check

Action	Yes	No
<p>Step 1 Perform a print test on paper from a fresh package, and then check the result.</p> <p>Are there print quality defects on the test page?</p>	Go to step 2.	Go to step 3.
<p>Step 2 Identify, and then resolve the print quality defects. See the “Fixing print quality issues” section.</p> <p>Note: If a supply was replaced, then make sure that the maintenance kit counter is reset.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3 Perform a feed test to check if the printer has paper feed problems.</p> <p>Does the printer have a problem feeding paper during the test?</p>	Go to step 4.	Go to step 5.
<p>Step 4 Resolve the feed problem.</p> <p>Note: If a transfer roller was replaced, then make sure that the maintenance kit counter is reset.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5 Replace the affected part with a new one.</p> <ul style="list-style-type: none"> • Fuser • Pick roller • Transfer roller <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Printer hardware errors

111 errors

111 error messages

Error code	Description	Action
111.20	Printhead error (mirror motor lock) was detected before the motor was turned on.	See “Printhead service check” on page 89 .
111.21	No printhead power (+5 V) when the laser servo started.	
111.30	The printhead failed during power-on tests.	
111.31	Printhead error (no first HSYNC) was detected.	
111.32	Printhead error (lost HSYNC) was detected.	
111.33	Printhead error (lost HSYNC) was detected during servo.	
111.34	Printhead error (mirror motor lost lock) was detected.	
111.35	Printhead error (mirror motor never got first lock) was detected.	
111.36	Printhead error (mirror motor lock never stabilized) was detected.	
111.37	Paper reached the sensor but the mirror motor was not locked.	
111.38	Paper reached the sensor (input) but the printhead startup was not complete.	
111.40	The wrong printhead is installed.	
111.91	Printhead error (bad facet time reading).	

Printhead service check

Action	Yes	No
Step 1 Perform a POR. Does the problem remain?	Go to step 2.	The problem is solved.
Step 2 a Make sure that the JVD01 and JMIR1 cables are properly connected on the controller board. b Check the cables for damage. Are the cables properly connected and free of damage?	Go to step 4.	Go to step 3.

Action	Yes	No
<p>Step 3 Replace the printhead. See “Printhead removal” on page 186.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4 Perform a POR.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5 Replace the controller board. See “Controller board removal” on page 169.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

121 errors

121 error messages

Error code	Description	Action
121.00	Fuser did not reach the required temperature.	See “Fuser service check” on page 92.
121.02	Fuser went over the required temperature during EWC/line voltage detection.	
121.04	During an attempt to heat up, the fuser relay was open and the micro-controller was not reporting an error.	
121.05	During an attempt to heat up, the fuser relay was open and the micro-controller was reporting an error.	
121.10	Fuser did not reach the required temperature during the start of EWC/line voltage detection.	
121.11	Fuser reached the required temperature too late during the final EWC/line voltage detection.	
121.12	Fuser did not reach the required temperature during the final EWC/line voltage detection.	
121.13	Fuser reached the required temperature too fast during the final EWC/line voltage detection.	
121.14	Fuser is heating too fast.	
121.20	Fuser did not reach the required temperature during steady state control. This can occur during printing or in standby mode.	
121.22	Open fuser relay was detected.	
121.23	Fuser relay was turned off, but the feedback to the engine code indicated that it was still open.	
121.24	Fuser did not reach the required temperature during the final EWC/line voltage detection.	
121.28	Fuser did not reach the required temperature during EP warm-up.	
121.32	Fuser did not reach the required temperature at 100% power.	
121.33	Fuser did not reach the required temperature while page is in the fuser).	
121.34	Fuser did not reach the required temperature during steady state control.	
121.50	Fuser went over the required temperature during global over-temp check.	
121.52	Main thermistor temperature is out of range.	
121.53	Main thermistor temperature change rate is out of range.	
121.71	Open fuser main heater thermistor was detected.	

Fuser service check

Action	Yes	No
<p>Step 1 Make sure that the fuser is properly installed.</p> <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.
<p>Step 2 Check whether the fuser installed is genuine and supported by the printer model.</p> <p>Is the fuser a genuine and supported Lexmark unit?</p>	Go to step 3.	Go to step 5.
<p>Step 3 Check if the fuser type is compatible with the printer model.</p> <p>Are the fuser and printer compatible?</p>	Go to step 4.	Go to step 5.
<p>Step 4 Check the fuser life.</p> <p>Has the fuser reached its end of life?</p>	Go to step 5.	Go to step 6.
<p>Step 5 Replace the fuser. See “Fuser removal” on page 186.</p> <p>Note: Make sure that the new fuser is supported by the printer model.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6 Make sure that the voltage output of the electrical outlet matches the voltage rating of the printer.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7 Make sure that the JFUSER1 and JEXIT1 cables are properly connected on the controller board.</p> <p>Does the problem remain?</p>	Go to step 8.	The problem is solved.
<p>Step 8 Make sure that the high voltage cable is properly connected to the LVPS.</p> <p>Does the problem remain?</p>	Go to step 9.	The problem is solved.
<p>Step 9 Perform a POR.</p> <p>Does the problem remain?</p>	Go to step 10.	The problem is solved.

Action	Yes	No
Step 10 Replace the LVPS. See “LVPS removal” on page 171. Does the problem remain?	Go to step 11.	The problem is solved.
Step 11 Replace the fuser. See “Fuser removal” on page 186. Does the problem remain?	Contact the next level of support.	The problem is solved.

126 errors

126 error messages

Error code	Description	Action
126.01	Line frequency has gone outside the operating range.	See “LVPS service check” on page 93.
126.02	No line frequency was detected.	
126.05	The LVPS power dropped but the printer was not in sleep mode.	
126.06	LVPS 25 V line error was detected.	
126.07	LVPS 5 V rail was down during power-on.	
126.10	No line frequency was detected.	
126.11	Line frequency exceeded the operating range.	
126.14	LVPS relay is stuck or closed.	

LVPS service check

Action	Yes	No
Step 1 Make sure that the printer is directly plugged into the electrical outlet. Does the problem remain?	Go to step 2.	The problem is solved.
Step 2 Make sure that the voltage output of the electrical outlet matches the voltage rating of the printer. Does the problem remain?	Go to step 3.	The problem is solved.

Action	Yes	No
<p>Step 3</p> <p>a Make sure that the PCN1 cable on the LVPS is properly connected.</p> <p>b Make sure that the JLVPS1 cable on the controller board is properly connected.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4</p> <p>Make sure that the voltage output of the electrical outlet matches the voltage rating of the LVPS.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5</p> <p>Perform a POR.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6</p> <p>Replace the LVPS. See “LVPS removal” on page 171.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7</p> <p>Perform a POR.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

140 errors

140 error messages

Error code	Description	Action
140.80	Motor (main drive) does not turn on.	See “Motor (main drive) service check” on page 95 .
140.81	Motor (main drive) does not turn off.	
140.82	Motor (main drive) speed did not ramp up to the required level.	
140.83	Motor (main drive) stalled.	
140.85	Motor (main drive) ran too fast.	
140.86	Motor (main drive) ran too long.	

Motor (main drive) service check

Action	Yes	No
<p>Step 1</p> <p>a Remove the imaging unit.</p> <p>b Manually turn the photoconductor gear, and then check the cleaning blade for damage or failure.</p> <p>Does the photoconductor drum rotate?</p>	Go to step 3.	Go to step 2.
<p>Step 2</p> <p>Replace the imaging unit.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>a Make sure that the JMTR1 cable is properly connected to the controller board.</p> <p>b Check the cable for damage.</p> <p>Is the cable free of damage?</p>	Go to step 5.	Go to step 4.
<p>Step 4</p> <p>Replace the JMTR1 cable.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5</p> <p>Perform a POR.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

162 errors

162 error messages

Error code	Description	Action
162.80	The motor (tray 2 pick) does not turn on.	See “Optional tray pick drive failure service check” on page 96.
162.81	The motor (tray 2 pick) does not turn off.	
162.82	The motor (tray 2 pick) speed did not ramp up to the required level.	
162.83	The motor (tray 2 pick) stalled.	
162.84	The motor (tray 2 pick) ran too slow.	
162.85	The motor (tray 2 pick) ran too fast.	
162.86	The motor (tray 2 pick) ran too long.	

Optional tray pick drive failure service check

Action	Yes	No
<p>Step 1 Check if the optional tray motor (pick) runs.</p> <p>Does the motor run?</p>	Go to step 3.	Go to step 2.
<p>Step 2 Reseat the motor cable, and then reseat the cable on the optional tray controller board.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3 a Remove the optional tray. b Under the printer, check the interconnect cable for damage.</p> <p>Is the cable free of damage?</p>	Go to step 5.	Go to step 4.
<p>Step 4 Insert the optional tray.</p> <p>Note: Make sure that the interconnect cable properly fits with the socket on the optional tray.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5 a Remove the tray insert from the optional tray. b Check if the lift plate moves properly. c Check the lift plate gears for damage.</p> <p>Is the tray insert functional and free of damage?</p>	Contact the next level of support.	Go to step 6.
<p>Step 6 Replace the tray insert.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

6yy errors

600-680 error messages

Error code	Description	Action	
600.01	Toner tally from the RIP was not received.	Resend the print job. If the problem remains, then contact the next level of support.	
600.02	Video did not start.		
600.04	Duplex page was not picked.		
600.05	Invalid PH NVRAM Type error was detected.		
600.06	Paper port driver is unresponsive.		
600.07	Page is at image point before EP is ready.		
600.09	EP update error was detected.		
600.10	EP late run-in error was detected.		
600.11	Packing material was detected by the sensor (toner density).		Remove the imaging unit and toner cartridge, and then make sure that all packing material are properly removed.
600.95	RIP intentionally declared a jam error, usually to prevent a kiosk user from printing free pages.		Resend the print job. If the problem remains, then contact the next level of support.
602.29	Tray 2 was not ready for picking.	See “Optional tray pick drive failure service check” on page 96.	
611.02	An Input ISR error occurred and the printhead was not ready.	See “Printhead service check” on page 89.	
611.32	Lost Hsync errors were detected. Laser safety interlock system may be the cause.		
611.33	Lost Hsync errors were detected during servo.		
611.34	A mirror motor lock error was detected.		
611.35	Mirror motor never got first lock.		
611.36	Mirror motor lock never stabilized.		
611.37	Paper reached the sensor (input) but the mirror motor was not locked.		
611.38	Paper reached the sensor (input) but the printhead startup was not complete.		
621.01	Fuser heater was too cold when paper entered the fuser nip.	Resend the print job. If the problem remains, then contact the next level of support.	
640.84	The motor (main drive) stalled or ran too slow.	See “Motor (main drive) service check” on page 95.	

Error code	Description	Action
662.23	The tray 2 lift plate failed to lift.	See “Optional tray pick drive failure service check” on page 96.
662.80	Jam detection caused by motor (tray 2) not turning on.	
662.81	Jam detection caused by motor (tray 2) not turning off.	
662.82	Jam detection caused by motor (tray 2) speed not ramping up to the required level.	
662.83	Jam detection caused by motor (tray 2) stalling.	
662.84	Jam detection caused by motor (tray 2) running too slow.	
662.85	Jam detection caused by motor (tray 2) running too fast.	
662.86	Jam detection caused by motor (tray 2) running too long.	
680.20	During an ADF job, there was no paper detected on the ADF tray.	See “ADF failure service check” on page 99.
680.40	During a scan job, a communication error occurred.	See “Scanner communication error service check” on page 100.

Fuser overheated service check

Action	Yes	No
<p>Step 1</p> <p>a Allow fuser to cool for three minutes.</p> <p>b Resend the print job.</p> <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.
<p>Step 2</p> <p>Replace the fuser. See “Fuser removal” on page 186.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

ADF failure service check

Action	Yes	No
<p>Step 1</p> <p>Check the ADF paper path for paper fragments, partially fed paper, and obstructions.</p> <ul style="list-style-type: none"> • Under the ADF cover • Under the ADF • ADF bin <p>Is the paper path free of paper fragments, partially fed paper, and obstructions?</p>	Go to step 3.	Go to step 2.
<p>Step 2</p> <p>Remove the paper fragments, partially fed paper, and obstructions.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>a Enter the Diagnostics menu, and then navigate to: Scanner diagnostics > Motor tests</p> <p>b Select ADF transport, and then start the test.</p> <p>Does the motor run?</p>	Go to step 5.	Go to step 4.
<p>Step 4</p> <p>a Make sure that the ADF is properly installed. Lift the ADF, and then check if it closes properly.</p> <p>b Check the ADF for damage.</p> <p>Is the ADF free of damage?</p>	Go to step 5.	Go to step 9.
<p>Step 5</p> <p>a Enter the Diagnostics menu, and then navigate to: Scanner diagnostics > Sensor tests</p> <p>b Run the test on the following sensors:</p> <ul style="list-style-type: none"> • ADF paper present • ADF scan <p>Does the sensor status change while toggling the sensors?</p>	Go to step 10.	Go to step 6.
<p>Step 6</p> <p>Check the affected sensor and its flag for damage.</p> <p>Is the sensor free of damage?</p>	Go to step 7.	Go to step 9.

Action	Yes	No
<p>Step 7</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Reseat the scanner cables.</p> <p>Does the problem remain?</p>	Go to step 8.	The problem is solved.
<p>Step 8</p> <p>Check the cable for damage.</p> <p>Is the cable free of damage?</p>	Go to step 10.	Go to step 9.
<p>Step 9</p> <p>Replace the ADF and scanner. See “ADF and scanner removal” on page 193.</p> <p>Does the problem remain?</p>	Go to step 10.	The problem is solved.
<p>Step 10</p> <p>Make sure that the controller board is properly installed. Reseat all the cables on the controller board.</p> <p>Does the problem remain?</p>	Go to step 11.	The problem is solved.
<p>Step 11</p> <p>Check the controller board and its connector pins for damage.</p> <p>Are the controller board and its connectors free of damage?</p>	Contact the next level of support.	Go to step 12.
<p>Step 12</p> <p>Replace the controller board. See “Controller board removal” on page 169.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Scanner communication error service check

Action	Yes	No
<p>Step 1</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Reseat the following cables on the controller board:</p> <ul style="list-style-type: none"> • JADFM1 • JFBM1 • JSCANSNS1 • scanner ground cable <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.

Action	Yes	No
<p>Step 2</p> <p>Make sure that the scanner ground cable is properly connected to the controller board.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>Replace the ADF and scanner. See “ADF and scanner removal” on page 193.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4</p> <p>Replace the controller board. See “Controller board removal” on page 169.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

84y errors

840–845 error messages

Error code	Description	Action
840.01	The scanner was manually disabled by the user.	See “Scanner communication failure service check” on page 102.
840.02	The scanner was automatically disabled by the printer after two consecutive hardware failures.	
842.00	A scanner communication error (no response) was detected.	
842.01	A scanner communication error (HW protocol) was detected.	
842.02	A scanner communication error (logical protocol) was detected.	
843.00	The scanner CIS failed to reach its home position.	See “Scanner noise service check” on page 104.
845.02	A front side scan error occurred.	See “Scanner communication failure service check” on page 102.
845.03	A back side scan error occurred.	See “Duplex scan error service check” on page 105.

Scanner communication failure service check

Action	Yes	No
<p>Step 1</p> <p>Check the ADF paper path for paper fragments, partially fed paper, and obstructions.</p> <ul style="list-style-type: none"> • Under the ADF cover • Under the ADF • ADF bin <p>Is the paper path free of paper fragments, partially fed paper, and obstructions?</p>	Go to step 3.	Go to step 2.
<p>Step 2</p> <p>Remove the paper fragments, partially fed paper, and obstructions.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Reseat the scanner cables on the controller board.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4</p> <p>Check the cables for damage.</p> <p>Is the cable free of damage?</p>	Go to step 5.	Go to step 12.
<p>Step 5</p> <p>a From the control panel, navigate to: Settings > Device > Maintenance > Config Menu > Scanner Configuration > Disable Scanner</p> <p>b Select Enable.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6</p> <p>a Enter the Diagnostics menu, and then navigate to: Scanner diagnostics > Motor tests</p> <p>b Select ADF transport, and then start the test.</p> <p>Does the motor run?</p>	Go to step 8.	Go to step 7.
<p>Step 7</p> <p>a Make sure that the ADF is properly installed. Lift the ADF, and then check if it closes properly.</p> <p>b Check the ADF for damage.</p> <p>Is the ADF free of damage?</p>	Go to step 8.	Go to step 13.

Action	Yes	No
<p>Step 8</p> <p>a Enter the Diagnostics menu, and then navigate to: Scanner diagnostics > Sensor tests</p> <p>b Run the test on the following sensors:</p> <ul style="list-style-type: none"> • ADF paper present • ADF scan <p>Does the sensor status change while toggling the sensors?</p>	Go to step 10.	Go to step 9.
<p>Step 9</p> <p>Check the affected sensor and its flag for damage.</p> <p>Is the sensor free of damage?</p>	Go to step 10.	Go to step 13.
<p>Step 10</p> <p>a Enter the Diagnostics menu, and then navigate to: Scanner diagnostics > Motor tests</p> <p>b Select Scanner, and then start the test.</p> <p>Does the motor run?</p>	Go to step 14.	Go to step 11.
<p>Step 11</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Reseat the scanner cables.</p> <p>Does the problem remain?</p>	Go to step 12.	The problem is solved.
<p>Step 12</p> <p>Check the scanner and its components for damage.</p> <ul style="list-style-type: none"> • CIS • Belt • Cables <p>Is the scanner free of damage?</p>	Go to step 14.	Go to step 13.
<p>Step 13</p> <p>Replace the ADF and scanner. See “ADF and scanner removal” on page 193.</p> <p>Does the problem remain?</p>	Go to step 14.	The problem is solved.
<p>Step 14</p> <p>Make sure that the controller board is properly installed. Reseat all the cables on the controller board.</p> <p>Does the problem remain?</p>	Go to step 15.	The problem is solved.

Action	Yes	No
<p>Step 15 Check the controller board and its connector pins for damage.</p> <p>Are the controller board and its connectors free of damage?</p>	Contact the next level of support.	Go to step 16.
<p>Step 16 Replace the controller board. See “Controller board removal” on page 169.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Scanner noise service check

Action	Yes	No
<p>Step 1 With the scanner cover open, do a copy job to check the scanner lamp.</p> <p>Note: The scanner lamp must light up and move along the scan area.</p> <p>Is the scanner lamp functional?</p>	Go to step 3.	Go to step 2.
<p>Step 2 a Remove the right cover. See “Right cover removal” on page 167. b Reseat the scanner cables on the controller board.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3 Check the scanner and its components for damage.</p> <ul style="list-style-type: none"> • Scanner lamp • Motor (scanner) • Scanner belt • Glass panes • Cables <p>Are the scanner and its components free of damage?</p>	Go to step 5.	Go to step 4.
<p>Step 4 Replace the ADF and scanner. See “ADF and scanner removal” on page 193.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.

Action	Yes	No
<p>Step 5 Check the firmware version.</p> <p>Is the firmware updated to the latest version?</p>	Go to step 7.	Go to step 6.
<p>Step 6 Update the firmware.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7 Make sure that the controller board is properly installed. Reseat all the cables on the controller board.</p> <p>Does the problem remain?</p>	Go to step 8.	The problem is solved.
<p>Step 8 Replace the controller board. See “Controller board removal” on page 169.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Duplex scan error service check

Action	Yes	No
<p>Step 1 Check the ADF paper path for paper fragments, partially fed paper, and obstructions.</p> <ul style="list-style-type: none"> • Under the ADF cover • Under the ADF • ADF bin <p>Is the paper path free of paper fragments, partially fed paper, and obstructions?</p>	Go to step 3.	Go to step 2.
<p>Step 2 Remove the paper fragments, partially fed paper, and obstructions.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>a Enter the Diagnostics menu, and then navigate to: Scanner diagnostics > Motor tests</p> <p>b Select ADF transport, and then start the test.</p> <p>Does the motor run?</p>	Go to step 5.	Go to step 4.

Action	Yes	No
<p>Step 4</p> <p>a Make sure that the ADF is properly installed. Lift the ADF, and then check if it closes properly.</p> <p>b Check the ADF for damage.</p> <p>Is the ADF free of damage?</p>	Go to step 5.	Go to step 7.
<p>Step 5</p> <p>a Enter the Diagnostics menu, and then navigate to: Scanner diagnostics > Sensor tests</p> <p>b Run the test on the following sensors:</p> <ul style="list-style-type: none"> • ADF paper present • ADF scan <p>Does the sensor status change while toggling the sensors?</p>	Go to step 8.	Go to step 6.
<p>Step 6</p> <p>Check the affected sensor and its flag for damage.</p> <p>Is the sensor free of damage?</p>	Go to step 8.	Go to step 7.
<p>Step 7</p> <p>a Remove the right cover. See “Right cover removal” on page 167.</p> <p>b Reseat the scanner cables on the controller board.</p> <p>Does the problem remain?</p>	Go to step 8.	The problem is solved.
<p>Step 8</p> <p>Check the cable for damage.</p> <p>Is the cable free of damage?</p>	Go to step 9.	Go to step 10.
<p>Step 9</p> <p>With the scanner cover open, do a duplex copy job to check the ADF scanner lamp.</p> <p>Note: The scanner lamp must light up.</p> <p>Is the scanner lamp functional?</p>	Contact the next level of support.	Go to step 10.
<p>Step 10</p> <p>Replace the ADF and scanner. See “ADF and scanner removal” on page 193.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Procedure before starting the 9yy service checks

Retrieve certain information that helps your next level of support in diagnosing the problem before replacing the controller board.

Warning—Potential Damage: Do not replace the controller board unless instructed by your next level of support.

- 1 Collect the history information and firmware logs (Fwdebug and logs.tar.gz) from the SE menu.
- 2 Collect the settings from the Menu Settings Page.
- 3 Collect information from the user.

Note: Not all of the items are retrievable from the printer that you are working on.

A. Collecting the history information from the SE menu

Note: Make sure that your printer is connected to a network or to a print server.

- 1 Open a web browser, type **http://printer_IP_address/se**, and then press **Enter**.

Notes:

- **printer_IP_address** is the TCP/IP address of the printer.
- **se** is required to access the printer diagnostic information.

- 2 Click **History Information**, copy all information, and then save it as a text file.
- 3 Email the text file to your next level of support.

B. Collecting the firmware logs (Fwdebug and logs.tar.gz) from the SE menu

Notes:

- Make sure that your printer is connected to a network or to a print server.
- Some printers are designed to restart automatically after a 9yy error. On these printers, you can retrieve the secondary crash code information using the SE menu.

- 1 Open a web browser, type **http://printer_IP_address/se**, and then press **Enter**.
- 2 Click **Logs Gzip Compressed**.

Note: A logs.tar.gz file is saved to the Downloads folder. The file may take several minutes to save. You may rename the file if a logs.tar.gz already exists in the Downloads folder.

- 3 Email the logs to your next level of support.

Note: To download the FWdebug log to a flash drive, see [“General SE Menu” on page 143](#).

C. Collecting the settings from the Menu Settings Page

Note: The Menu Settings Page is different for each printer. For more information, see the *User's Guide*. Your next level of support will tell you which page they want to see.

Copying the Menu Settings Page from the Embedded Web Server (EWS)

Note: Make sure that your printer is connected to a network or to a print server.

- 1 Open a web browser, type **http://printer_IP_address**, and then press **Enter**.
- 2 Click **Settings**, and then select one of the settings pages from the links shown on the page.
- 3 Copy all the information, and then save it as a text file.
- 4 Email the text file to your next level of support.

Printing the Menu Settings Page

- 1 From the home screen, navigate to:
Reports > Menu Settings Page
- 2 Print the Menu Settings Page, and then email a scanned copy of the page to your next level of support.

D. Collecting information from the user

Ask the user for information about the following:

- Print job being run
- Operating system being used
- Print driver being used
- Other information on what was happening when the 9yy error occurred

900 errors

900 error messages

Error code	Description	Action
900.xx	Unrecoverable RIP software error/illegal trap.	See “900 error service check” on page 108 .

900 error service check

Action	Yes	No
Step 1 a Perform a POR. b Check if a 900.xx error code appears on the display. Does a 900.xx error code appear?	Go to step 4.	Go to step 2.
Step 2 Check if another type of error code appears instead of the 900.xx error code. Does a different error code appear?	Go to step 3.	Go to step 4.

Action	Yes	No
<p>Step 3 See the error code and its service instructions in the printer <i>Service Manual</i>.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4</p> <ul style="list-style-type: none"> a Turn off the printer. b At the rear of the printer, disconnect the network cable, USB cable, and fax line. c Turn on the printer. <p>Does the problem remain?</p>	Go to step 12.	Go to step 5.
<p>Step 5</p> <ul style="list-style-type: none"> a From the control panel, navigate to the Reports menu. b Select Device Statistics and Device Settings. <p>Does the problem remain?</p>	Go to step 12.	Go to step 6.
<p>Step 6 Check if the printer has a scanner.</p> <p>Does the printer have a scanner?</p>	Go to step 7.	Go to step 8.
<p>Step 7 Using the scanner, perform a one-page copy job in color.</p> <p>Does the problem remain?</p>	Go to step 12.	Go to step 8.
<p>Step 8</p> <ul style="list-style-type: none"> a Turn off the printer. b At the rear of the printer, connect the network cable, USB cable, and fax line. c Turn on the printer. <p>Does the problem remain?</p>	Go to step 9.	Go to step 10.
<p>Step 9</p> <ul style="list-style-type: none"> a Start the printer in Invalid engine mode. See “Entering invalid engine mode” on page 145. b Check if an Invalid Engine Code message appears. <p>Does an Invalid Engine Code message appear?</p>	Go to step 10.	Contact the next level of support.

Action	Yes	No
<p>Step 10</p> <p>Using the Device Settings report that is printed in step 5, check if the firmware level is older than the latest available version.</p> <p>Is the firmware version older, and does the customer agree to update the firmware?</p>	Go to step 11.	Contact the next level of support.
<p>Step 11</p> <p>Update the firmware to the latest version.</p> <p>Does the problem remain?</p>	Go to step 12.	The problem is solved.
<p>Step 12</p> <p>a Turn off the printer.</p> <p>b Reseat all FFC type cables on the controller board, and then make sure that the cables are properly connected.</p> <p>c Make sure that all the cables on the controller board and scanner are properly connected.</p> <p>d Turn on the printer.</p> <p>e From the control panel, navigate to the Reports menu, and then select Device Statistics and Device Settings.</p> <p>f For MFPs, perform a one-page copy and scan job in color.</p> <p>Does the problem remain?</p>	Go to step 13.	The problem is solved.
<p>Step 13</p> <p>Check if a hard disk is installed.</p> <p>Is a hard disk installed?</p>	Go to step 14.	Go to step 17.
<p>Step 14</p> <p>a Check for buffered print jobs, and then delete them.</p> <p>b Perform a POR.</p> <p>Does the problem remain?</p>	Go to step 15.	The problem is solved.
<p>Step 15</p> <p>a Turn off the printer.</p> <p>b Uninstall the hard disk.</p> <p>c Perform a POR.</p> <p>Does the problem remain?</p>	Go to step 17.	Go to step 16.
<p>Step 16</p> <p>Replace the hard disk.</p> <p>Does the problem remain?</p>	Go to step 17.	The problem is solved.

Action	Yes	No
<p>Step 17</p> <p>Check if the printer has any of the following components installed:</p> <ul style="list-style-type: none"> • Memory options • Fax card • Modem • Wireless and network option cards <p>Is any of the components installed?</p>	Go to step 18.	Go to step 21.
<p>Step 18</p> <p>a Turn off the printer.</p> <p>b Remove all the installed components.</p> <p>c Turn on the printer.</p> <p>Does the problem remain?</p>	Go to step 21.	Go to step 19.
<p>Step 19</p> <p>a Turn off the printer.</p> <p>b Install the following components one at a time:</p> <ul style="list-style-type: none"> • Memory options • Fax card • Modem • Wireless and network option cards <p>Note: Make sure to perform a POR after installing each component.</p> <p>Does the problem remain?</p>	Go to step 20.	The problem is solved.
<p>Step 20</p> <p>a Turn off the printer.</p> <p>b Replace the components that caused the error.</p> <p>c Turn on the printer.</p> <p>Does the problem remain?</p>	Go to step 21.	The problem is solved.
<p>Step 21</p> <p>Replace the controller board. See “Controller board removal” on page 169.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

912 errors

912 error messages

Error code	Description	Action
912.01	An engine error occurred.	Resend the print job. If the problem remains, then contact the next level of support.
912.02	An engine error occurred.	
912.04	An engine error occurred.	
912.05	An engine error occurred.	
912.06	An engine error occurred.	
912.07	An engine error occurred.	See “Optional tray communication error service check” on page 114.
912.08	An engine error occurred.	Resend the print job. If the problem remains, then contact the next level of support.
912.09	An engine error occurred.	
912.10	An engine error occurred.	
912.13	An engine error occurred.	
912.14	An engine error occurred.	
912.15	An engine error occurred.	
912.16	An engine error occurred.	
912.17	An engine error occurred.	
912.18	An engine error occurred.	
912.19	An engine error occurred.	
912.20	An engine error occurred.	
912.21	An engine error occurred.	
912.28	An engine error occurred.	
912.30	An engine error occurred.	
912.31	An engine error occurred.	
912.32	An engine error occurred.	
912.33	An engine error occurred.	
912.34	An engine error occurred.	
912.35	An engine error occurred.	
912.36	An engine error occurred.	
912.38	An engine error occurred.	See “Optional tray communication error service check” on page 114.

Error code	Description	Action
912.39	An engine error occurred.	Resend the print job. If the problem remains, then contact the next level of support.
912.40	An engine error occurred.	
912.42	An engine error occurred.	
912.43	An engine error occurred.	
912.44	An engine error occurred.	
912.45	An engine error occurred.	
912.46	An engine error occurred.	
912.48	An engine error occurred.	
912.49	An engine error occurred.	
912.51	An engine error occurred.	
912.52	An engine error occurred.	
912.53	An engine error occurred.	
912.54	An engine error occurred.	
912.55	An engine error occurred.	
912.56	An engine error occurred.	
912.57	An engine error occurred.	
912.58	An engine error occurred.	
912.60	An engine error occurred.	
912.61	An engine error occurred.	
912.64	An engine error occurred.	
912.65	An engine error occurred.	
912.66	An engine error occurred.	
912.69	An engine error occurred.	
912.70	An engine error occurred.	
912.72	An engine error occurred.	
912.73	An engine error occurred.	
912.74	An engine error occurred.	
912.75	An engine error occurred.	
912.77	An engine error occurred.	
912.86	An engine error occurred.	

Optional tray communication error service check

Action	Yes	No
<p>Step 1 Check the paper path and trays for paper fragments and partially fed paper.</p> <p>Is the paper path free of paper fragments and partially fed paper?</p>	Go to step 3.	Go to step 2.
<p>Step 2 Remove the paper fragments and partially fed paper.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3 Make sure that all the trays and tray inserts are properly inserted.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4 Enter the Diagnostics menu, and then select Input tray quick print. Perform a print test on the optional tray.</p> <p>Does the error occur in the optional tray?</p>	Go to step 5.	Contact the next level of support.
<p>Step 5</p> <ul style="list-style-type: none"> a Remove the optional tray. b Make sure that the interconnect cable of the tray is properly installed. c Check the interconnect cable and its connector pins for damage. d Make sure that the tray controller board is properly installed. e Reseat all the cables on the tray controller board. f Check the optional tray controller board and its connector pins for damage. <p>Are the tray interconnect cable and controller board free of damage?</p>	Contact the next level of support.	Go to step 6.
<p>Step 6 Replace the optional tray.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

938–992 errors

938–992 error messages

Error code	Description	Action
938.yy	Supplies security is not enabled.	Restart the printer. If the problem remains, then contact the next level of support.
950.10	Non-Generic FRU installed. Mismatch between system NVRAM part and mirror NVRAM part. Note: .xx points to the setting that does not match.	See “NVRAM mismatch failure service check” on page 115.
953.99	NVRAM chip failure with mirror part.	
980.yy	An option communication error occurred.	See “Optional tray communication error service check” on page 114.
981.yy	An invalid paper port protocol error occurred.	
982.yy	A paper port error occurred.	
983.yy	An unsupported paper port command error occurred.	
984.yy	An invalid paper port parameter error occurred.	
992.yy	An option device software error occurred.	

NVRAM mismatch failure service check

Warning—Potential Damage: To avoid NVRAM mismatch issues, replace only one of the following components at a time:

- Control panel
- Controller board

To replace a component and to test whether the problem is resolved:

- 1 Replace the affected component.

Warning—Potential Damage: Do not perform a Power-On Reset (POR) until the problem is resolved. If a POR is performed at this point, then the replacement part can no longer be used in another printer and must be returned to the manufacturer.

- 2 Enter the Diagnostics menu. The Diagnostics menu allows you to use temporarily the replacement part.

Warning—Potential Damage: Some printers perform automatically a POR if the Diagnostics menu is not opened within five seconds. If a POR is performed at this point, then the replacement part can no longer be used in another printer and must be returned to the manufacturer.

- 3 Use the Diagnostics menu to test the replacement part. Perform a feed test to check if the problem is resolved.
 - If the problem is not resolved—Turn off the printer, and then install the old part.
 - If the problem is resolved—Perform a POR.

Action	Yes	No
<p>Step 1</p> <p>Check if the control panel was recently replaced.</p> <p>Was the control panel recently replaced?</p>	Go to step 2.	Go to step 4.
<p>Step 2</p> <p>Replace the current control panel with the original control panel. See “Control panel removal” on page 178.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>Replace the original control panel with a new control panel.</p> <p>Note: Make sure that the new control panel is not previously installed from another printer.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.
<p>Step 4</p> <p>Check if the controller board was recently replaced.</p> <p>Was the controller board recently replaced?</p>	Go to step 5.	Contact the next level of support.
<p>Step 5</p> <p>Replace the current controller board with the original controller board. See “Controller board removal” on page 169.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6</p> <p>Replace the original controller board with a new controller board.</p> <p>Note: Make sure that the new controller board is not previously installed from another printer.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Other symptoms

Base printer symptoms

Base printer symptoms

Symptom	Action
A false tray paper low message appears.	See “Tray near empty service check” on page 117.
A false bin full message appears	See “False bin full error service check” on page 118.

Tray near empty service check

Action	Yes	No
<p>Step 1 Check the actuator in the tray insert for damage.</p> <p>Is the actuator free of damage?</p>	Go to step 3.	Go to step 2.
<p>Step 2 Replace the tray insert.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3 a Make sure that the sensor (tray near empty) is properly installed. b Check the sensor for damage.</p> <p>Is the sensor free of damage?</p>	Go to step 5.	Go to step 4.
<p>Step 4 Replace the sensor (tray near empty) assembly.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5 a Make sure that the sensor cable is properly connected to the controller board. b Check the sensor cable for damage.</p> <p>Is the sensor cable free of damage?</p>	Go to step 7.	Go to step 6.
<p>Step 6 Replace the sensor cable.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7 Perform a POR.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

False bin full error service check

Action	Yes	No
<p>Step 1 Remove, and then install the bin full sensor actuator. See “Bin full sensor actuator removal” on page 189.</p> <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.
<p>Step 2 Check the bin full sensor actuator for damage, and replace if necessary</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3 Check the sensor (bin full) for damage, and replace if necessary.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Fax symptoms

Fax symptoms

Symptom	Action
No dial tone.	See “Modem/fax card service check” on page 122.
The printer does not transmit faxes.	See “Fax transmission service check” on page 125.
The printer does not receive faxes.	See “Fax reception service check” on page 127.
Cannot set up etherFAX.	See “Cannot set up etherFAX” on page 123.
Cannot send or receive faxes using Etherfax.	See “Cannot send or receive faxes using etherFAX” on page 124.
A Lost connection to HTTPS Fax Server error message appears.	See “Lost connection to HTTPS fax server when using etherFAX service check” on page 130.

Fax error log codes

Error code	Description	Action
000	No error occurred during fax transmission.	No action is needed.
200	Error occurred when transmitting training.	<ul style="list-style-type: none"> • Check line quality. • Select a lower Max Speed value under Fax Send settings. • Adjust the transmit level.

Error code	Description	Action
3XX	Error occurred when receiving image data.	<ul style="list-style-type: none"> • Check line quality. • Adjust Receive Threshold. • Select a lower Max Speed value under Fax Receive settings.
4XX	Error occurred when sending image data.	<ul style="list-style-type: none"> • Check line quality. • Adjust 'Transmit Level'. • Select a lower 'Max Speed' value under Fax Receive settings.
5XX	Received unknown response from remote fax device.	No action needed. Issue is with the other device.
6XX	Error occurred when receiving a frame.	<ul style="list-style-type: none"> • Check line quality. • Adjust 'Receive Threshold'.
7XX	Error occurred when sending a frame.	<ul style="list-style-type: none"> • Check line quality. • Adjust 'Transmit Level'. • Select a lower 'Max Speed' value under Fax Send settings.
800	Received EOT unexpectedly from the modem in V34 mode.	If error persists, then disable V34 modulation scheme.
802	Too many timeouts occurred during ECM reception.	If error persists, then disable ECM mode.
803	Fax cancelled by user	No action needed.
804	Unexpectedly received a disconnect command from the remote end.	<ul style="list-style-type: none"> • Check line quality. • Adjust Transmit Level/Receive Threshold values. • Remote device could be requesting an unsupported feature.
805	Remote fax device failed to respond to the DCS command.	<ul style="list-style-type: none"> • Adjust Transmit Level/Receive Threshold values. • Remote device could be malfunctioning.
808	T1 timeout occurred when trying to establish a connection with a remote fax device.	Adjust Transmit Level/Receive Threshold values.
809	T2 Timeout occurred due to loss of command/response synchronization.	Adjust Transmit Level/Receive Threshold values.
80A	T5 Timeout occurred when transmitting image data to remote fax device.	<ul style="list-style-type: none"> • Check line quality. • Adjust 'Transmit Level'. • Select a lower 'Max Speed' value under Fax Send settings.

Error code	Description	Action
80B	Too many errors when transmitting in ECM mode.	<ul style="list-style-type: none"> • Check line quality. • Adjust 'Transmit Level'. • Select a lower 'Max Speed' value under Fax Send settings.
80C	Remote device failed to respond to the CTC command.	<ul style="list-style-type: none"> • Select a lower 'Max Speed' value under Fax Send settings. • Adjust 'Transmit Level'.
80D	Received too many requests from remote end to repeat the previous command sent.	<ul style="list-style-type: none"> • Check line quality. • Adjust 'Transmit Level'. • Check if line conditions on remote end will facilitate a good connection.
80E	Functional limitation-Remote fax device does not support G3 receive capability.	No action needed. Issue with the remote device.
811	Failed to detect a fax device at the remote end.	<ul style="list-style-type: none"> • Verify MFD is answering to fax call and not a voice call. • Decrease value of 'Rings To Answer' setting.
812	No more data rates available in V34 modulation scheme.	Adjust to a lower modulation scheme.
813	Timeout occurred after waiting too long to receive a good frame.	Adjust "Receive Threshold".
814	Tried too many times at selected speed using V34 modulation scheme.	<ul style="list-style-type: none"> • Adjust 'Transmit Level'. • Adjust to a lower modulation scheme.
815	Fax transmission was interrupted due to power failure.	Troubleshoot MFP if error persists. See "Modem/fax card service check" on page 122.
818	Fax transmission failed due to insufficient memory to store scanned image.	Adjust 'Memory Use' setting to allocate more memory for send jobs.
819	Fax transmission failed due to insufficient memory to store received image.	Adjust 'Memory Use' setting to allocate more memory for receive jobs.
81A	A timeout occurred during transmission of a page in ECM mode.	Select a lower 'Max Speed' value under Fax Send settings.
880	Failure to transmit training successfully in V17, V29, V27 terminal modulation schemes.	<ul style="list-style-type: none"> • Select a lower "Max Speed" under Fax Send settings. • Adjust the "Transmit Level". • Check line quality.
881	Failure to transmit training successfully in V33, V29, V27 terminal modulation schemes.	<ul style="list-style-type: none"> • Select a lower "Max Speed" under Fax Send settings. • Adjust the "Transmit Level". • Check line quality.

Error code	Description	Action
882	Failure to transmit training successfully in V17, V29 terminal modulation schemes.	<ul style="list-style-type: none"> • Select a lower “Max Speed” under Fax Send settings. • Adjust the “Transmit Level”. • Check line quality.
883	Failure to transmit training successfully in V17, V27 terminal modulation schemes.	<ul style="list-style-type: none"> • Select a lower “Max Speed” under Fax Send settings. • Adjust the “Transmit Level”. • Check line quality.
884	Failure to transmit training successfully in V29, V27 terminal modulation schemes.	<ul style="list-style-type: none"> • Select a lower “Max Speed” under Fax Send settings. • Adjust the “Transmit Level”. • Check line quality.
885	Failure to transmit training successfully in V17 terminal modulation scheme.	<ul style="list-style-type: none"> • Select a lower “Max Speed” under Fax Send settings. • Adjust the “Transmit Level”. • Check line quality.
886	Failure to transmit training successfully in V29 terminal modulation scheme.	<ul style="list-style-type: none"> • Select a lower “Max Speed” under Fax Send settings. • Adjust the “Transmit Level”. • Check line quality.
887	Failure to transmit training successfully in V27 terminal modulation scheme.	<ul style="list-style-type: none"> • Select a lower “Max Speed” under Fax Send settings. • Adjust the “Transmit Level”. • Check line quality.
888	Failure to transmit training successfully at 2400 bps in V27 terminal modulation scheme.	<ul style="list-style-type: none"> • Adjust “Transmit Level”. • Check line quality.
889	Failed to connect at the minimum speed supported by the MFP.	<ul style="list-style-type: none"> • Adjust “Transmit Level”. • Incompatible connection.
88A	Failed to connect using V.34 modulation scheme.	<ul style="list-style-type: none"> • Check line quality. • Adjust to a lower modulation scheme. • Adjust Transmit Level Receive Threshold values.
901	No fax tones detected from remote end.	<ul style="list-style-type: none"> • Verify destination phone number. • Verify that the remote fax is authorized to receive faxes.
902	No dial tone detected.	<ul style="list-style-type: none"> • Check by enabling ‘Behind a PABX’ setting. • Check phone line. • Check MFD modem hardware.

Error code	Description	Action
903	Busy tone detected.	Check with remote end if successive attempts fail.
904	Hardware error detected.	See “Modem/fax card service check” on page 122.
905	A timeout occurred after dialing the number and waiting for a response.	Check with remote end if successive attempts fail.
906	Fax cancelled by user.	No action needed.
907	Modem detected a digital line connection.	Verify the MFP is connected to an analog line. See “Fax transmission service check” on page 125.
908	Phone line was disconnected	Restore phone line connection.
A00	Received request for unsupported function from remote fax device.	No action needed.
A01	Received request for unsupported image width from remote fax device.	No action needed.
A02	Received request for unsupported image resolution from remote fax device.	No action needed.
A03	Received request for unsupported compression type from remote fax device.	No action needed.
A04	Received request for unsupported image length from remote fax device.	No action needed.
F00	Unknown error occurred.	No action needed.

Modem/fax card service check

Action	Yes	No
<p>Step 1</p> <p>Check if the telephone cable is properly connected to the modem card and electrical outlet.</p> <p>Is the cable properly connected to the modem card and electrical outlet?</p>	Go to step 2.	Go to step 3.
<p>Step 2</p> <p>Connect the telephone cable to the modem card and electrical outlet.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>Check if the telephone cable can make and receive calls.</p> <p>Is the phone line properly working?</p>	Go to step 5.	Go to step 4.

Action	Yes	No
<p>Step 4 Connect the printer to a properly functioning telephone jack.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5 Make sure that the modem cable is properly connected to the modem card and to the JFAX2 connector on the controller board.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6 Replace the fax card.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7 Check the voltages values of the following pins on the JFAX1 connector on the controller board:</p> <ul style="list-style-type: none"> • Pin 5: +5 V dc • Pin 7: Ground • Pin 9: Ground • Pin 11: Ground • Pin 13: Ground <p>Are the voltage values approximately the same?</p>	Contact the next level of support.	Go to step 8.
<p>Step 8 Replace the controller board. See “Controller board removal” on page 169.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Cannot set up etherFAX

Action	Yes	No
<p>Step 1 Check the printer connectivity.</p> <p>a Print the Network Setup Page. From the home screen, touch Settings > Reports > Network > Network Setup Page.</p> <p>b Check the network status.</p> <p>Is the printer connected to the network?</p>	Go to step 3.	Go to step 2.

Action	Yes	No
<p>Step 2</p> <p>Make sure that the printer is connected to a network and that the network is connected to the Internet.</p> <p>Can you set up etherFAX?</p>	The problem is solved.	Go to step 3.
<p>Step 3</p> <p>Make sure that etherFAX is set up correctly. For more information, see the printer <i>User's Guide</i>.</p> <p>Can you set up etherFAX?</p>	The problem is solved.	Go to https://www.etherfax.net/lexmark .

Cannot send or receive faxes using etherFAX

Action	Yes	No
<p>Step 1</p> <p>Make sure that the printer is connected to a network and that the network is connected to the Internet.</p> <p>Can you send or receive faxes using etherFAX?</p>	The problem is solved.	Go to step 2.
<p>Step 2</p> <p>a From the home screen, touch Settings > Fax > Fax Setup > General Fax Settings.</p> <p>b Make sure that you have the correct fax number.</p> <p>c Make sure that Fax Transport is set to etherFAX.</p> <p>Can you send or receive faxes using etherFAX?</p>	The problem is solved.	Go to step 3.
<p>Step 3</p> <p>Split large documents into smaller file sizes.</p> <p>Can you send or receive faxes using etherFAX?</p>	The problem is solved.	Go to https://www.etherfax.net/lexmark .

Fax transmission service check

Note: These instructions apply only to printers that support analog fax. For more information, see [“Supported fax” on page 25](#).

Actions	Yes	No
<p>Step 1 Reseat the telephone cable on the LINE port of the printer and on the wall jack.</p> <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.
<p>Step 2 Check for a dial tone.</p> <p>Is there a dial tone?</p>	Go to step 3.	Go to step 5.
<p>Step 3 Check if the telephone line can send and receives calls.</p> <p>Is the phone line properly working?</p>	Go to step 6.	Go to step 4.
<p>Step 4 Check if the telephone line is free of static or external noise.</p> <p>Is the line free of static or external noise?</p>	Go to step 6.	Go to step 5.
<p>Step 5 Connect the telephone cable to a working wall jack.</p> <p>Does the problem remain?</p>	Go to step 6.	The problem is solved.
<p>Step 6</p> <p>a From the home screen, navigate to Settings > Fax > Analog Fax Setup > Fax Receive Settings > Admin Controls > Enable Fax Receive.</p> <p>b Select On.</p> <p>Does the problem remain?</p>	Go to step 7.	The problem is solved.
<p>Step 7</p> <p>a From the home screen, navigate to Settings > Fax > Analog Fax Setup > Fax Receive Settings > Admin Controls > Answer on.</p> <p>b Select a ring pattern.</p> <p>Does the problem remain?</p>	Go to step 8.	The problem is solved.
<p>Step 8 Check if the telephone line is analog.</p> <p>Is the line analog?</p>	Go to step 11.	Go to step 9.

Actions	Yes	No
<p>Step 9 Check if the telephone line is a VOIP line.</p> <p>Is the line VOIP?</p>	Go to step 11.	Go to step 10.
<p>Step 10 Ask the system administrator to check if the VOIP server is configured to receive faxes.</p> <p>Is the server configured to receive faxes?</p>	Go to step 11.	Contact the next level of support.
<p>Step 11 Check if the printer receives a fax from one specific remote device.</p> <p>Does the printer receive a fax from one specific remote device?</p>	Go to step 13.	Go to step 12.
<p>Step 12 Check if a different device can send a fax.</p> <p>Can the device send a fax?</p>	Contact the next level of support.	Go to step 13.
<p>Step 13</p> <p>a From the home screen, navigate to Settings > Fax > Analog Fax Setup > Fax Receive Settings > Admin Controls > Block No Name Fax.</p> <p>b Select Off.</p> <p>Does the problem remain?</p>	Go to step 14.	The problem is solved.
<p>Step 14</p> <p>a From the home screen, navigate to Settings > Fax > Analog Fax Setup > Fax Receive Settings > Admin Controls > Banned Fax List.</p> <p>b Check if the remote device number is on the list.</p> <p>Is the number on the list?</p>	Go to step 15.	Go to step 16.
<p>Step 15 Remove the remote device number from the list.</p> <p>Does the problem remain?</p>	Go to step 16.	The problem is solved.
<p>Step 16</p> <p>a Enter the Service Engineer menu, and then navigate to: Fax SE > Modem Settings > Receive Thresh</p> <p>b Adjust the setting in steps of 2 dB.</p> <p>Note: The recommended adjustment range is between -33 dB and -48 dB.</p> <p>Does the problem remain?</p>	Go to step 17.	The problem is solved.

Actions	Yes	No
<p>Step 17</p> <p>a Enter the Service Engineer menu, and then navigate to: Fax SE > Fax Settings > AutoPrint T30 Logs</p> <p>b Check the reported error code. See “Fax error log codes” on page 118.</p> <p>c Perform the action suggested for the error.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Fax reception service check

Note: These instructions apply only to printers that support analog fax. For more information, see [“Supported fax” on page 25](#).

Note: Before performing this service check, make sure that the correct country code is selected.

Actions	Yes	No
<p>Step 1</p> <p>Reseat the telephone cable on the LINE port of the printer and on the wall jack.</p> <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.
<p>Step 2</p> <p>Check if the telephone line can send and receive calls.</p> <p>Is the phone line properly working?</p>	Go to step 4.	Go to step 3.
<p>Step 3</p> <p>Connect the telephone cable to a working wall jack.</p> <p>Does the problem remain?</p>	Go to step 4.	The problem is solved.
<p>Step 4</p> <p>Check if the telephone line is analog.</p> <p>Is the telephone line analog?</p>	Go to step 7.	Go to step 5.
<p>Step 5</p> <p>Check if the telephone line is a VOIP line.</p> <p>Is the line VOIP?</p>	Go to step 6.	Go to step 7.
<p>Step 6</p> <p>Ask the system administrator to verify if the VOIP server is configured to receive faxes.</p> <p>Is the server configured to receive faxes?</p>	Go to step 7.	Contact the next level of support.

Actions	Yes	No
<p>Step 7 Check if the printer is on a PABX.</p> <p>Is the printer on a PABX?</p>	Go to step 9.	Go to step 8.
<p>Step 8</p> <p>a From the home screen, navigate to Settings > Fax > Analog Fax Setup > Fax Send Settings > Behind a PABX.</p> <p>b Select Yes.</p> <p>Does the problem remain?</p>	Go to step 9.	The problem is solved.
<p>Step 9</p> <p>a From the home screen, navigate to Settings > Fax > Analog Fax Setup > Fax Send Settings > Behind a PABX.</p> <p>b Select No.</p> <p>c Check if access to an outside line needs a dial prefix.</p> <p>Does access to an outside line need a dial prefix?</p>	Go to step 10.	Go to step 11.
<p>Step 10</p> <p>Send a fax using a dial prefix.</p> <p>Does the problem remain?</p>	Go to step 11.	The problem is solved.
<p>Step 11</p> <p>Check if the printer sends a fax to one specific destination.</p> <p>Does the printer send a fax to one specific destination?</p>	Go to step 13.	Go to step 12.
<p>Step 12</p> <p>Check if the device that does not receive a fax can send a fax.</p> <p>Can the device send a fax?</p>	Go to step 13.	Contact the next level of support.
<p>Step 13</p> <p>a Enter the Service Engineer menu, and then navigate to: Fax SE > Fax Settings > AutoPrint T30 Logs</p> <p>b Check the reported error code. See “Fax error log codes” on page 118.</p> <p>c Perform the action suggested for the error.</p> <p>Does the problem remain?</p>	Go to step 14.	The problem is solved.

Actions	Yes	No																																																												
<p>Step 14</p> <p>Check the TIA/EIA-IS-968 Standard "Technical Requirements for Connection of Terminal Equipment to the Telephone Network" for your geography.</p> <p>Is it permitted for analog modulated transmitted data to transmit above -9 dBm?</p>	Go to step 15.	Contact the next level of support.																																																												
<p>Step 15</p> <p>a Open a web browser and then type https://<IP address>/se.</p> <p>b Navigate to: Fax > Settings > Silabs Configuration</p> <p>c Adjust the Transmit Level setting (A) in steps of ± 1 dB.</p> <div data-bbox="311 716 870 1465" style="border: 1px solid black; padding: 10px; margin: 10px 0;"> <p style="text-align: center;">Silabs Configuration</p> <p>Modem Card Configuration</p> <p>1-port <input type="button" value="Submit"/></p> <p>Note: Select the card configuration of the Silabs modem attached to the MFP. You need to restart the MFP for these changes to take effect.</p> <p>Configuration Overrides</p> <table border="1" data-bbox="339 1056 842 1400"> <thead> <tr> <th>Config</th> <th>Apply Override?</th> <th>Value</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td>Transmit Level</td> <td>No ▾</td> <td>-10</td> <td>Min=-15 Max=-7 Def=-10</td> </tr> <tr> <td>Receive Level Gain</td> <td>No ▾</td> <td>0</td> <td>Min=0 Max=7 Def=0</td> </tr> <tr> <td>V.34 Pre-Emphasis Filter</td> <td>No ▾</td> <td>Disable ▾</td> <td>Def=Disable</td> </tr> <tr> <td>V.34 Aggressiveness</td> <td>No ▾</td> <td>Auto ▾</td> <td>Def=Auto</td> </tr> <tr> <td>Ring Impedance</td> <td>No ▾</td> <td>Disable ▾</td> <td>Def=Disable</td> </tr> <tr> <td>Ring Threshold</td> <td>No ▾</td> <td>Disable ▾</td> <td>Def=Disable</td> </tr> <tr> <td>Minimum Loop Current</td> <td>No ▾</td> <td>10</td> <td>Min=10 Max=16 Def=10</td> </tr> <tr> <td>Current Limiting</td> <td>No ▾</td> <td>Disable ▾</td> <td>Def=Disable</td> </tr> <tr> <td>Over Current Detection</td> <td>No ▾</td> <td>Enable ▾</td> <td>Def=Enable</td> </tr> <tr> <td>Off-Hook Settle Time</td> <td>No ▾</td> <td>100</td> <td>Min=20 Max=500 Def=100</td> </tr> <tr> <td>DTMF Power Level</td> <td>No ▾</td> <td>Default ▾</td> <td>Def=Default</td> </tr> <tr> <td>Noise Sensitivity</td> <td>No ▾</td> <td>Default ▾</td> <td>Def=Default</td> </tr> <tr> <td>Silence Detect Interval</td> <td>No ▾</td> <td>50</td> <td>Min=0 Max=100 Def=50</td> </tr> <tr> <td>Impedance</td> <td>No ▾</td> <td>600 Ohm ▾</td> <td>Def=Default</td> </tr> </tbody> </table> <p><input type="button" value="Save"/> <input type="button" value="Save & Configure"/></p> </div> <p>Does the problem remain?</p>	Config	Apply Override?	Value	Comment	Transmit Level	No ▾	-10	Min=-15 Max=-7 Def=-10	Receive Level Gain	No ▾	0	Min=0 Max=7 Def=0	V.34 Pre-Emphasis Filter	No ▾	Disable ▾	Def=Disable	V.34 Aggressiveness	No ▾	Auto ▾	Def=Auto	Ring Impedance	No ▾	Disable ▾	Def=Disable	Ring Threshold	No ▾	Disable ▾	Def=Disable	Minimum Loop Current	No ▾	10	Min=10 Max=16 Def=10	Current Limiting	No ▾	Disable ▾	Def=Disable	Over Current Detection	No ▾	Enable ▾	Def=Enable	Off-Hook Settle Time	No ▾	100	Min=20 Max=500 Def=100	DTMF Power Level	No ▾	Default ▾	Def=Default	Noise Sensitivity	No ▾	Default ▾	Def=Default	Silence Detect Interval	No ▾	50	Min=0 Max=100 Def=50	Impedance	No ▾	600 Ohm ▾	Def=Default	Contact the next level of support.	The problem is solved.
Config	Apply Override?	Value	Comment																																																											
Transmit Level	No ▾	-10	Min=-15 Max=-7 Def=-10																																																											
Receive Level Gain	No ▾	0	Min=0 Max=7 Def=0																																																											
V.34 Pre-Emphasis Filter	No ▾	Disable ▾	Def=Disable																																																											
V.34 Aggressiveness	No ▾	Auto ▾	Def=Auto																																																											
Ring Impedance	No ▾	Disable ▾	Def=Disable																																																											
Ring Threshold	No ▾	Disable ▾	Def=Disable																																																											
Minimum Loop Current	No ▾	10	Min=10 Max=16 Def=10																																																											
Current Limiting	No ▾	Disable ▾	Def=Disable																																																											
Over Current Detection	No ▾	Enable ▾	Def=Enable																																																											
Off-Hook Settle Time	No ▾	100	Min=20 Max=500 Def=100																																																											
DTMF Power Level	No ▾	Default ▾	Def=Default																																																											
Noise Sensitivity	No ▾	Default ▾	Def=Default																																																											
Silence Detect Interval	No ▾	50	Min=0 Max=100 Def=50																																																											
Impedance	No ▾	600 Ohm ▾	Def=Default																																																											

Lost connection to HTTPS fax server when using etherFAX service check

Action	Yes	No
<p>Step 1</p> <p>a Enter the Service Engineer (SE) menu, and then navigate to: Fax SE Menu > Fax Settings</p> <p>b Make sure that the Fax Transport option is set to etherFAX.</p> <p>Does the problem remain?</p>	Go to step 2.	The problem is solved.
<p>Step 2</p> <p>a Make sure that the printer is connected to a stable network.</p> <p>b Perform a POR.</p> <p>Does the problem remain?</p>	Go to step 3.	The problem is solved.
<p>Step 3</p> <p>Check if the printer controller board was previously replaced.</p> <p>Was the printer controller board previously replaced?</p>	Go to step 4.	Go to step 5.
<p>Step 4</p> <p>a Go to your etherFAX portal account, and then remove the printer from the etherFAX registry.</p> <p>b Perform a POR.</p> <p>Does the problem remain?</p>	Go to step 5.	The problem is solved.
<p>Step 5</p> <p>Make sure that the printer serial number is properly added in your etherFAX portal account.</p> <p>Does the problem remain?</p>	Contact the next level of support.	The problem is solved.

Service menus

Understanding the printer control panel

Using the control panel



	Control panel part	Function
1	Display	<ul style="list-style-type: none"> View printer messages and supply status. Set up and operate the printer.
2	Power button	Turn on or turn off the printer. Note: To turn off the printer, press and hold the power button for five seconds.
3	Home button	Go to the home screen.
4	Back button	Return to the previous screen.
5	Start button	Start a job, depending on which mode is selected.
6	Indicator light	Check the status of the printer.

Understanding the status of the indicator light


Indicator light	Printer status
Off	The printer is off or in Hibernate mode.
Blue	The printer is ready or processing data.
Blinking red	The printer requires user intervention.
Solid amber	The printer is in Sleep mode.

Diagnostics menu

Entering the Diagnostics Menu

The Diagnostics Menu contains tests that are used to help isolate printer issues.

- To access the menu from POST, do the following:
 - 1** Unplug the power cord from the electrical outlet.
 - 2** Open tray 1.
 - 3** Connect the power cord to the electrical outlet.
When the display shows the following icon, close tray 1.



- 4** From the menu that appears on the display, select **Diagnostics_Mode**, and then select **Boot**.
- To access the Diagnostics Menu from the home screen, on the control panel, press the following buttons in this sequence: **Back, Back, Start, Start**

Reports

Device Settings

This report lists all the current printer settings.

Enter the Diagnostics menu, and then navigate to:

Reports > Device > Device Settings

For non-touch-screen printer models, press **OK** to navigate through the settings.

Installed Licenses

This setting lists all the installed licenses and their feature data.

Enter the Diagnostics menu, and then navigate to:

Reports > Licenses > Installed Licenses

For non-touch-screen printer models, press **OK** to navigate through the settings.

Advanced Print Quality Samples

This setting prints the Print Quality Test Pages.

Enter the Diagnostics menu, and then select **Advanced Print Quality Samples**.

Format Fax Storage

This setting allows formatting of non-volatile fax storage.

Enter the Diagnostics menu, and then navigate to:

Format Fax Storage > Format Fax Storage

Event Log

Display Log

This setting shows a history of printer events.

Enter the Diagnostics menu, and then navigate to:

Event Log > Display Log

For non-touch-screen printer models, press **OK** to navigate through the settings.

Print Log

This setting shows additional information about the printer events.

Enter the Diagnostics menu, and then navigate to:

Event Log > Print Log

For non-touch-screen printer models, press **OK** to navigate through the settings.

Note: The events that appear in the report vary depending on the operational history of the printer.

Print Log Summary

This setting lists a brief summary of the various printer events.

Enter the Diagnostics menu, and then navigate to:

Event Log > Print Log Summary

For non-touch-screen printer models, press **OK** to navigate through the settings.

Note: The events that appear in the report vary depending on the operational history of the printer.

Mark Log

This setting allows you to create a service, maintenance, or custom log entry. Each log entry is added in the printer event log.

- 1 Enter the Diagnostics menu, and then navigate to:

Event Log > Mark Log

For non-touch-screen printer models, press **OK** to navigate through the settings.

- 2 Select a log that you want to create.

Input tray quick print

This setting lets you print a single or continuous Quick Test page in either duplex or simplex mode.

- 1 Enter the Diagnostics menu, and then select **Input tray quick print**.
- 2 Select a paper source.
- 3 Select whether to print a single or continuous test page.

Output bin quick feed

This setting lets you feed a single or continuous page from the standard bin.

- 1 Enter the Diagnostics menu, and then navigate to:

Output bin quick feed > Standard bin

For non-touch-screen printer models, press **OK** to navigate through the settings.

- 2 Select whether to print a single or continuous test page.

Printer Setup

Printed page count (mono)

This setting displays the amount of pages printed in mono.

- 1 Enter the Diagnostics menu, and then navigate to:

Printer Setup > Printed page count (mono)

- 2 View the printed page count for mono.

Permanent page count

This setting displays the total number of pages printed. After all the print tests are completed, this value resets to zero.

- 1 Enter the Diagnostics menu, and then navigate to:

Printer Setup > Permanent page count

- 2 View the permanent page count.

Enable edge-to-edge (printing)

This setting allows print jobs to include the edges of the page.

- 1 Enter the Diagnostics menu, and then navigate to:
Printer Setup > Enable edge-to-edge (printing)
- 2 Select a setting.

Enable edge-to-edge (copy)

This setting allows copy jobs to include the edges of the page.

- 1 Enter the Diagnostics menu, and then navigate to:
Printer Setup > Enable edge-to-edge (copy)
- 2 Select a setting.

Processor ID

This setting indicates the ID of the processor on the controller board.

- 1 Enter the Diagnostics menu, and then navigate to:
Printer Setup > Processor ID
- 2 View the processor ID.

Serial number

This setting shows the printer serial number.

- 1 Enter the Diagnostics menu, and then navigate to:
Printer Setup > Serial number
For non-touch-screen printer models, press **OK** to navigate through the settings.
- 2 View the serial number.

Model name

This setting shows the model name of the printer.

- 1 Enter the Diagnostics menu, and then navigate to:
Printer Setup > Model name
For non-touch-screen printer models, press **OK** to navigate through the settings.
- 2 View the model name.

Engine setting [x]

Warning—Potential Damage: Do not change this setting without specific instructions from the next level of support.

This setting allows you to select a printer engine setting. Possible values are 0–255. 0 is the default.

For non-touch-screen printer models, press **OK** to navigate through the settings.

- 1 Enter the Diagnostics menu, and then navigate to:
Printer Setup > Engine setting [x]
- 2 Select a setting, and then enter a value.

EP setup

Warning—Potential Damage: Do not change this setting without specific instructions from the next level of support.

This setting allows you to adjust the EP setup of the printer.

For non-touch-screen printer models, press **OK** to navigate through the settings.

- 1 Enter the Diagnostics menu, and then navigate to:
Printer Setup > EP setup
- 2 Select a setting.

Printer diagnostics & adjustments

Sensor tests

- 1 Enter the Diagnostics menu, and then select **Printer diagnostics & adjustments**.

A list of sensor tests appears.

- 2 Find, and then manually toggle the sensor.

Notes:

- The sensor status on the screen toggles between **1** and **0** when the sensor is properly working.
- If a sensor test fails, the test failure may not indicate a failed sensor. Further troubleshooting may be required. Check the boards and cables for possible issues.
- For the fuser exit sensor actuator, toggle it toward the rear door.

List of sensor tests

MPF media present
Tray1 present
Input
Output bin/Narrow media
Fuser exit
Front door interlock

Motor tests

1 Enter the Diagnostics menu, and then navigate to:

Printer diagnostics & adjustments > Motor tests

For non-touch-screen printer models, press **OK** to navigate through the settings.

2 Select a motor.

Notes:

- If the motor is activated, then it is properly working.
- Some motors require automatic deactivation to avoid secondary issues such as possible damage and contamination.
- Some tests require a special action to activate a motor such as removing a major component.
- If the motor fails, the test failure may not indicate a failed motor. Further troubleshooting may be required. Check the boards and cables for possible issues.
- To stop a running motor in non-touch-screen printer models, press **OK**.

List of motor tests

Main Motor
MPF Pick Solenoid
Media Pick Clutch
Fan (main)

Registration adjust

This setting lets you adjust the skew and margins or print a Quick Test page.

For non-touch-screen printer models, press **OK** to navigate through the settings.

1 Enter the Diagnostics menu, and then navigate to:

Printer diagnostics and adjustments > Registration adjust

2 Select a setting to adjust.

Margin Offset

This setting allows you to adjust the margin offset and to print or reset the default settings.

For non-touch-screen printer models, press **OK** to navigate through the settings.

1 Enter the Diagnostics menu, and then navigate to:

Printer diagnostics & adjustments > Margin Offset

2 Select a setting.

Universal Override

This setting allows the user to load custom paper sizes into a paper source.

For non-touch-screen printer models, press **OK** to navigate through the settings.

- 1 Enter the Diagnostics menu, and then navigate to:
Printer diagnostics and adjustments > Universal Override
- 2 Select a setting to adjust.

Scanner Diagnostics

Motor Tests

- 1 Enter the Diagnostics menu, and then navigate to:
Scanner Diagnostics > Motor Tests
- For non-touch-screen printer models, press **OK** to navigate through the settings.
- 2 Select a motor.

Notes:

- If the motor is activated, then it is properly working.
- Some motors require automatic deactivation to avoid secondary issues such as possible damage and contamination.
- Some tests require a special action to activate a motor such as removing a major component.
- If the motor fails, the test failure may not indicate a failed motor. Further troubleshooting may be required. Check the boards and cables for possible issues.

List of motor tests

Scanner
ADF transport

Sensor Test

This test verifies the status of the scanner sensors.

- 1 Enter the Diagnostics menu, and then navigate to:
Scanner diagnostics > Sensor test
- A list of sensor tests appears.
- 2 Find, and then manually toggle the sensor.

Notes:

- The sensor status on the screen toggles between **1** and **0** when the sensor is properly working.
- If a sensor test fails, the test failure may not indicate a failed sensor. Further troubleshooting may be required. Check the boards and cables for possible issues.

List of sensor tests

ADF paper present
ADF scan

Feed Test

This test allows for a continuous feed from the ADF or flatbed.

- 1 Enter the Diagnostics menu, and then navigate to:

Scanner Diagnostics > Feed Test

Note: Set the paper size to match the paper loaded in the ADF tray if necessary.

- 2 Touch **Feed Test**.

Scanner Calibration Reset

Before starting the test, clean the scanner. For more information, see [“Cleaning the scanner” on page 209](#).

- 1 Enter the Diagnostics menu, and then select **Scanner Diagnostics**.

- 2 Touch **Scanner Calibration Reset**.

To verify the result, do the following:

Note: The following procedure only applies to models with ADF.

- 1 Load the ADF with a document containing light and dark content.
- 2 Print a two-sided copy of the document.

Notes:

- If the back side of the copy has vertical streaks, then clean the scanner glass and scanner glass pad, and then print another copy.
- If the streaks still appear, then repeat the cleaning and verification procedure or replace the scanner cover.

Controller Calibration

This test must be done when the scanner controller or flatbed scanner is changed.

- 1 Enter the Diagnostics menu, and then navigate to:

Scanner Diagnostics > Controller Calibration

- 2 Touch **Start**.

Config Menu

Entering the Config Menu

The Config menu consists of menus, settings, and operations that are used to configure the printer.

To access the Config menu, press and hold **Right arrow** and **OK** on the control panel, and then turn on the printer.

Config Menu

Menu item	Description
USB Configuration USB PnP 1* 2	Change the USB driver mode of the printer to improve its compatibility with a personal computer.
USB Configuration USB Scan to Local On* Off	Set whether the USB device driver enumerates as a USB Simple device (single interface) or as a USB Composite device (multiple interfaces).
USB Configuration USB Speed Full Auto*	Set the USB port to run at full speed and disable its high-speed capabilities.
Tray Configuration Tray Linking Automatic* Off	Set the printer to link the trays that have the same paper type and paper size settings.
Tray Configuration Show Tray Insert Message Off Only for unknown sizes* Always	Display a message to select paper size and type after inserting the tray.
Tray Configuration A5 Loading Short Edge Long Edge*	Specify the page orientation when loading A5 paper size.
Tray Configuration Paper Prompts Auto* MP Feeder Manual Paper	Set the paper source that the user fills when a prompt to load paper appears.
Tray Configuration Envelope Prompts Auto* MP Feeder Manual Envelope	Set the paper source that the user fills when a prompt to load envelope appears.
Tray Configuration Action for Prompts Prompt user* Continue Use current	Set the printer to resolve paper- or envelope-related change prompts.

Note: An asterisk (*) next to a value indicates the factory default setting.

Menu item	Description
Reports Menu Settings Page Event Log Event Log Summary	Print reports about printer menu settings, status, and event logs.
Supply Usage And Counters Clear Supply Usage History Reset Black Cartridge Counter Reset Black Imaging Unit Counter Reset Maintenance Counter	Reset the supply page counter or view the total printed pages.
Printer Emulations PS Emulation Off On*	Set the printer to recognize and use the PS data stream.
Printer Emulations Emulator Security Page Timeout 0–60 (60*)	Set the page timeout during emulation.
Printer Emulations Emulator Security Reset Emulator After Job (Off*)	Reset the emulator after a print job.
Printer Emulations Emulator Security Disable Printer Message Access (On*)	Disable access to the printer message during emulation.
Fax Configuration Fax Low Power Support Disable Sleep Permit Sleep Auto*	Set fax to enter Sleep mode whenever the printer determines that it must. Note: This menu item is available only in some printer models.
Print Configuration Font Sharpening 0–150 (24*)	Set a text point-size value below which the high-frequency screens are used when printing font data.
Print Configuration Print Density Disabled 1–5 (3*) Copy Density Disabled 1–5 (3*)	Adjust the toner density when printing or copying documents.
Note: An asterisk (*) next to a value indicates the factory default setting.	

Menu item	Description
Device Operations Quiet Mode On Off*	Set the printer to reduce the amount of noise that it makes when printing. Note: Enabling this setting slows down the overall performance of the printer.
Device Operations Panel Menus Enable* Disable	Set the printer to show the control panel menus. Note: This menu item appears only in the Embedded Web Server.
Device Operations Safe Mode Off* On	Set the printer to operate in a special mode, in which it attempts to continue offering as much functionality as possible, despite known issues. For example, when set to On, and the duplex motor is nonfunctional, the printer performs one-sided printing of the documents even if the job is two-sided printing. Note: This setting cannot be used when the tray is not fully inserted or the tray sensor is damaged.
Device Operations Clear Custom Status	Erase all custom messages.
Device Operations Clear all remotely-installed messages	Erase all remotely-installed messages.
Device Operations Automatically Display Error Screens On* Off	Show existing error messages on the display after the printer remains inactive on the home screen for a length of time equal to the Screen Timeout setting.
Scanner Configuration Scanner Manual Registration Print Quick Test	Print a Quick Test target page. Note: Make sure that the margin spacing on the target page is uniform all the way around the target. If it is not, then the printer margins must be reset.
Scanner Configuration Scanner Manual Registration Front ADF Registration Flatbed Registration	Manually register the flatbed and ADF after replacing the ADF, scanner glass, or controller board.
Scanner Configuration Edge Erase Flatbed Edge Erase (3*) ADF Edge Erase (3*)	Set the size, in millimeters, of the no-print area around an ADF or flatbed scan job.
Scanner Configuration Disable Scanner Enabled* Disabled ADF Disabled	Disable the scanner if it is not working properly.
Note: An asterisk (*) next to a value indicates the factory default setting.	

Menu item	Description
Scanner Configuration Tiff Byte Order CPU Endianness* Little Endian Big Endian	Set the byte order of a TIFF-formatted scan output.
Scanner Configuration Exact Tiff Rows Per Strip On* Off	Set the RowsPerStrip tag value of a TIFF-formatted scan output.
Note: An asterisk (*) next to a value indicates the factory default setting.	

Service Engineer (SE) menu

Entering the SE Menu

To access the menu from the home screen, on the control panel, press the following buttons in this sequence:

Back, Back, Home, Home

General SE Menu

- Capture Logs to USB Drive

Note: This setting allows you to save a log file to a USB drive.

- Code Versions
- Debug Level

Network SE Menu

Enter the SE menu, and then select **Network SE Menu**.

Note: Use these settings as directed by the next level of support.

Top-level menu	Intermediate menu
HISTORY	<ul style="list-style-type: none"> • Print History • Mark History
MAC	<ul style="list-style-type: none"> • Set Card Speed • LAA • Keep Alive
NPAP	Print Alerts

Top-level menu	Intermediate menu
TCP/IP	<ul style="list-style-type: none"> • DHCP Request Options • netstat • arp • Allow SNMP Set • MTU • Meditech Mode • RAW LPR Mode • Garp Interval
Wireless Settings	<ul style="list-style-type: none"> • Wireless Performance Enhancement • Unset Wireless Region
Ping Test	<ul style="list-style-type: none"> • Ping Address • Attempts • Packet Size • Ping
Other Actions	<ul style="list-style-type: none"> • ifconfig • IPtables [Firewall Dump] • IP6tables [Firewall Dump] • IPsec Dump
Enable DHCPD Debugging	N/A
Enable wpa-supPLICANT Debugging	N/A
Enable Ethernet Gigabit	N/A

Scanner SE Menu

Enter this setting to view the calibration data.

Fax SE Menu

Use this menu to help resolve fax transmission and reception issues.

Enter the SE menu, and then touch **Fax SE Menu**.

Note: Use these settings as directed by the next level of support.

Note: For printers with firmware version FW7.1 and up, adjust the Transmit Level setting via EWS SE. See [“EWS SE Menu” on page 145](#)

Top-level menu	Intermediate menu
Agency Test Menu	<ul style="list-style-type: none"> • Go Off Hook • Ring Detect • Generate Tones • Modulations

Top-level menu	Intermediate menu
Fax Settings	<ul style="list-style-type: none"> • Fax Modulations • FOIP Settings • Miscellaneous Settings • Reset Fax Settings
Modem Settings	<ul style="list-style-type: none"> • Caller ID Pattern Note: Changing the value of this setting also changes the value of the Caller ID setting in the Fax Settings. • Pulse Dial Type • Disable Sending CRP
Fax logs	<ul style="list-style-type: none"> • Print all T30 Logs • Print CallerID Log • Print Call Log • Print Fax Settings • Print Job Log • Print All T30 Log Errors • Print All Auto Captured Logs On • Print T38 Trace Log • Clear T38 Trace Log
Reboot System	N/A

EWS SE Menu

Enter this setting to help resolve customer communication related printing issues.

To access the Silabs configuration:


- 1 Open a web browser and then type **https://<IP address>/se** .
- 2 Navigate to:
Fax > Settings > Silabs Configuration

Entering invalid engine mode

This mode allows the printer to load the correct firmware code.

- 1 Unplug the power cord from the electrical outlet.
- 2 Open tray 1.
- 3 Connect the power cord to the electrical outlet.

When the display shows the following icon, close tray 1.



- 4 From the menu that appears on the display, select →, and then select **ENGINE_FLASH**.

Entering Recovery mode

This mode allows the printer to boot from a secondary set of instructions and flash firmware code. While in this mode, you can only flash firmware code through a USB cable directly connected to a PC.


Depending on your printer model, do any of the following:

For LED display

- 1 Turn off the printer.
- 2 Open the front door.
- 3 Press and hold the **Stop** button.
- 4 Turn on the printer.
- 5 When all the icons flash, release the button.


For 2-line display

- 1 Turn off the printer.
- 2 Press and hold the **OK** and **Back** buttons.
- 3 Turn on the printer.
- 4 When the display shows the following icon, release the buttons.



For 2.4-, 4.3-, 7-, and 10-inch displays with number pads

- 1 Turn off the printer.
- 2 Press and hold the **2**, **7**, and **8** buttons.
- 3 Turn on the printer.
- 4 When the display shows the following icon, release the buttons.



For 2.8-, 4.3-, 7-, and 10-inch displays without number pads

- 1 Turn off the printer.
- 2 Open tray 1.
Note: Make sure that paper is loaded in the tray.
- 3 Turn on the printer.
- 4 When an ellipses appears on the upper-left corner of the display, close tray 1.
Note: If tray 1 is not closed, then the printer boots normally.

Parts removal

Important removal information

Removal precautions

-  **CAUTION—SHOCK HAZARD:** The low-voltage power supply (LVPS) and the high-voltage power supply (HVPS) may have residual voltage present. To avoid the risk of electrical shock, do not touch their circuit components or the solder side of the board. Only handle them by their outer edges or metal housing.
-  **CAUTION—SHOCK HAZARD:** This product uses an electronic power switch. It does not physically disconnect the input AC voltage. To avoid the risk of electrical shock, always remove the power cord from the printer when removal of the input AC voltage is required.
-  **CAUTION—SHOCK HAZARD:** To avoid the risk of electrical shock and to prevent damage to the printer, remove the power cord from the electrical outlet and disconnect all connections to any external devices before you connect or disconnect any cable, electronic board, or assembly.
-  **CAUTION—HOT SURFACE:** The inside of the printer might be hot. To reduce the risk of injury from a hot component, allow the surface to cool before touching it.
-  **CAUTION—PINCH HAZARD:** To avoid the risk of a pinch injury, use caution in areas marked with this label. Pinch injuries may occur around moving parts, such as gears, doors, trays, and covers.

Précautions de retrait

-  **ATTENTION—RISQUE D'ELECTROCUTION :** Une tension résiduelle peut être présente dans le bloc d'alimentation basse tension (LVPS) et le bloc d'alimentation haute tension (HVPS). Pour éviter tout risque d'électrocution, ne touchez pas les composants du circuit ou le côté soudure de la carte. Tenez-les uniquement par leurs extrémités ou le boîtier en métal.
-  **ATTENTION—RISQUE D'ELECTROCUTION :** Ce produit utilise un commutateur d'alimentation électronique. Il ne déconnecte pas physiquement la tension d'alimentation CA. Pour éviter tout risque d'électrocution, débranchez toujours le cordon d'alimentation de l'imprimante lorsque vous devez déconnecter la tension d'alimentation CA.
-  **ATTENTION—RISQUE D'ELECTROCUTION :** Pour éviter tout risque d'électrocution et éviter d'endommager l'imprimante, débranchez le cordon d'alimentation de la prise électrique et déconnectez toute connexion à tout périphérique externe avant de brancher ou débrancher des câbles ou circuits et assemblages électroniques.
-  **ATTENTION—SURFACE CHAUDE :** L'intérieur de l'imprimante risque d'être brûlant. pour réduire le risque de brûlure, laissez la surface ou le composant refroidir avant d'y toucher.
-  **ATTENTION : RISQUE DE PINCEMENT :** Pour éviter tout risque de blessure par pincement, agissez avec précaution au niveau des zones signalées par cette étiquette. Les blessures par pincement peuvent se produire autour des pièces mobiles telles que les engrenages, portes, tiroirs et capots.

Precauciones durante la extracción

-  **PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS:** La fuente de alimentación de bajo voltaje (LVPS) y la fuente de alimentación de alto voltaje (HVPS) pueden presentar voltaje residual. Para evitar el riesgo de descarga eléctrica, no toque los componentes del circuito ni el lateral soldado de la placa. Manipule solo los bordes exteriores o la carcasa metálica.
-  **PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS:** Este producto utiliza un interruptor de corriente electrónico. No desconecta físicamente la entrada de voltaje de CA. Para evitar el riesgo de descarga eléctrica, desenchufe siempre el cable de alimentación de la impresora cuando sea necesario retirar la entrada de voltaje de CA.
-  **PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS:** Para evitar el riesgo de descargas eléctricas y daños en la impresora, retire el cable de alimentación de la toma eléctrica y desconecte todas las conexiones a dispositivos externos antes de conectar o desconectar cualquier cable, placa electrónica o conjunto.
-  **PRECAUCIÓN: SUPERFICIE CALIENTE:** El interior de la impresora podría estar caliente. Para evitar el riesgo de heridas producidas por el contacto con un componente caliente, deje que la superficie se enfríe antes de tocarlo.
-  **PRECAUCIÓN: PELIGRO DE ATRAPAMIENTO:** Para evitar el riesgo de lesión por atrapamiento, preste atención en las áreas marcadas con esta etiqueta. Las lesiones por atrapamiento se pueden producir en torno a partes móviles, tales como engranajes, puertas, bandejas y cubiertas.

Vorsichtsmaßnahmen bei der Demontage

-  **VORSICHT – STROMSCHLAGGEFAHR:** Im Niederspannungsnetzteil (LVPS) und Hochspannungsnetzteil (HVPS) liegt unter Umständen Restspannung vor. Um das Risiko eines elektrischen Schlags zu vermeiden, berühren Sie keine umliegenden Bauteile oder die Lötseite der Platine. Fassen Sie sie nur an den Außenkanten oder am Metallgehäuse an.
-  **VORSICHT – STROMSCHLAGGEFAHR:** Dieses Produkt verwendet einen elektronischen Leistungsschalter. Er trennt die Eingangswchselspannung nicht physikalisch. Um das Risiko eines elektrischen Schlags zu vermeiden, ziehen Sie stets das Netzkabel vom Drucker ab, wenn eine Abtrennung der Eingangswchselspannung erforderlich ist.
-  **VORSICHT – STROMSCHLAGGEFAHR:** Um das Risiko eines elektrischen Schlags und Schäden am Drucker zu vermeiden, ziehen Sie das Netzkabel aus der Steckdose und trennen Sie alle Verbindungen zu jeglichen externen Geräten, bevor Sie Kabel, Elektronikplatinen oder Baugruppen einstecken oder abziehen.
-  **VORSICHT – HEISSE OBERFLÄCHE:** Das Innere des Druckers kann sehr heiß sein. Vermeiden Sie Verletzungen, indem Sie heiße Komponenten stets abkühlen lassen, bevor Sie ihre Oberfläche berühren.
-  **VORSICHT – QUETSCHGEFAHR:** Um das Risiko einer Quetschung zu vermeiden, gehen Sie in Bereichen, die mit diesem Etikett gekennzeichnet sind, mit Vorsicht vor. Quetschungen können im Bereich von beweglichen Komponenten auftreten, wie z. B. Zahnrädern, Klappen, Fächern und Abdeckungen.

Handling ESD-sensitive parts

Many electronic products use parts that are known to be sensitive to electrostatic discharge (ESD). To prevent damage to ESD-sensitive parts, do the following:

- Turn off the printer before removing logic boards.
- Keep the parts in their original packing material until you are ready to install them into the printer.
- Make the least possible movements with your body to prevent an increase of static electricity from clothing fibers, carpets, and furniture.
- Put the ESD wrist strap on your wrist. Connect the wrist band to the system ground point. This action discharges any static electricity in your body to the printer.
- Hold the parts by their edge connector shroud. Do not touch its pins. If you are removing a pluggable module, then use the correct tool.
- If possible, keep all parts in a grounded metal cabinet.
- Do not place the parts on the printer cover or on a metal table. If you need to put down the parts, then put them into their packing material.
- Prevent parts from being accidentally touched by other personnel. Cover the printer when you are not working on it.
- Be careful while working with the parts when cold-weather heating is used. Low humidity increases static electricity.

Critical information for controller board or control panel replacement

 **CAUTION—POTENTIAL INJURY:** The lithium battery in this product is not intended to be replaced. There is a danger of explosion if a lithium battery is incorrectly replaced. Do not recharge, disassemble, or incinerate a lithium battery. Discard used lithium batteries according to the manufacturer's instructions and local regulations.

 **ATTENTION—RISQUE DE BLESSURE :** La batterie lithium de ce produit n'est pas destinée à être remplacée. Il existe un risque d'explosion si une batterie lithium est placée de façon incorrecte. Ne rechargez pas, ne démontez pas et n'incinerez pas une batterie lithium. Mettez les batteries lithium usagées au rebut selon les instructions du fabricant et les réglementations locales.

 **PRECAUCIÓN: POSIBLES DAÑOS PERSONALES:** La batería de litio de este producto no debe reemplazarse. Existe riesgo de explosión si se sustituye incorrectamente una batería de litio. No recargue, desmonte ni incinere una batería de litio. Deseche las baterías de litio según las instrucciones del fabricante y las normativas locales.

 **VORSICHT – MÖGLICHE VERLETZUNGSGEFAHR** Die Lithiumbatterie in diesem Produkt darf nicht ausgetauscht werden. Wird eine Lithiumbatterie nicht ordnungsgemäß ausgetauscht, besteht Explosionsgefahr. Lithiumbatterien dürfen auf keinen Fall wieder aufgeladen, auseinander genommen oder verbrannt werden. Befolgen Sie zum Entsorgen verbrauchter Lithiumbatterien die Anweisungen des Herstellers und die örtlichen Bestimmungen.

Warning—Potential Damage: Observe all precautions when handling ESD sensitive parts. See [“Handling ESD-sensitive parts” on page 151](#).

Warning—Potential Damage: Carefully remove cables and connectors. Make sure they are not damaged.

Warning—Potential Damage: To avoid damaging the part or experiencing NVRAM mismatch issues, replace only one of the following components at a time:

- Control panel
- Controller board

To replace a component and to test whether the problem is resolved:

1 Replace the affected component.

Warning—Potential Damage: Do not perform a Power-On Reset (POR) until the problem is resolved. If a POR is performed at this point, then the replacement part can no longer be used in another printer and must be returned to the manufacturer.

2 Enter the Diagnostics menu. The menu allows you to temporarily use the replacement part.

Warning—Potential Damage: Some printers perform a POR automatically if the Diagnostics menu is not opened within five seconds. If a POR is performed at this point, then the replacement part can no longer be used in another printer and must be returned to the manufacturer.

3 Use the Diagnostics menu to test the replacement part. Do a feed test to check if the problem is resolved.

- If the problem is not resolved—Turn off the printer, and then install the old part.
- If the problem is resolved—Perform a POR.
- If NVRAM error occurs during the replacement, then see [“NVRAM mismatch failure service check” on page 115](#).

Restoring the printer configuration

Restore the printer to its correct configuration to complete the replacement service. Use the Service Restore Tool to download the software bundle, and then flash the printer settings and embedded solutions.

Note: If you do not have access to Service Restore Tool, then contact your next level of support.

Note: The software bundle contains the latest version of the firmware, applications, and software licenses from the Lexmark CFM and Package Builder. The printer firmware may be at a different level from what is used before replacement of the part.

Using the Service Restore Tool

1 Go to <https://cdp.lexmark.com/service-restore-tool/> to access the tool.

2 Log in using your Lexmark or partner login.


If your login fails, then contact your next level of support.

- 3 Enter the printer serial number, and then submit the information.

Note: Make sure that the serial number that appears on the verification screen is correct.

- 4 Save the zip file.


Note: Make sure that the serial number in the zip file matches the serial number of the printer being restored.



5 Extract the contents of the zip file, open the *Readme* file, and then follow the instructions in the file.

Notes:

- Perform the install instructions on the *Readme* file in the exact order shown. Restart the printer only if the file says so.
- For more information on how to flash the downloaded files, see [“Updating the printer firmware” on page 154](#).



```

README.txt - Notepad
File Edit Format View Help
How to unpack the restore package:
* The restore package provided is a compressed archive and must be
extracted using an archive manager.
  once extracted, the following is provided at the root of the
extracted directory:
  * This restore document
  * All applicable firmware files
  * All solutions and their licenses
  * Settings bundle(s) that do not contain sensitive settings

Install the files from the zip in the order shown below:
* Install FDN.PIR.E309.fls
* Install LW20.PRL.P235.fls
* Install LW1.PRL.P124_NON.fls
* Install 82M0235-004.zip
* Reboot the printer

The following device settings were not included due to availability
limitations
(Please contact your next level of support for more information):
* 82M1256-001 (Error Code: 101)
  
```

6 If the printer had eSF apps previously installed, then confirm from the customer if all the eSF apps have been installed after performing the installation instructions in the *Readme* file.

Notes:

- If you are unable to access the administrative menus to verify that the printer is restored, then ask the customer for access rights.
- If a 10.00 error appears after you restart the printer, then contact the next level of support.

Updating the printer firmware

Warning—Potential Damage: Before updating the printer firmware, ask the next level of support for the correct code. Using an incorrect code level may damage the printer.

Using a flash drive

Note: The printer must be in ready state to update the firmware.

This option is available only in printer models with front USB port.

- 1 Insert the flash drive into the USB port.
- 2 Depending on the printer model, do any of the following:
 - From the control panel, navigate to **USB Menu: Print from USB > Accept** or **OK**, and then select the file that you need to flash.
 - Select the firmware file.

Note: Do not turn off the printer while the update is going on.

Using a network computer

Using the File Transfer Protocol (FTP)

Note: The printer must be in ready state to update the firmware.

- 1 Turn on the printer.
- 2 Obtain the IP address from the home screen.
- 3 From the command prompt of a network computer, open an FTP session to the printer IP address.
- 4 Use a PUT command to place the firmware file on the printer.
The printer performs a POR sequence and terminates the FTP session.

Using the Embedded Web Server

Note: The printer must be in ready state to update the firmware.

- 1 Open a web browser, and then type the printer IP address.
- 2 Click **Settings > Device > Update Firmware**.
- 3 Select the file to use.
The printer performs a POR sequence and terminates the EWS session.

Using a USB cable connection

Note: Make sure that the cable is connected to the rear USB port.

Using USB Flash Utility

- 1 Go to support.lexmark.com, and then download USB Flash Utility.
- 2 Extract, and then run the utility.
- 3 Click **Browse Files**, and then browse to the firmware file directory.
- 4 Select the firmware file.
- 5 Select the source printer.
- 6 Click **Start**.

Using USButil

- 1 Go to support.lexmark.com, and then download USButil.
- 2 Extract, and then drag and drop the firmware file onto the USButil icon.
- 3 A command prompt window appears briefly.

Note: Make sure to disconnect other USB devices when using USButil.


Ribbon cable connectors

Low insertion force (LIF) connector

Warning—Potential Damage: When installing a cable into an LIF connector, avoid bending the edges of the cables and damaging the contacts on the cables.

Inserting the cable

- 1 Make sure that the contacts of the controller board and connectors are on the same side.



- 2 Insert the cable.

Note: Make sure that the cable is installed straight into the connector to avoid intermittent failures.



Adjustments

Adjusting the fax volume

- 1 Enter the SE menu on the EWS page by navigating to the following address: *http://<printer's IP address>/se*.
- 2 From the menu options, click **Fax**.
- 3 Under Settings, click **Conexant Configuration**.
- 4 Change the volume level based on the following values:
 - Low = 0
 - Medium = 1
 - High = 1
- 5 Click **Save**.

Removal procedures

Keep the following tips in mind as you replace parts:

- Some removal procedures require removing cable ties. You must replace cable ties during reassembly to avoid pinching wires, obstructing the paper path, or restricting mechanical movement.
- Remove the toner cartridges, imaging unit, and trays before removing other printer parts. The imaging kit must be carefully set on a clean, smooth, and flat surface. It must also be protected from light while out of the printer.
- Disconnect all external cables from the printer to prevent possible damage during service.
- Unless otherwise stated, install the parts in reverse order of removal.
- When installing a part held with several screws, start all screws before the final tightening.
- For printers that have an electronic power switch, make sure to unplug the power cord after powering off.


Left side removals

Left cover removal

- 1 Remove the screw at the front, and then remove the screw at the rear of the cover.



- 2 Open the front door, and then release the left front door link.



- 3 Place the printer on its right side.

- 4 Release the three latches (A) at the bottom of the cover, and then remove the cover.




Main drive gears removal

Note: For a video demonstration, see [Main drive gears removal](#).

- 1 Remove the left cover. See [“Left cover removal” on page 158](#).
- 2 Place the printer on its right side.


Warning—Potential Damage: If the printer is not placed on its right side, then the gears fall out of place when the gear plates are removed.

- 3 Remove the 12 screws, remove the gear covers, and then remove the gears.




Installation notes:

- Pay attention to the position of the gears.
- Most gears have a molded letter for identification.




- Note the letter or number on the gears, and then use the following illustration to match their proper location and position in the printer.

- Some locations have multiple gears stacked on top of each other.




4 Remove the left front door link. See [“Left front door link removal” on page 165](#).

5 Remove the two screws (A), and then remove the coupling (B).




- 6 Place the printer on its left side, remove the screw (C), and then remove the duplex swing arm assembly (D).



Installation notes:

- a Make sure that the gears assembly is properly installed in the housing.




- b** Align the tab on the housing to the notch in the frame, and then install the duplex swing arm assembly.




Imaging unit coupling removal

- 1 Remove the left cover. See [“Left cover removal” on page 158.](#)
- 2 Remove the left front door link. See [“Left front door link removal” on page 165.](#)
- 3 Remove the two screws (A), and then remove the imaging unit coupling (B).




Pick roller clutch removal

- 1 Remove the left cover. See [“Left cover removal” on page 158.](#)
- 2 Remove the six screws, and then remove the gear cover.




- 3 Remove the three gears.




Installation note: Pay attention to the position of the gears.

- 4 Remove the clutch (A), and then disconnect the cable (B).



Left front door link removal


- 1 Remove the left cover. See [“Left cover removal” on page 158](#).
- 2 Remove the six screws, and then remove the gear cover.



- 3 Remove the gear.



- 4 Release the left front door link (A) from the retainer (B), and then remove the left front door link.



Right side removals


Right cover removal

- 1 Remove the screw at the front, and then remove the screw at the rear of the cover.



- 2 Open the front door, and then place the printer on its left side.

3 Release the three latches at the bottom (A).



4 Release the latch at the front, and then remove the cover.



Parts removal

Controller board removal


Note: For a video demonstration, see [Controller board removal](#).

Note: When replacing the controller board for the MX431adn, MX431adw, MB3442adw, and XM1342 models, make sure that it is compatible with the ADF scanner. Not all ADF scanners are compatible with the controller board. Check the following before installation:


- Printer serial number
- ADF scanner connector
- Printer controller board connector slot

Use the following table to differentiate between the ADF scanners, and then identify their compatible printer controller boards.


Printer S/N	Flatbed scanner and ADF variant	Compatible printer controller board
<p>Serial number for older printers: The eighth character is 0.</p>	<p>Part number: 41X2598 Number of pins on the ADF CIS FFC: 14</p>  <p>Notes:</p> <ul style="list-style-type: none"> • If 41X2598 is no longer available, then perform one of the following: <ul style="list-style-type: none"> – For printer model MX431adn, replace both the ADF scanner and the printer controller board with the newer ADF scanner (41X2980) and the newer controller board (41X2976). – For printer models MB3442adw, MX431adw, and XM1342, replace both the ADF scanner and the printer controller board with the newer ADF scanner (41X2980) and the newer controller board (41X2977). • Make sure to upgrade the firmware to FW 074.038 version or later. 	<p>Part numbers:</p> <ul style="list-style-type: none"> • 41X2660 (MX431adn) • 41X2661 (MB3442adw, MX431adw, XM1342) <p>JDCIS1 connector: 14-pin slot</p>  <p>Notes:</p> <ul style="list-style-type: none"> • If 41X2660 is no longer available, then replace both the ADF scanner and the printer controller board with the newer ADF scanner (41X2980) and the newer controller board (41X2976). • If 41X2661 is no longer available, then replace both the ADF scanner and the printer controller board with the newer ADF scanner (41X2980) and the newer controller board (41X2977). • Make sure to upgrade the firmware to FW 074.038 version or later.

Printer S/N	Flatbed scanner and ADF variant	Compatible printer controller board
<p>Serial number for newer printers: The eighth character is equal to or greater than 1.</p>	<p>Part number: 41X2980 Number of pins on the ADF CIS FFC: 30</p> 	<p>Part numbers:</p> <ul style="list-style-type: none"> • 41X2976 (MX431adn) • 41X2977 (MB3442adw, MX431adw, XM1342) <p>JDCIS2 connector: 30-pin slot</p> 
<p>Note: Do not downgrade the firmware to versions earlier than FW 074.038.</p>		

- 1 Remove the right cover. See [“Right cover removal” on page 167](#).
- 2 Disconnect all the cables from the controller board.




- 3 Remove the five screws, and then remove the controller board.



LVPS removal

Note: For a video demonstration, see [LVPS removal](#).

- 1 Remove the right cover. See [“Right cover removal” on page 167](#).
- 2 Disconnect the two cables (A), remove the six screws (B), and then remove the LVPS.






-  **CAUTION—SHOCK HAZARD:** To avoid the risk of electrical shock, do not remove the shield from the back of the LVPS.
-  **ATTENTION—RISQUE D'ELECTROCUTION :** Pour éviter tout risque d'électrocution, ne retirez pas la protection de l'arrière du bloc d'alimentation basse tension (LVPS).
-  **PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS:** Para evitar el riesgo de descarga eléctrica, no retire la protección de la parte trasera de la fuente de alimentación de bajo voltaje (LVPS).
-  **VORSICHT – STROMSCHLAGGEFAHR:** Um die Gefahr eines elektrischen Schlags zu vermeiden, entfernen Sie die Abdeckung nicht von der Rückseite des Niederspannungsnetzteils.

HVPS removal

Note: For a video demonstration, see [HVPS removal](#).

- 1 Remove the left cover. See [“Left cover removal” on page 158](#).
- 2 Remove the right cover. See [“Right cover removal” on page 167](#).
- 3 Remove the rear door. See [“Rear door removal” on page 185](#).
- 4 Place the printer on its left side.


5 Remove the three screws (A), release the HVPS, and then disconnect the cable (B).




Sensor (MPF paper present) removal

Note: For a video demonstration, see [Sensor \(MPF paper present\) removal](#).

- 1 Remove the right cover. See [“Right cover removal”](#) on page 167.
- 2 Open the front door, and then remove the screw.




- 3 Release the latches securing the sensor, and then disconnect the sensor cable.



Right front door link removal

- 1 Remove the right cover. See [“Right cover removal” on page 167.](#)
- 2 Remove the screw, and then remove the link from the front door.




MPF solenoid cable removal

Note: For a video demonstration, see [MPF solenoid cable removal.](#)

- 1 Remove the left cover. See [“Left cover removal” on page 158.](#)
- 2 Remove the right cover. See [“Right cover removal” on page 167.](#)
- 3 Remove the ADF and scanner. See [“ADF and scanner removal” on page 193.](#)

- 4 Disconnect the cable, and then remove the screw to remove the solenoid cable.




Main fan removal

Note: For a video demonstration, see [Main fan removal](#).


- 1 Remove the left cover. See [“Left cover removal” on page 158](#).
- 2 Remove the right cover. See [“Right cover removal” on page 167](#).
- 3 Remove the ADF and scanner. See [“ADF and scanner removal” on page 193](#).

4 Disconnect the cable, and then remove the screw to remove the fan.




Speaker removal

- 1 Remove the right cover. See [“Right cover removal” on page 167](#).
- 2 Disconnect the cable (A), remove the screw (B), and then remove the speaker.



Interlock switch removal

- 1 Remove the right cover. See [“Right cover removal” on page 167](#).
- 2 Remove the screw (A), and then disconnect the connector (B).




- 3 Remove the switch.

Front removals

Control panel removal

- 1 Remove the right cover. See [“Right cover removal” on page 167.](#)
- 2 Disconnect the two cables.



- 3 Remove the ADF and scanner. See [“ADF and scanner removal” on page 193.](#)
- 4 Remove the control panel cables from the top right frame of the printer.
- 5 Remove the screw, and then remove the control panel.



Upper front cover removal

Note: For a video demonstration, see [Upper front cover removal](#).

- 1 Open the front door.
- 2 Release the two latches.



- 3 Remove the cover.




Front door removal

Note: For a video demonstration, see [Front door removal](#).

- 1 Remove the right cover. See [“Right cover removal” on page 167](#).
- 2 Remove the right front door link. See [“Right front door link removal” on page 174](#).


- 3 Release the left front door link, and then remove the front door.



Transfer roller removal

Note: For a video demonstration, see [Transfer roller removal](#).

- 1 Open the front door.
- 2 Release the two latches, and then remove the transfer roller.




Installation notes:

- Do not touch the foam on the roller.
- The shaft has grease. To avoid contaminating the roller, do not touch the shaft.
- Make sure that the spring is properly installed on the left side of the roller.


MPF pick roller removal

- 1 Open the front door.
- 2 Remove the MPF pick roller.




Pick separator roller removal

- 1 Remove the tray insert.
- 2 Remove the pick separator roller.




Sensor (input) removal


- 1 Open the front door.
- 2 Remove the imaging unit.
- 3 Remove the two screws (A), and then remove the roller assembly (B).



4 Release the two latches (C), and then remove the paper guide (D).




5 Remove the screw (E), and then disconnect the cable (F) from the sensor.



Important information before installing the duplex shaft bushing

The duplex shaft bushing (41X4471) comes with grease applied to a small area (A).




The grease may spread and contaminate other areas of the bushing. If this happens, the grease may transfer when paper is being picked from the tray.

To avoid the problem, wipe clean the areas in orange with a soft cloth before installing the bushing in the printer.

Rear removals

Rear door removal

- 1 Remove the left cover. See [“Left cover removal” on page 158.](#)
- 2 Remove the screw, and then remove the rear door.




Note: Pay attention to the position of the locating feature on the right side before removing the door.



Fuser removal

Note: For a video demonstration, see [Fuser removal](#).

- 1 Remove the right cover. See [“Right cover removal” on page 167](#).
- 2 Disconnect the three cables.



- 3 Open the rear door, remove the four screws, and then remove the fuser.




Top removals

Printhead removal


Note: For a video demonstration, see [Printhead removal](#).

- 1 Remove the right cover. See [“Right cover removal” on page 167](#).
- 2 Remove the left cover. See [“Left cover removal” on page 158](#).
- 3 Remove the ADF and scanner. See [“ADF and scanner removal” on page 193](#).


4 Disconnect the two cables.



5 Remove the three screws (A), remove the two cables (B) from the toroid (C), and then remove the printhead.



Installation note: When installing the printhead, tighten the screws in the following the order:




Redrive removal

Note: For a video demonstration, see [Redrive removal](#).

- 1 Remove the right cover. See [“Right cover removal” on page 167](#).
- 2 Remove the left cover. See [“Left cover removal” on page 158](#).
- 3 Remove the ADF and scanner. See [“ADF and scanner removal” on page 193](#).
- 4 Remove the four screws.




- 5 Lift the redrive, and then disconnect the cable from the redrive.



Bin full sensor actuator removal


- 1 Remove the ADF and scanner. See [“ADF and scanner removal” on page 193](#).
- 2 Firmly pull the bin full actuator to the left until it is disengaged from the printer frame.




- 3 Remove the actuator.

Installation notes:

- a Make sure that the actuator is properly positioned as shown.



- b** Carefully rotate the actuator upward until it is engaged to the printer frame.





- c** Make sure that the actuator is properly installed and freely rotates without binding.


Bottom removals

Duplex guide removal

- 1 Place the printer on its left side.
- 2 Remove the duplex guide.



Installation note: Make sure that the duplex guide is properly inserted into the locating features inside the printer.



ADF and scanner removals

ADF cover removal

- 1 Open the ADF cover.
- 2 Remove the ADF cover.



ADF tray removal

- 1 Open the ADF cover.
- 2 Remove the ADF tray.



ADF separator pad removal

- 1 Open the ADF cover.
- 2 Release the latch to remove the ADF separator pad.



Installation note: Do not lose the spring under the ADF separator pad.


ADF and scanner removal


Note: For a video demonstration, see [ADF and scanner removal](#).

Note: When replacing the ADF scanner for the MX431adn, MX431adw, MB3442adw, and XM1342 models, make sure that it is compatible with the controller board. Not all ADF scanners are compatible with the controller board. Check the following before installation:


- Printer serial number
- ADF scanner connector
- Printer controller board connector slot

Use the following table to differentiate between the ADF scanners, and then identify their compatible printer controller boards.

Printer S/N	Flatbed scanner and ADF variant	Compatible printer controller board
<p>Serial number for older printers: The eighth character is 0.</p>	<p>Part number: 41X2598 Number of pins on the ADF CIS FFC: 14</p>  <p>Notes:</p> <ul style="list-style-type: none"> • If 41X2598 is no longer available, then perform one of the following: <ul style="list-style-type: none"> – For printer model MX431adn, replace both the ADF scanner and the printer controller board with the newer ADF scanner (41X2980) and the newer controller board (41X2976). – For printer models MB3442adw, MX431adw, and XM1342, replace both the ADF scanner and the printer controller board with the newer ADF scanner (41X2980) and the newer controller board (41X2977). • Make sure to upgrade the firmware to FW 074.038 version or later. 	<p>Part numbers:</p> <ul style="list-style-type: none"> • 41X2660 (MX431adn) • 41X2661 (MB3442adw, MX431adw, XM1342) <p>JDCIS1 connector: 14-pin slot</p>  <p>Notes:</p> <ul style="list-style-type: none"> • If 41X2660 is no longer available, then replace both the ADF scanner and the printer controller board with the newer ADF scanner (41X2980) and the newer controller board (41X2976). • If 41X2661 is no longer available, then replace both the ADF scanner and the printer controller board with the newer ADF scanner (41X2980) and the newer controller board (41X2977). • Make sure to upgrade the firmware to FW 074.038 version or later.



Printer S/N	Flatbed scanner and ADF variant	Compatible printer controller board
Serial number for newer printers: The eighth character is equal to or greater than 1 .	Part number: 41X2980 Number of pins on the ADF CIS FFC: 30 	Part numbers: <ul style="list-style-type: none"> • 41X2976 (MX431adn) • 41X2977 (MB3442adw, MX431adw, XM1342) JDCIS2 connector: 30-pin slot 
Note: Do not downgrade the firmware to versions earlier than FW 074.038.		

- 1 Remove the right cover. See [“Right cover removal” on page 167](#).
- 2 Remove the left cover. See [“Left cover removal” on page 158](#).
- 3 Remove the control panel. See [“Control panel removal” on page 178](#).
- 4 Remove the controller board. See [“Controller board removal” on page 169](#).
- 5 Remove the screw (A) securing the fax card ground wire to the frame, if present.




Installation note: Secure the fax card ground wire to location A on the frame (see above).

6 Remove the three screws from the printer frame.



7 Remove the ADF and scanner.



Installation note: Make sure to perform the ADF scanner calibration after replacing the ADF and scanner.

To perform the ADF scanner calibration:

- 1 Load the calibration sheet into the ADF tray.

Note: Adjust the guides to match the size of the calibration sheet.

- 2 Enter the Diagnostics menu, and then select **Scanner Diagnostics**.

- 3 Touch **Scanner Calibration Reset**.

- 4 Wait for about 45 seconds for the calibration to finish.

Notes:

- A **Test Completed** message appears on the display when the calibration is finished.
- If the host printer firmware is FW.081.016 or older, make sure the fax volume levels are manually adjusted. See [“Adjusting the fax volume” on page 157](#).

Scanner pivot arm removal

- 1 Slightly raise the ADF and scanner assembly.
- 2 While pulling on the scanner pivot arm latch, completely raise the ADF and scanner assembly to release the latch.




- 3 Remove the two screws, and then remove the scanner pivot arm.



Component locations

Printer configuration



1	Automatic document feeder (ADF)
2	ADF tray
3	ADF bin
4	Control panel
5	Standard bin
6	Multipurpose feeder
7	Standard 250-sheet tray
8	Optional 550-sheet tray

Controller board connectors

Connector	Connects to	Pin number	Signal
JSCANSNS1	Sensor (ADF paper present)	1	SNS_ADF_DOC
		2	SNS_ADF_DOC_LED
		3	GND
		4	SNS_ADF_SCAN
		5	PWR_ADF_SCAN_LED
		6	GND

Connector	Connects to	Pin number	Signal
JFBM1	Motor (scanner fatbed)	1	FBM_BOUT1
		2	FBM_BOUT2
		3	FBM_AOUT2
		4	FBM_AOUT1
JADFM1	Motor (ADF scanner)	1	ADFM_BOUT1
		2	ADFM_BOUT2
		3	ADFM_AOUT2
		4	ADFM_AOUT1
JACIS1	Scanner flatbed analog CIS bar	1	OS1_AFE
		2	GND
		3	OS2_AFE
		4	GND
		5	OS3_AFE
		6	GND
		7	+3.3 V_FB_C
		8	AFE_REV_ID1
		9	AFE_REV_ID2
		10	A_SOL
		11	GND
		12	A_CIS_PCLK
		13	+5 V_AWAKE
		14	SCAN_LEDB
		15	SCAN_LEDG
		16	SCAN_LEDR

Connector	Connects to	Pin number	Signal
JDCIS1	Scanner ADF digital CIS bar	1	GND
		2	SCAN_RXIN_P(0)
		3	SCAN_RXIN_N(0)
		4	GND
		5	SCAN_RXCLK_P
		6	SCAN_RXCLK_N
		7	GND
		8	D_SOL
		9	D_AFE_SEN
		10	D_AFE_SDIO
		11	D_AFE_SCK
		12	GND
		13	D_CIS_PCLK
		14	+3.3 V_ADF
JWIFI1	Wi-Fi antenna	1	WIFI_ANT
		2	GND
J3	USB front port cable	1	+5 V_FUSB
		2	USB_N
		3	USB_P
		4	NC
		5	GND

Connector	Connects to	Pin number	Signal
JVDO1	Printhead video	1	VDO_HSYNC-
		2	GND
		3	VDO_K1+
		4	VDO_K1-
		5	GND
		6	VDO_LPOW_K
		7	VDO_LADJ_K1
		8	VDO_BOOST_K
		9	+3.3 V_PHRAIL_SW
		10	GND
		11	VDO_LEN_K-
		12	+3.3 V_PHRAIL_SW
		13	VDO_K0+
		14	VDO_K0-
		15	GND
		16	VDO_LADJ_K0
JMIR1	Motor (printhead mirror)	1	+25 V_SW
		2	GND
		3	MM_START
		4	MM_LOCK
		5	MM_REFCLK

Connector	Connects to	Pin number	Signal
JUICC28	2.8-in. control panel LCD	1	LED_DRIVE
		2	+5 V_CONT
		3	MIR_TXD
		4	MIR_CS-
		5	POWER_BUTTON
		6	LCD_RS
		7	LCD_TE
		8	MIR_RXD
		9	GND
		10	MIR_CLK
		11	GND
		12	I2C_DAT
		13	I2C_CLK
		14	+5 V_UI
		15	RESET-
		16	IRQ-
		17	GND
		18	LCD_WR
		19	LCD_RD
		20	+5 V_UI
		21	D0
		22	D1
		23	GND
		24	D2
		25	D3
		26	+5 V_UI
		27	D4
		28	D5
		29	GND
		30	D6
		31	D7
		32	+5 V_UI
JSPKR1	Speaker	1	Speaker+
		2	Speaker -

Connector	Connects to	Pin number	Signal
JSCHIP1	Toner cartridge and imaging unit smart chip	1	I2C_DAT
		2	+3.3 V_SCHIP
		3	I2C_CLK
		4	GND
		5	TONER_EMPTY
JCVR1	Front door laser safety switch	1	+3.3 V_PHRAIL
		2	+3.3 V
		3	GND
JMPSNS1	Sensor (MPF paper present)	1	SNS_MPS
		2	GND
		3	PWR_MPF
JHVPS1	HVPS	1	+25 V_SW
		2	DEV_PWM
		3	ADC_HV_SERVO
		4	XFER_EN
		5	TX_PWM
		6	GND
		7	CHG_PWM

Connector	Connects to	Pin number	Signal
JMTR1	Motor (main drive)	1	+25 V_SW
		2	GND
		3	BRAKE
		4	PWM
		5	DIR
		6	FG
		7	+25 V_SW
		8	GND
	Sensor (toner density)	9	LED_PWM_TDS
		10	THERM_TDS
		11	SNS_TDS
		12	GND
		13	PWR_TDS
	Pick clutch	14	+25 V_SW
		15	CLUTCH_SINK
	Sensor (input)	16	SNS_INPUT
		17	GND
		18	PWR_INPUT
JTRAY1	Tray present switch	1	PWR_TRAY
		2	TRAY_DETECT
JOPT1	Paper handling option	1	+25 V_SW
		2	TXD_OPT
		3	TRAY_PULLED_N
		4	RXD_OPT
		5	GND
		6	5 V_OPT
JLVPS1	LVPS	1	RELAY_ON
		2	HEAT_ON
		3	ZERO_CROSS
		4	+25 V_SW_ON
		5	+25 V_CONT_RAIL
		6	GND
		7	+25 V_SW_RAIL
		8	GND

Connector	Connects to	Pin number	Signal
JEXIT1	Sensor (fuser exit)	1	SNS_EXIT
		2	GND
		3	PWR_EXIT
JFUSER1	Fuser thermistor	1	THERM_FUSER
		2	GND
		3	AC_RELAY_ON_TCO
		4	AC_RELAY_ON
JFAN1	Fan	1	+25 V_SW
		2	FAN_SINK
JBIN1	Sensor (bin full)	1	SNS_BF
		2	GND
		3	PWR_BF
JSOL1	MPF pick solenoid	1	+25 V_SW
		2	SOL_SINK
JFAX1	Fax Note: This connector is only applicable for the MB3442adw, MX331, MX431, and XM1342 printer models.	1	TONE
		2	FAX_PWR
		3	FAX_PWR
		4	RES
		5	+5V
		6	IRQ
		7	GND
		8	SCK
		9	GND
		10	MOSI
		11	GND
		12	MISO
		13	GND
		14	CS

Maintenance

Cleaning printer parts

Cleaning the printer

-  **CAUTION—SHOCK HAZARD:** To avoid the risk of electrical shock when cleaning the exterior of the printer, unplug the power cord from the electrical outlet and disconnect all cables from the printer before proceeding.
-  **ATTENTION—RISQUE D'ELECTROCUTION :** pour éviter tout risque d'électrocution lors du nettoyage de l'extérieur de l'imprimante, débranchez le cordon d'alimentation électrique de la prise et déconnectez tous les câbles de l'imprimante avant de continuer.
-  **PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS:** Para evitar el riesgo de descarga eléctrica al limpiar el exterior de la impresora, desconecte el cable de alimentación de la toma eléctrica y desconecte todos los cables de la impresora antes de realizar la operación.
-  **VORSICHT – STROMSCHLAGGEFAHR:** Um das Risiko eines elektrischen Schlags beim Reinigen des Druckergehäuses zu vermeiden, ziehen Sie das Netzkabel aus der Steckdose, und ziehen Sie alle Kabel vom Drucker ab, bevor Sie fortfahren.

Notes:

- Perform this task after every few months.
- Damage to the printer caused by improper handling is not covered by the printer warranty.

- 1 Turn off the printer, and then unplug the power cord from the electrical outlet.
- 2 Remove paper from the standard bin and multipurpose feeder.
- 3 Remove any dust, lint, and pieces of paper around the printer using a soft brush or vacuum.
- 4 Wipe the outside of the printer with a damp, soft, lint-free cloth.


Notes:

- Do not use household cleaners or detergents, as they may damage the finish of the printer.
- Make sure that all areas of the printer are dry after cleaning.

- 5 Connect the power cord to the electrical outlet, and then turn on the printer.

Cleaning the scanner

- 1 Open the scanner cover.



2 Using a damp, soft, lint-free cloth, wipe the following areas:

- ADF glass pad

Note: In some printer models, this location has an ADF glass instead of a pad.



- Scanner glass pad



- ADF glass



- Scanner glass



3 Close the scanner cover.

Parts catalog

Legend


The following column headings are used in the parts catalog:

- **Asm-index**—Identifies the item in the illustration.
- **Part number**—Identifies the unique number that correlates with the part.
- **Units/mach**—Refers to the number of units actually used in the base machine or product.
- **Units/FRU**—Refers to the number of units in a particular FRU.
- **Description**—Describes the part.

The following abbreviations are used in the parts catalog:

- **NS** (not shown) in the Asm-index column indicates that the part is procurable but is not pictured in the illustration.
- **PP** (parts packet) in the Description column indicates that the part is contained in a parts packet.


Assembly 1: Covers



Assembly 1: Covers

Asm-index	P/N	Units/mach	Units/FRU	Description	Removal procedure
1	41X2582	1	1	Rear door	“Rear door removal” on page 185
2	41X2580	1	1	Right cover (MX331)	“Right cover removal” on page 167
2	41X4207	1	1	Right cover (MB3442, MX431, XM1342)	“Right cover removal” on page 167
3	41X2584	1	1	Front door with MPF pick roller	“Front door removal” on page 179
4	41X2670	1	4	Upper front cover with decals (MX331, MB3442, MX431)	“Upper front cover removal” on page 179
4	41X2929	1	1	Upper front cover with decals (XM1342)	“Upper front cover removal” on page 179
5	41X2578	1	1	Left front door link	“Left front door link removal” on page 165
6	41X2579	1	1	Left cover	“Left cover removal” on page 158


Assembly 2: Control panel



Assembly 2: Control panel

Asm-index	P/N	Units/mach	Units/FRU	Description	Removal procedure
1	41X2595	1	1	Control panel assembly	“Control panel removal” on page 178

Assembly 3: Electronics




Assembly 3: Electronics

Asm-index	P/N	Units/mach	Units/FRU	Description	Removal procedure
1	41X2573	1	1	Printhead	“Printhead removal” on page 186
2	41X2978	1	1	Speaker	“Speaker removal” on page 177
3	41X2659	1	1	Controller board (MX331adn)	“Controller board removal” on page 169
3	41X2975	1	1	Controller board (MX331adn) Note: Make sure to upgrade the firmware to FW 074.038 version or later.	“Controller board removal” on page 169
3	41X2660	1	1	Controller board (MX431adn) <ul style="list-style-type: none"> • This part is compatible with older printers that have 0 as the eighth character of the printer serial number. • If 41X2660 is no longer available, then replace both the ADF scanner and the printer controller board with the newer ADF scanner (41X2980) and the newer controller board (41X2976). • Make sure to upgrade the firmware to FW 074.038 version or later. 	“Controller board removal” on page 169
3	41X2976	1	1	Controller board (MX431adn) <ul style="list-style-type: none"> • This part is compatible for new printers that have 1 or greater as the eighth character of the printer serial number. • Make sure to upgrade the firmware to FW 074.038 version or later. 	“Controller board removal” on page 169

Asm-index	P/N	Units/mach	Units/FRU	Description	Removal procedure
3	41X2661	1	1	Controller board (MB3442adw, MX431adw, XM1342) <ul style="list-style-type: none"> • This part is compatible with older printers that have 0 as the eighth character of the printer serial number. • If 41X2661 is no longer available, then replace both the ADF scanner and the printer controller board with the newer ADF scanner (41X2980) and the newer controller board (41X2977). • Make sure to upgrade the firmware to FW 074.038 version or later. 	“Controller board removal” on page 169
3	41X2977	1	1	Controller board (MB3442adw, MX431adw, XM1342) <ul style="list-style-type: none"> • This part is compatible for new printers that have 1 or greater as the eighth character of the printer serial number. • If 41X2977 is not available, use 41X4479. • Make sure to upgrade the firmware to FW 074.038 version or later. 	“Controller board removal” on page 169
3	41X4479	1	1	Controller board (MB3442adw, MX431adw, XM1342) <ul style="list-style-type: none"> • This part is compatible for new printers that have 1 or greater as the eighth character of the printer serial number. • Make sure to upgrade the firmware to FW 074.038 version or later. 	“Controller board removal” on page 169
4	41X2590	1	1	LVPS, 75 W and 120 V	“LVPS removal” on page 171
4	41X2591	1	1	LVPS, 75 W and 230 V	“LVPS removal” on page 171
5	41X2592	1	1	HVPS	“HVPS removal” on page 171
6	41X2587	1	1	Transfer roller, bearing, and spring	“Transfer roller removal” on page 180
7	41X2636	1	1	Main fan	“Main fan removal” on page 175

Asm-index	P/N	Units/mach	Units/FRU	Description	Removal procedure
8	41X1083	1	1	Sensor (input)	“Sensor (input) removal” on page 182
9	41X4273	1	3	Toner cartridge contact	--
10	41X4485	1	1	Interlock switch	“Interlock switch removal” on page 177


Assembly 4: Gears



Assembly 4: Gears

Asm-index	P/N	Units/mach	Units/FRU	Description	Removal procedure
1	41X2425	1	1	Pick roller clutch	“Pick roller clutch removal” on page 164
2	41X2576	1	31	Main drive gears kit	“Main drive gears removal” on page 159
3	41X4471	1	1	Duplex shaft bushing	“Important information before installing the duplex shaft bushing” on page 184


Assembly 5: Paper path



Assembly 5: Paper path

Asm-index	P/N	Units/mach	Units/FRU	Description	Removal procedure
1	41X2575	1	1	Pick separator roller Note: This part has a CRU sheet.	“Pick separator roller removal” on page 182
2	41X2585	1	1	250-sheet tray	--
3	41X2599	1	1	Fuser, 100 V	“Fuser removal” on page 186
3	41X2586	1	1	Fuser, 115 V	“Fuser removal” on page 186
3	41X2600	1	1	Fuser, 230 V	“Fuser removal” on page 186
4	41X2712	1	1	Duplex guide	“Duplex guide removal” on page 191
5	41X4195	1	1	Redrive	“Redrive removal” on page 188
6	41X4196	1	1	Bin full sensor actuator	“Bin full sensor actuator removal” on page 189


Assembly 6: 550-sheet optional tray



Assembly 6: 550-sheet optional tray

Asm-index	P/N	Units/mach	Units/FRU	Description	Removal procedure
1	41X2612	1	1	550-sheet tray	--
2	41X2614	1	1	550-sheet tray pick roller	--
3	41X2613	1	1	550-sheet tray insert	--

Assembly 7: ADF and scanner



Assembly 7: ADF and scanner

Asm-index	P/N	Units/mach	Units/FRU	Description	Removal procedure
1	41X2597	1	1	Scanner with fax card (MX331) (simplex ADF)	“ADF and scanner removal” on page 193
1	41X2598	1	1	Scanner with fax card (MB3442, MX431, XM1342) Notes: <ul style="list-style-type: none"> This part is compatible with older printers that have 0 as the eighth character of the printer serial number. If 41X2598 is no longer available, then replace both the ADF scanner and the printer controller board with the newer ADF scanner (41X2980) and the newer controller board (41X2976 or 41X2977). Make sure to upgrade the firmware to FW 074.038 version or later. 	“ADF and scanner removal” on page 193
1	41X2980	1	1	Scanner with fax card (MB3442, MX431, XM1342) Notes: <ul style="list-style-type: none"> This part is compatible with new printers that have 1 or greater as the eighth character of the printer serial number. Make sure to upgrade the firmware to FW 074.038 version or later. 	“ADF and scanner removal” on page 193
2	41X2510	1	1	ADF cover	“ADF cover removal” on page 192
3	41X2511	1	1	ADF separator pad	“ADF separator pad removal” on page 193
4	41X2428	1	1	ADF tray	“ADF tray removal” on page 193
5	41X2596	1	1	Scanner pivot arm	“Scanner pivot arm removal” on page 198

Assembly 8: Miscellaneous

Asm-index	P/N	Units/mach	Units/FRU	Description	Removal procedure
NS	41X1872	1	1	MarkNet N8372 802.11 a/b/g/n/ac wireless print server (MX431, MB3442, XM1342)	N/A
NS	40X0288	1	1	Power cord, Argentina	N/A
NS	40X1767	1	1	Power cord, Europe	N/A
NS	40X1766	1	1	Power cord, Bolivia and Peru	N/A
NS	40X0259	1	1	Power cord, Brazil	N/A
NS	40X0273	1	1	Power cord, Chile and Uruguay	N/A
NS	40X1792	1	1	Power cord, Korea	N/A
NS	40X0303	1	1	Power cord, PRC	N/A
NS	40X1791	1	1	Power cord, Taiwan	N/A
NS	40X0301	1	1	Power cord, Australia and New Zealand	N/A
NS	40X0271	1	1	Power cord, United Kingdom, Asian, Brunei, Cambodia, Indonesia, Laos, Malaysia, Myanmar, Philippines, Singapore, Thailand, Vietnam, Afghanistan, Bangladesh, Bhutan, India, Nepal, Pakistan, Sri Lanka, Tibet, and Hong Kong	N/A
NS	40X7229	1	1	Power cord, India	N/A

Printer specifications

Power consumption

Product power consumption

The following table documents the power consumption characteristics of the product.

Note: Some modes may not apply to your product.

Mode	Description	Power consumption (Watts)
Printing	The product is generating hard-copy output from electronic inputs.	One-sided: 530 (MX331); 580 (MB3442, MX431, XM1342) Two-sided: 315 (MX331); 330 (MB3442, MX431, XM1342)
Copy	The product is generating hard-copy output from hard-copy original documents.	550 (MX331); 600 (MB3442, MX431, XM1342)
Scan	The product is scanning hard-copy documents.	13 (MX331); 14 (MB3442, MX431, XM1342)
Ready	The product is waiting for a print job.	6.5 (MX331); 7 (MX431dn, MX431adn); 7.5 (MB3442, MX431adw, XM1342)
Sleep Mode	The product is in a high-level energy-saving mode.	0.8 (MX331); 0.9 (MX431dn, MX431adn); 1.1 (MB3442, MX431adw, XM1342)
Hibernate	The product is in a low-level energy-saving mode.	0.1
Off	The product is plugged into an electrical outlet, but the power switch is turned off.	0.1

The power consumption levels listed in the previous table represent time-averaged measurements. Instantaneous power draws may be substantially higher than the average.

Values are subject to change. See www.lexmark.com for current values.

Sleep Mode

This product is designed with an energy-saving mode called *Sleep Mode*. The Sleep Mode saves energy by lowering power consumption during extended periods of inactivity. The Sleep Mode is automatically engaged after this product is not used for a specified period of time, called the *Sleep Mode Timeout*.

Factory default Sleep Mode Timeout for this product (in minutes):	15
-------------------------------------------------------------------	----

By using the configuration menus, the Sleep Mode Timeout can be modified between 1 minute and 120 minutes. If the print speed is less than or equal to 30 pages per minute, then you can set the timeout only up to 60 minutes. Setting the Sleep Mode Timeout to a low value reduces energy consumption, but may increase the response time of the product. Setting the Sleep Mode Timeout to a high value maintains a fast response, but uses more energy.

Hibernate Mode

This product is designed with an ultra-low power operating mode called *Hibernate mode*. When operating in Hibernate Mode, all other systems and devices are powered down safely.

The Hibernate mode can be entered in any of the following methods:

- Using the Hibernate Timeout
- Using the Schedule Power modes

Factory default Hibernate Timeout for this product in all countries or regions	3 days
--------------------------------------------------------------------------------	--------

The amount of time the printer waits after a job is printed before it enters Hibernate mode can be modified between one hour and one month.

Off mode

If this product has an off mode which still consumes a small amount of power, then to completely stop product power consumption, disconnect the power supply cord from the electrical outlet.

Total energy usage

It is sometimes helpful to estimate the total product energy usage. Since power consumption claims are provided in power units of Watts, the power consumption should be multiplied by the time the product spends in each mode in order to calculate energy usage. The total product energy usage is the sum of each mode's energy usage.

Applicability of Regulation (EU) 2019/2015 and (EU) 2019/2020

Per Commission Regulation (EU) 2019/2015 and (EU) 2019/2020, the light source contained within this product or its component is intended to be used for Image Capture or Image Projection only, and is not intended for use in other applications.

Selecting a location for the printer

- Leave enough room to open trays, covers, and doors and to install hardware options.
- Set up the printer near an electrical outlet.

 **CAUTION—POTENTIAL INJURY:** To avoid the risk of fire or electrical shock, connect the power cord to an appropriately rated and properly grounded electrical outlet that is near the product and easily accessible.

 **CAUTION—SHOCK HAZARD:** To avoid the risk of electrical shock, do not place or use this product near water or wet locations.

- Make sure that airflow in the room meets the latest revision of the ASHRAE 62 standard or the CEN Technical Committee 156 standard.
- Provide a flat, sturdy, and stable surface.
- Keep the printer:
 - Clean, dry, and free of dust
 - Away from stray staples and paper clips

- Away from the direct airflow of air conditioners, heaters, or ventilators
- Free from direct sunlight and humidity extremes
- Observe the recommended temperatures and avoid fluctuations.

Ambient temperature	10 to 32.2°C (50 to 90°F)
Storage temperature	-40 to 40°C (-40 to 104°F)

- Allow the following recommended amount of space around the printer for proper ventilation:



1	Top	305 mm (12 in.)
2	Rear	100 mm (3.94 in.)
3	Right side	76.2 mm (3 in.)
4	Front	305 mm (12 in.) Note: The minimum space needed in front of the printer is 76 mm (3 in.).
5	Left side	110 mm (4.33 in.)

Noise emission levels

The following measurements were made in accordance with ISO 7779 and reported in conformance with ISO 9296.

Note: Some modes may not apply to your product.

1-meter average sound pressure, dBA	
Printing	One-sided: 53; Two-sided: 50
Ready	14

Values are subject to change. See www.lexmark.com for current values.

Temperature information

Ambient operating temperature	10 to 32.2°C (50 to 90°F)
Shipping temperature	-40 to 40°C (-40 to 104°F)
Storage temperature and relative humidity	-40 to 40°C (-40 to 104°F) 8 to 80% RH


Theory of operation

POR sequence

As the printer is turned on, the engine code goes through a series of tests to verify hardware integrity. If a hardware failure is detected, then it is reported to the printer. If the POR sequence cannot be completed successfully, then the printer may post an error message. The message states that service may be needed.

Print cycle operation


Print engine layout




1	Printhead
2	Toner cartridge
3	Imaging unit
4	Transfer roller
5	Fuser

Print cycle

Flowchart




Charge



1	Charge roller
2	Photoconductor

The charge roller applies a uniform negative electrical charge to the surface of the photoconductor. The insulative properties of the photoconductor allow it to hold a charge and its photoconductive properties allow it to discharge when exposed to light.


Expose



1	Photoconductor
2	Printhead

The printhead emits a laser that exposes the surface of the photoconductor. The laser pulses coincide with the digital latent image. The exposed areas of the photoconductor surface are discharged, resulting in a photoconductor surface potential that is less negative than the non-exposed areas.


Develop



1	Developer roller
2	Toner cartridge
3	Photoconductor

The developer roller applies the toner from the toner cartridge to the photoconductor during the development process. The difference in surface potential creates an electric field that causes the toner particles to move to the photoconductor according to the pattern of the latent image.

Transfer




1	Charge roller
2	Transfer roller
3	Paper

A positive potential relative to the toned image formed on the photoconductor is applied to the transfer roller. This allows the transfer roller to move the developed toner from the surface of the photoconductor to the paper as the paper is passed between the transfer roller and photoconductor.

Clean

The cleaning blade removes the residual toner from the photoconductor after the transfer. After cleaning, the process moves again to the charge process and repeats each cycle until the entire image is transferred to a side of the paper.

Fuse




1	Fuser
2	Paper

After the toner image is transferred to the paper, the toner particles are not yet permanently bonded to the paper. For the final step in the print process, paper is transported to the fuser where heat and pressure are applied to it. As a result, the toner particles melt and are permanently fused to the paper, completing the print process. The print cycle repeats for the succeeding pages.

Printer operation


Printer sections



1	Output bin
2	Printhead
3	Imaging unit
4	Toner cartridge
5	Simplex paper path
6	MPF
7	Standard tray
8	Optional tray
9	Transfer roller
10	Duplex paper path
11	Fuser

Printer paper path

Simplex print job




1	Photoconductor
2	Transport roller
3	MPF pick roller
4	Feed roller
5	Separator roller
6	Pick roller
7	Separator pad
8	Transfer roller
9	Fuser
10	Paper exit roller

The pick roller picks and the feed roller feeds the paper to the separator roller or separator pad. The feed roller feeds the paper to the transport roller. For MPF print jobs, the MPF pick roller picks and feeds the paper to the transport roller.

The transport rollers feed the paper to the transfer roller. At the transfer roller, the photoconductor transfers the developed image to the paper to create the printed image.

As the paper passes the fuser, heat and pressure are applied to permanently bond the toner to the paper. After printing, the paper exit roller ejects the paper to the output bin.


Duplex print job



After the first side is printed, the paper stops at the output bin while still in the paper exit roller. The paper is fed again into the duplex paper path to have the opposite side printed.


The paper travels along the duplex path until it enters again the transport roller. From there, the paper continues its path until the print job is done.

Printer paper path sensors



#	Sensor	Function
1	Sensor (input)	Detects paper that is traveling from the transport roller
2	Sensor (MPF paper present)	Detects paper presence in the MPF
3	Sensor (trailing edge)	Detects the trailing edge of the paper that is fed from the optional tray
4	Sensor (index)	Detects if the pick roller is at the correct height to pick paper from the optional tray
5	Sensor (paper present)	Detects paper presence in the optional tray
6	Sensor (fuser exit)	Detects paper that is exiting the fuser
7	Sensor (narrow media/bin full)	<ul style="list-style-type: none"> • Detects if paper is narrow • Detects if the bin is full

Main drive



1	MPF pick roller
2	Transport roller
3	Motor (main drive)
4	Transfer roller
5	Photoconductor
6	Fuser
7	Paper exit roller
8	Duplex


The motor (main drive) provides mechanical power to the printer.

The motor transfers power through several gears to the following parts:

- MPF pick roller
- Transport roller
- Transfer roller
- Photoconductor

- Fuser
- Paper exit roller
- Duplex

Tray drive



1	Pick roller
2	Separator roller
3	Separator pad
4	Optional tray
5	Standard tray


The motor (main drive) in the printer drives the standard tray. The lift plate in the tray is spring loaded and is not driven by a motor. The spring raises the lift plate until the paper is in contact with the pick roller.

The motor inside the optional tray drives the optional tray. The motor drives the lift plate to a specified height in the tray.

To prepare for feeding, the lift plate raises to push the paper against the pick roller. The lift plate stops pushing at the point where the pick roller is at the proper height for picking. After the pick roller is in position, it feeds the topmost paper. The separator roller and separator pad ensures that only one sheet is fed at a time.

ADF theory

ADF paper path



1	ADF tray
2	ADF pick roller
3	ADF separator pad
4	ADF feed roller
5	ADF scan roller
6	Sensor (ADF scan)
7	Sensor (ADF paper present)
8	ADF exit roller
9	ADF bin

Paper from the ADF tray enters the ADF through the ADF pick roller, ADF feed roller, and ADF separator pad. On the ADF tray, the sensor (ADF paper present) detects if paper is loaded.

After the paper is fed, it travels to the ADF scan roller for scanning. As the paper passes the sensor (ADF scan), the scanner under the ADF obtains the image from the sheet. If equipped, a CIS unit obtains the image from the other side of the sheet in a duplex scan job.

After the paper is scanned, the ADF exit roller ejects the paper to the ADF bin.

Index

A

ADF paper path 248
 adjustments
 fax volume 157
 advanced print quality samples 133

C

cannot send or receive faxes using etherFAX 124
 charge 237
 clean 240
 cleaning
 exterior of the printer 209
 interior of the printer 209
 cleaning the printer 209
 cleaning the scanner 209
 config menu
 accessing 139
 configurations
 printer models 21
 connectors
 controller board 201
 control panel
 critical information 151
 using 131
 controller board
 critical information 151

D

data security notice 33
 develop 239
 diagnostics menu
 accessing 132
 controller calibration 139
 feed test 139
 scanner calibration reset 139
 duplex shaft bushing 184

E

electrostatic-sensitive parts 151
 emission notices 233
 error codes
 121 error messages 91
 126 error messages 93
 140 error messages 94
 162 error messages 95
 200 paper jam messages 62
 202 paper jam messages 69

232 paper jam messages 75
 242 paper jam messages 77
 280 paper jam messages 77
 29 81
 295 paper jam messages 77
 31 81
 32 81
 33 81
 41 83
 42 83
 43 83
 600 error messages 97
 602 error messages 97
 611 error messages 97
 621 error messages 97
 662 error messages 97
 680 error messages 97
 80 87
 84 87
 840 error messages 101
 842 error messages 101
 843 error messages 101
 845 error messages 101
 88 87
 912 error messages 112
 938–992 error messages 115
 ESD-sensitive parts 151
 event log
 display log 133
 mark log 134
 print log 133
 print log summary 133
 expose 238

F

fax error log codes 118
 fax troubleshooting
 cannot send or receive faxes using etherFAX 124
 cannot set up etherFAX 123
 finding the printer serial number 26
 format fax storage 133
 fuse 241

I

indicator light
 understanding the status 131
 invalid code, fixing 145

invalid engine mode
accessing 145

L

low insertion force (LIF) connector 156

M

menu

Config Menu 140
moving the printer 232

N

noise emission levels 233
notices 231, 232, 233, 234

P

paper path, duplex 243
paper path, simplex 243
paper sizes, supported 21
paper types, supported 24
paper weights, supported 24
parts catalog legend 212
parts of the printer 201
print cycle 236
charge 237
clean 240
develop 239
expose 238
flowchart 236
fuse 241
transfer 240
print engine layout 235
print quality troubleshooting
fax reception service check 127
fax transmission service check 125
printer
minimum clearances 232
selecting a location 232
printer configuration 201
printer diagnostics
input tray quick print 134
output bin quick feed 134
printer diagnostics & adjustments
motor tests 137
sensor tests 136
printer diagnostics and adjustments
margin offset 137
registration adjust 137
universal override 137
printer model
configurations 21

printer sections 242
printer setup
enable edge-to-edge (copy) 135
enable edge-to-edge (printing) 135
engine setting [x] 135
EP setup 136
model name 135
permanent page count 134
printed page count (mono) 134
process ID 135
serial number 135
printer status 131

R

recovery mode
accessing 146
removal procedures
tips 157
removals
ADF and scanner 193
ADF cover 192
ADF separator pad 193
ADF tray 193
bin full sensor actuator 189
control panel 178
controller board 169
duplex guide 191
front door 179
fuser 186
HVPS 171
imaging unit coupling 163
interlock switch 177
left cover 158
left front door link 165
LVPS 171
main drive gears 159
main fan 175
MPF pick roller 181
MPF solenoid cable 174
pick roller clutch 164
pick separator roller 182
printhead 186
rear door 185
redrive 188
right cover 167
right front door link 174
scanner pivot arm 198
sensor (input) 182
sensor (MPF paper present) 173
speaker 177
transfer roller 180
upper front cover 179

- reports
 - device settings 132
 - installed licenses 132
- resetting the printer
 - without admin credentials 32
- restoring configuration 152

S

- safe mode 31
- scanner
 - cleaning 209
- scanner diagnostics
 - controller calibration 139
 - feed test 139
 - motor tests 138
 - scanner calibration reset 139
 - sensor tests 138
- security reset jumper
 - using 32
- selecting a location for the printer 232
- sensors, paper path 245
- serial number, printer
 - finding 26
- service checks troubleshooting
 - 111 service error messages 89
 - 900 service error messages 108
- service engineer (SE) menu
 - accessing 143
 - EWS SE menu 145
 - fax SE menu 144
 - general SE 143
 - network SE menu 143
 - scanner SE menu 144
- supported fax 25
- supported paper sizes 21
- supported paper types 24
- supported paper weights 24
- symptoms
 - fax 118
 - printer 116

T

- theory
 - duplex paper path 243
 - main drive 246
 - paper path sensors 245
 - simplex paper path 243
 - tray drive 247
- theory of operation
 - POR sequence 235
- tools, required 27

- transfer 240
- troubleshooting
 - initial check 31
- troubleshooting, fax
 - cannot send or receive faxes using etherFAX 124
 - cannot set up etherFAX 123
- troubleshooting, print quality
 - fax reception service check 127
 - fax transmission service check 125
- troubleshooting, service checks
 - 111 service error messages 89
 - 900 service error messages 108

U

- updating the printer firmware
 - using a flash drive 154
 - using a network computer 154
 - using a USB cable connection 154
- using the control panel 131

Part number index

P/N	Part name	Page
40X0259	Power cord, Brazil.....	229
40X0271	Power cord, United Kingdom, Asian, Brunei, Cambodia, Indonesia, Laos, Malaysia, Myanmar, Philippines, Singapore, Thailand, Vietnam, Afghanistan, Bangladesh, Bhutan, India, Nepal, Pakistan, Sri Lanka, Tibet, and Hong Kong.....	229
40X0273	Power cord, Chile and Uruguay.....	229
40X0288	Power cord, Argentina.....	229
40X0301	Power cord, Australia and New Zealand.....	229
40X0303	Power cord, PRC.....	229
40X1766	Power cord, Bolivia and Peru.....	229
40X1767	Power cord, Europe.....	229
40X1791	Power cord, Taiwan.....	229
40X1792	Power cord, Korea.....	229
40X7229	Power cord, India.....	229
41X1083	Sensor (input).....	220
41X1872	MarkNet N8372 802.11 a/b/g/n/ac wireless print server (MX431, MB3442, XM1342).....	229
41X2425	Pick roller clutch.....	222
41X2428	ADF tray.....	228
41X2510	ADF cover.....	228
41X2511	ADF separator pad.....	228
41X2573	Printhead.....	218
41X2575	Pick separator roller.....	224
41X2576	Main drive gears kit.....	222
41X2578	Left front door link.....	214
41X2579	Left cover.....	214
41X2580	Right cover (MX331).....	214
41X2582	Rear door.....	214
41X2584	Front door with MPF pick roller.....	214
41X2585	250-sheet tray.....	224
41X2586	Fuser, 115 V.....	224
41X2587	Transfer roller, bearing, and spring.....	219
41X2590	LVPS, 75 W and 120 V.....	219
41X2591	LVPS, 75 W and 230 V.....	219

P/N	Part name	Page
41X2592	HVPS.....	219
41X2595	Control panel assembly.....	216
41X2596	Scanner pivot arm.....	228
41X2597	Scanner with fax card (MX331) (simplex ADF).....	228
41X2598	Scanner with fax card (MB3442, MX431, XM1342).....	228
41X2599	Fuser, 100 V.....	224
41X2600	Fuser, 230 V.....	224
41X2612	550-sheet tray.....	226
41X2613	550-sheet tray insert.....	226
41X2614	550-sheet tray pick roller.....	226
41X2636	Main fan.....	219
41X2659	Controller board (MX331adn).....	218
41X2660	Controller board (MX431adn).....	218
41X2661	Controller board (MB3442adw, MX431adw, XM1342).....	219
41X2670	Upper front cover with decals (MX331, MB3442, MX431).....	214
41X2712	Duplex guide.....	224
41X2929	Upper front cover with decals (XM1342).....	214
41X2975	Controller board (MX331adn).....	218
41X2976	Controller board (MX431adn).....	218
41X2977	Controller board (MB3442adw, MX431adw, XM1342).....	219
41X2978	Speaker.....	218
41X2980	Scanner with fax card (MB3442, MX431, XM1342).....	228
41X4195	Redrive.....	224
41X4196	Bin full sensor actuator.....	224
41X4207	Right cover (MB3442, MX431, XM1342).....	214
41X4273	Toner cartridge contact.....	220
41X4471	Duplex shaft bushing.....	222
41X4479	Controller board (MB3442adw, MX431adw, XM1342).....	219
41X4485	Interlock switch.....	220

Part name index

P/N	Part name	Page
41X2585	250-sheet tray.....	224
41X2612	550-sheet tray.....	226
41X2613	550-sheet tray insert.....	226
41X2614	550-sheet tray pick roller.....	226
41X2510	ADF cover.....	228
41X2511	ADF separator pad.....	228
41X2428	ADF tray.....	228
41X4196	Bin full sensor actuator.....	224
41X2595	Control panel assembly.....	216
41X2661	Controller board (MB3442adw, MX431adw, XM1342).....	219
41X2977	Controller board (MB3442adw, MX431adw, XM1342).....	219
41X4479	Controller board (MB3442adw, MX431adw, XM1342).....	219
41X2659	Controller board (MX331adn).....	218
41X2975	Controller board (MX331adn).....	218
41X2660	Controller board (MX431adn).....	218
41X2976	Controller board (MX431adn).....	218
41X2712	Duplex guide.....	224
41X4471	Duplex shaft bushing.....	222
41X2584	Front door with MPF pick roller.....	214
41X2599	Fuser, 100 V.....	224
41X2586	Fuser, 115 V.....	224
41X2600	Fuser, 230 V.....	224
41X2592	HVPS.....	219
41X4485	Interlock switch.....	220
41X2579	Left cover.....	214
41X2578	Left front door link.....	214
41X2590	LVPS, 75 W and 120 V.....	219
41X2591	LVPS, 75 W and 230 V.....	219
41X2576	Main drive gears kit.....	222
41X2636	Main fan.....	219
41X1872	MarkNet N8372 802.11 a/b/g/n/ac wireless print server (MX431, MB3442, XM1342).....	229
41X2425	Pick roller clutch.....	222

P/N	Part name	Page
41X2575	Pick separator roller.....	224
40X0288	Power cord, Argentina.....	229
40X0301	Power cord, Australia and New Zealand.....	229
40X1766	Power cord, Bolivia and Peru.....	229
40X0259	Power cord, Brazil.....	229
40X0273	Power cord, Chile and Uruguay.....	229
40X1767	Power cord, Europe.....	229
40X7229	Power cord, India.....	229
40X1792	Power cord, Korea.....	229
40X0303	Power cord, PRC.....	229
40X1791	Power cord, Taiwan.....	229
40X0271	Power cord, United Kingdom, Asian, Brunei, Cambodia, Indonesia, Laos, Malaysia, Myanmar, Philippines, Singapore, Thailand, Vietnam, Afghanistan, Bangladesh, Bhutan, India, Nepal, Pakistan, Sri Lanka, Tibet, and Hong Kong.....	229
41X2573	Printhead.....	218
41X2582	Rear door.....	214
41X4195	Redrive.....	224
41X4207	Right cover (MB3442, MX431, XM1342).....	214
41X2580	Right cover (MX331).....	214
41X2596	Scanner pivot arm.....	228
41X2598	Scanner with fax card (MB3442, MX431, XM1342).....	228
41X2980	Scanner with fax card (MB3442, MX431, XM1342).....	228
41X2597	Scanner with fax card (MX331) (simplex ADF).....	228
41X1083	Sensor (input).....	220
41X2978	Speaker.....	218
41X4273	Toner cartridge contact.....	220
41X2587	Transfer roller, bearing, and spring.....	219
41X2670	Upper front cover with decals (MX331, MB3442, MX431).....	214
41X2929	Upper front cover with decals (XM1342).....	214

MB3442adw, MB3442i, MX331adn, MX431adn, MX431adw, and XM1342

WIRING DIAGRAM

