



Professional Document Scanner **PARTS REFERENCE LIST**

MODEL:

**PDS-5000 / PDS-6000 /
PDS-5000F / PDS-6000F**



Read this list thoroughly before maintenance work.

Keep this list in a convenient place for quick and easy reference at all times.

NOTE FOR USING THIS PARTS REFERENCE LIST

1. In the case of ordering parts, it is necessary to mention the following items:

- (1) Code
- (2) Q'ty
- (3) Description

<Example>

	(1)	(2)	(3)			
REFNo.	CODE	Q'TY	DESCRIPTION	MODEL	SPEC	REMARKS

2. Design-changed parts:

If any of the parts is changed, one of the following symbols is indicated in the REMARKS column.

CHG (chg): The part is changed for a new one.

ADD (add): The part is newly added.

DEL (del): The part is deleted.

Symbol in capital letters indicates the latest parts change information in the page.

3. Parts change will be informed by the Parts change information.

4. Parts are subject to change in design without prior notice.

COUNTRIES & AREAS

ASA ----- ASIA

EU ----- EUROPE

US ----- U.S.A.

CONTENTS

1.	<u>UPPER</u>	1
2.	<u>LOWER</u>	3
3.	<u>COVER</u>	5
4.	<u>PCB</u>	7
5.	<u>FLAT BED</u>	9
6.	<u>ACCESSORIES</u>	11
7.	<u>PRINTED MATERIALS</u>	13
8.	<u>PACKING</u>	15
9.	<u>OTHERS</u>	17

1. UPPER

REF No.	CODE	Q'TY	DESCRIPTION	MODEL	SPEC	REMARKS
1	LD1572001	1	UPPER BASE ASSY	PDS-5000		
1	LD1572001	1	UPPER BASE ASSY	PDS-6000		
1	LD1834001	1	UPPER BASE ASSY	PDS-5000F		
1	LD1834001	1	UPPER BASE ASSY	PDS-6000F		
1-1	LD1617001	1	SECOND SIDE CCD UNIT	PDS-5000		
1-1	LD1617001	1	SECOND SIDE CCD UNIT	PDS-6000		
1-1	LD1833001	1	SECOND SIDE CCD UNIT	PDS-5000F		
1-1	LD1833001	1	SECOND SIDE CCD UNIT	PDS-6000F		
1-2	LD1574001	1	ADF COVER SENSOR PCB			
1-3	LD1575001	1	ADF COVER SENSOR FLAT CABLE			
1-4	LD1576001	1	D-FEED SENSOR PCB ASSY T			
1-5	LD1577001	1	SECOND SIDE CCD FLAT CABLE			
1-6	LD1578001	1	D-FEED SENSOR PCB FLAT CABLE T			
1-7	LD1579001	1	PAPER DETECTION SENSOR			
1-8	LD1580001	1	REVERSE ROLLER COVER ASSY			
1-9	LD1581001	2	ADF COVER HOOK			
1-10	LD1582001	2	RETAINING RING			
1-11	LD1583001	1	SECOND SIDE CCD GLASS	PDS-5000		
1-11	LD1583001	1	SECOND SIDE CCD GLASS	PDS-6000		
1-11	LD1840001	1	SECOND SIDE CCD GLASS	PDS-5000F		
1-11	LD1840001	1	SECOND SIDE CCD GLASS	PDS-6000F		
1-12	LD1585001	1	LED LIGHT PCB ASSY			
1-13	LD1587001	1	COVER RELEASE LEVER			
2	LD1588001	1	PANEL ASSY	PDS-5000		
2	LD1606001	1	PANEL ASSY	PDS-6000		
2	LD1841001	1	PANEL ASSY	PDS-5000F		
2	LD1846001	1	PANEL ASSY	PDS-6000F		
2-1	LD1570001	1	LCD PCB ASSY			
2-2	LD1571001	1	LCD SHEET			
3	LD1569001	1	LCD PCB FLAT CABLE			


1. UPPER

1		1-1		1-2	
1-3		1-4		1-5	
1-6		1-7		1-8	
1-9		1-10		1-11	
1-12		1-13		2	
2-1		2-2		3	

2. LOWER

REF No.	CODE	Q'TY	DESCRIPTION	MODEL	SPEC	REMARKS
1	LD1573001	1	FIRST SIDE CCD UNIT	PDS-5000		
1	LD1573001	1	FIRST SIDE CCD UNIT	PDS-6000		
1	LD1832001	1	FIRST SIDE CCD UNIT	PDS-5000F		
1	LD1832001	1	FIRST SIDE CCD UNIT	PDS-6000F		
2	LD1592001	1	PICK-UP ROLLER COVER			
3	LD1593001	1	FIRST SIDE CCD GLASS	PDS-5000		
3	LD1593001	1	FIRST SIDE CCD GLASS	PDS-6000		
3	LD1839001	1	FIRST SIDE CCD GLASS	PDS-5000F		
3	LD1839001	1	FIRST SIDE CCD GLASS	PDS-6000F		
4	LD1595001	1	FEED ROLLER ASSY			
5	LD1596001	1	EXIT ROLLER ASSY			
6	LD1577001	1	FIRST SIDE CCD FLAT CABLE			
7	LD1598001	1	D-FEED SENSOR PCB ASSY R			
8	LD1599001	1	D-FEED SENSOR PCB FLAT CABLE R			
9	LD1600001	1	FEED DRIVE BELT			
10	LD1664001	1	FEED DRIVE BELT S			
11	LD1601001	1	FEED MOTOR			
12	LD1601001	1	PIC-UP MOTOR			
13	LD1724001	1	MOTOR GASKET			
14	LD1585001	1	LED LIGHT PCB ASSY			
15	LD1602001	1	PICK-UP DRIVE BELT			
16	LD1594001	1	SHAFT MOUNT ASSY			
17	LD1586001	1	REVERSE ROLLER GEAR ASSY			

2. LOWER

1		2		3	
4		5		6	
7		8		9	
10		11		12	
13		14		15	
16		17			

3. COVER

REF No.	CODE	Q'TY	DESCRIPTION	MODEL	SPEC	REMARKS
1	LD1559001	1	TOP COVER ASSY			
2	LD1560001	1	BACK COVER	PDS-5000		
2	LD1560001	1	BACK COVER	PDS-6000		
2	LD1827001	1	BACK COVER	PDS-5000F		
2	LD1827001	1	BACK COVER	PDS-6000F		
3	LD1561001	1	BOTTOM COVER ASSY	PDS-5000		
3	LD1561001	1	BOTTOM COVER ASSY	PDS-6000		
4	LD1562001	1	OUTPUT TRAY ASSY	PDS-5000		
4	LD1562001	1	OUTPUT TRAY ASSY	PDS-6000		
5	LD1563001	1	SIDE COVER L			
6	LD1564001	1	SIDE COVER R			
7	LD1565001	1	UPPER BACK COVER			
8	LD1828001	1	JOINT COVER	PDS-5000F		
8	LD1828001	1	JOINT COVER	PDS-6000F		
9	LD1836001	1	BLIND SHEET CIRCLE BLACK	PDS-5000F		
9	LD1836001	1	BLIND SHEET CIRCLE BLACK	PDS-6000F		

3. COVER

1		2	
3		4	
5		6	
7		8	
9			

4. PCB

REF No.	CODE	Q'TY	DESCRIPTION	MODEL	SPEC	REMARKS
1	LD1567001	1	MAIN PCB ASSY	PDS-5000		
1	LD1605001	1	MAIN PCB ASSY	PDS-6000		
1	LD1831001	1	MAIN PCB ASSY	PDS-5000F		
1	LD1845001	1	MAIN PCB ASSY	PDS-6000F		

4. PCB



5. FLAT BED

REF No.	CODE	Q'TY	DESCRIPTION	MODEL	SPEC	REMARKS
1	LD1820001	1	FLAT BED UNIT	PDS-5000F		
1	LD1820001	1	FLAT BED UNIT	PDS-6000F		
1-1	LD1824001	1	FB CCD UNIT	PDS-5000F		
1-1	LD1824001	1	FB CCD UNIT	PDS-6000F		
1-2	LD1826001	1	FB CCD FLAT CABLE 24	PDS-5000F		
1-2	LD1826001	1	FB CCD FLAT CABLE 24	PDS-6000F		
1-3	LD1825001	1	FB CCD FLAT CABLE 18	PDS-5000F		
1-3	LD1825001	1	FB CCD FLAT CABLE 18	PDS-6000F		
2	LD1821001	1	HINGE L	PDS-5000F		
2	LD1821001	1	HINGE L	PDS-6000F		
3	LD1822001	1	HINGE R	PDS-5000F		
3	LD1822001	1	HINGE R	PDS-6000F		
4	LD1823001	1	DOCUMENT COVER ASSY	PDS-5000F		
4	LD1823001	1	DOCUMENT COVER ASSY	PDS-6000F		
5	LD1829001	1	RELAY PCB FLAT CABLE 18	PDS-5000F		
5	LD1829001	1	RELAY PCB FLAT CABLE 18	PDS-6000F		
6	LD1830001	1	RELAY PCB FLAT CABLE 24	PDS-5000F		
6	LD1830001	1	RELAY PCB FLAT CABLE 24	PDS-6000F		
7	LD1835001	1	BLIND SHEET SQUARE	PDS-5000F		
7	LD1835001	1	BLIND SHEET SQUARE	PDS-6000F		
8	LD1837001	1	BLIND SHEET CIRCLE GRAY	PDS-5000F		
8	LD1837001	1	BLIND SHEET CIRCLE GRAY	PDS-6000F		


5. FLAT BED

1		1-1	
1-2		1-3	
2		3	
4		5	
6		7	
8			

6. ACCESSORIES

REF No.	CODE	Q'TY	DESCRIPTION	MODEL	SPEC	REMARKS
1	LD1197001	1	AC ADAPTER PDS			
2	LD1198001	1	POWER SUPPLY CORD US		FOR US	
2	LD1199001	1	POWER SUPPLY CORD BRZ		FOR US	
2	LD1200001	1	POWER SUPPLY CORD EUR		FOR EU/ASA	
2	LD1201001	1	POWER SUPPLY CORD UK		FOR EU/ASA	
2	LD1511001	1	POWER SUPPLY CORD AUSTRALIA	PDS-5000	FOR ASA	
2	LD1511001	1	POWER SUPPLY CORD AUSTRALIA	PDS-6000	FOR ASA	
3	LD1203001	1	USB CABLE			
4	LD1196001	1	DVD ASSY	PDS-5000		
4	LD1206001	1	DVD ASSY	PDS-6000		
4	LD1815001	1	DVD ASSY	PDS-5000F		
4	LD1816001	1	DVD ASSY	PDS-6000F		


6. ACCESSORIES

1		2	
3		4	

7. PRINTING MATTER

REF No.	CODE	Q'TY	DESCRIPTION	MODEL	SPEC	REMARKS
1	LD1194001	1	QUICK SETUP GUIDE	PDS-5000	FOR US	
1	LD1194001	1	QUICK SETUP GUIDE	PDS-6000	FOR US	
1	LD1195001	1	QUICK SETUP GUIDE	PDS-5000	FOR EU	
1	LD1195001	1	QUICK SETUP GUIDE	PDS-6000	FOR EU	
1	LD1509001	1	QUICK SETUP GUIDE	PDS-5000	FOR ASA	
1	LD1509001	1	QUICK SETUP GUIDE	PDS-6000	FOR ASA	
1	LD1757001	1	QUICK SETUP GUIDE	PDS-5000F	FOR US	
1	LD1757001	1	QUICK SETUP GUIDE	PDS-6000F	FOR US	
1	LD1848001	1	QUICK SETUP GUIDE	PDS-5000F	FOR EU	ADD
1	LD1848001	1	QUICK SETUP GUIDE	PDS-6000F	FOR EU	ADD




7. PRINTING MATTER



8. PACKING

REF No.	CODE	Q'TY	DESCRIPTION	MODEL	SPEC	REMARKS
1	LD1192001	1	CARTON	PDS-5000	FOR US	
1	LD1193001	1	CARTON	PDS-5000	FOR EU	
1	LD1508001	1	CARTON	PDS-5000	FOR ASA	
1	LD1204001	1	CARTON	PDS-6000	FOR US	
1	LD1205001	1	CARTON	PDS-6000	FOR EU	
1	LD1512001	1	CARTON	PDS-6000	FOR ASA	
1	LD1755001	1	CARTON	PDS-5000F	FOR US	
1	LD1756001	1	CARTON	PDS-5000F	FOR EU	
1	LD1758001	1	CARTON	PDS-6000F	FOR US	
1	LD1759001	1	CARTON	PDS-6000F	FOR EU	
2	LD1725001	1	PAD ASSY	PDS-5000		
2	LD1725001	1	PAD ASSY	PDS-6000		
3	LD1842001	1	PAD ASSY	PDS-5000F		
3	LD1842001	1	PAD ASSY	PDS-6000F		
4	LD1612001	1	PROTECT SHEET A			
5	LD1614001	1	PE BAG	PDS-5000		
5	LD1614001	1	PE BAG	PDS-6000		
5	LD1844001	1	PE BAG	PDS-5000F		
5	LD1844001	1	PE BAG	PDS-6000F		
6	LD1607001	1	HOLDING TAPE A			
7	LD1615001	1	ACCESSORY PAD	PDS-5000		
7	LD1615001	1	ACCESSORY PAD	PDS-6000		
8	LD1843001	1	ACCESSORY PAD	PDS-5000F		
8	LD1843001	1	ACCESSORY PAD	PDS-6000F		



8. PACKING

1		2	
3		4	
5		6	
7		8	

9. OTHERS

REF No.	CODE	Q'TY	DESCRIPTION	MODEL	SPEC	REMARKS
1	LD1668001	1	PAPER FEED ROLLER KIT			
2	LD1663001	1	OD/WF CHART ASSY			
3	LD1838001	1	TEST CHART OD FB	PDS-5000F		
3	LD1838001	1	TEST CHART OD FB	PDS-6000F		
4	LD1625001	1	TEST CHART DS-001			del
5	LD1669001	1	CARRIER SHEET (X2)			add
6	D00DFL001	1	SPONGE ASSY PDS			ADD

9. OTHERS

1		2	
3		4	
5		6	